

KWAN YING MUN MOTOR SERVICE

BLK 3023A UBI ROAD 1 #01-57 S (408717)

REG NO: 34571600X

Tel: 67476845; Fax No: 67493302

Vehicle No: GBA1760D

Vehicle model: Toyota Hiace

Surveyor Name:

Contact No:

Claim officer:

Email:

Contact:

Estimated spare part cost:

- F/L door assy *Deletd*
- F/L step board *cut*
- F/L head lamp *be a*
- Front bumper *Deletd*

Total:

\$ 1248.00 ✓

\$ 250.00 ✓

\$ 851.00 ✗

\$ 482.00 ✓

\$ 2831.00

Estimated labor cost:

- Spray Painting
- Knocking & replacement
- Wiring

Total:

\$ 350.00 *200*

\$ 400.00 *300*

\$ 100.00 *30*

\$ 850.00

Grand Total: \$ 3681.00

Days of repair: 3 days

total: 2015

4/5: 1-6K.

Adrian Lim

1/5 04/06/19.

03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: