



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5582S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LIGHT REVERSE LED FOR ADL E500 DD BUS (CONSISTENT)	CRACKED	861.86	861.86
1	REFLECTOR REAR SCR EW-ON TYPE MBOC500 MBG (CONSISTENT)	CRACKED	5.14	5.14
1	RETANER MALE & FEMALE (CONSISTENT)	JAMMED	54.24	54.24
1	STICKER SG LOVE (CONSISTENT)	NOT NECESSARY	75.00	-
	LESS 10% DISCOUNT		-	-92.12
			996.24	829.12
<u>SPECIAL NETT ITEMS</u>				
1	STICKER SMRT (SN) (CONSISTENT)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,590.00	1,325.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		528.00	446.00
			2,118.00	1,771.00
GRAND TOTAL			3,189.24	2,675.12
RECOMMENDED COST OF REPAIRS				2,675.12

Report Ref No. CC4/ASM19005097/Jga3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.