

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:
 Assessment number: SIN00014
 Version: 1810
 Date calculated: 03/20/2019 03:10 PM

Full Report
 Registration: SDJ1608R
 Printed: 20/03/2019 3:10 PM

Total Paint	Hrs 9.00	WU 90.0	Price SGD 405.00
Material Cost - Paint			Price SGD
Repair Painting			34.98
Material-constant Metal			13.47
Total			221.95

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0260	FRT NO PLATE BACKG	211 817 0178	CRA ✓	115.00
0283	FRONT BUMPER COVER	211 880 1640	TOR ✓	980.00
0303	L/F OUT BUMP GRILLE	211 885 0922	? CRA ✓	16.00
0305	FRONT BUMPER GRILLE	211 885 0122	X SUC ✓	24.00
0309	L/F COVER	211 885 1174	? CRA ✓	56.00
0313	L/F BUMPER MOULDING	211 885 2321	CRA ✓	53.00
0314	R/F BUMPER MOULDING	211 885 2421	ne ✓	53.00
0340	FRT CTR BUMPER REINF	211 880 0703	? BA ✓	24.00
0341	L/F BUMPER REINF	211 880 0503	DE ✓	36.00
0342	R/F BUMPER REINF	211 880 0603	X SUC ✓	36.00
0345	L/F BUMPER BRACKET	211 880 1114	ne ✓	35.00
0347	L/OUT IMPACT DAMPER	211 885 1137	CRA ✓	31.00
0348	R/OUT IMPACT DAMPER	211 885 1237	X SUC ✓	31.00
0349	FRT/CTR IMPACT DAMP	211 885 1037	? CRA ✓	40.00
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	ne ✓	30.00
0405	GRILLE	211 880 1783 9040	CRA ✓	430.00
0432	FRONT STAR EMBLEM	221 880 0086	ne ✓	47.00
0471	BONNET	211 880 0457 28	BF ✓	1,020.00
0475	L/BONNET HINGE	211 880 0128	X SUC ✓	62.00
0476	R/BONNET HINGE	211 880 0428	X SUC ✓	62.00
0481	BONNET INSULATION	211 682 0626	X ✓	105.00
0503	L/BONNET CATCH	211 880 0360	Free ✓	32.50
0504	R/BONNET CATCH	211 880 0360	Free ✓	32.50
0561	LEFT HEADLAMP ASSY	211 820 4961	Bro ✓	520.00
0605	L/HEADLAMP WASH TRIM	211 880 1705 9197	MIS ✓	26.00
0625	L/HEADLAMP WASH JET	211 860 2147	MIS ✓	139.00
0637	L/F FOG LAMP	169 820 1556	? CRA ✓	105.00
0741	L/F WING	211 880 1318	BM ✓	355.00
0781	L/F WING MOULDING	211 690 2762 9999	? XAN ✓	40.00

ETHOZ Automotive Solutions Ltd

30 Bukit Batok Crescent

658075

Claim Reference:
 Assessment number: SIN00014
 Version: 1810
 Date calculated: 03/20/2019 03:10 PM

Full Report
 Registration: SDJ1608R
 Printed: 20/03/2019 3:10 PM

Code	Description	Part Number	Supplier	Price SGD
0785	L/F WING BADGE	211 817 4820	? X nn	10.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS	nee	30.00
0839	L/F W-HOUSE CVR FRT	211 698 0130	cut X	48.00
0841	L/F W-HOUSE CVR REAR	211 690 1330	? X snc	44.00
0930	CTR FRT REINF	211 620 0916	X snc	74.00
0988	CTR FRT REINF	211 620 1916	X snc	50.00
1001	FRT LWR CROSSMEMBER	211 620 2834	? X bt	325.00
1179	L/F UPP REINF	211 620 0316	? X bt	72.00
1187	L/HEADLAMP FRAME	211 620 0718	? X snc	58.00
1447	H-LAMP WASH PIPE KIT	211 860 0392	nee	65.00
4467	DRYER BOTTLE	211 835 0047	X snc	0.00
7751	UPPER AIR GUIDE	211 500 1216	Toru	51.00
7752	LOWER AIR GUIDE	211 505 0830	? X	80.00
1003	Bonnet Ins Clip	Bonnet	nee	38.00
1004	Frt Grille Logo	Grille	nee	27.00
f: OEM Parts				0.00
n: Non-OEM Parts				5,508.00
u: Used parts				550.80
Savings				
Subtotal				5,508.00
Addition(+10.00%)				550.80
Total				6,058.80

Extras

Code	Description	Price SGD
1000	Frt Number Plate	35.00*
1001	Air Cond Gas	50.00*
1002	Radiator Coolant	20.00*
Total Extras		105.00*

ETHOZ Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

Page 5 of 6

PRINT DATE 20/03/2019

Resurvey before paint

Resur
 Hp 90010068
 5 days
 P/P
 21/03/19
 excess: 400
 REVERT

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 03/20/2019 03:10 PM

Full Report

Registration: SDJ1608R

Printed: 20/03/2019 3:10 PM

Final Calculation

	SGD	SGD
Parts	5,508.00	
Addition(+10.00%)	550.80	
Total Parts		6,058.80
Labour Time Base 10 WU/h		
Total 143.0 WU X 45.00 SGD/h	643.50	571.50
Total of Labour		643.50
Total Of Extras		105.00
Paint Work Time Base 10 WU/h		
Labour Cost 90.0 WU X 45.00 SGD/h	405.00	387
Material Cost	221.95	219.45
Total Paint Including Material		626.95
Repair Cost Excludes GST	<u>8131.65</u>	7,434.25*
GST (+7.00%)		520.40
Repair Cost Included GST		7,954.65

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

finalised

Claim Reference:
Assessment number: SIN00014
Version: 1810
Date calculated: 03/05/2019 12:51 PM

Full Report
Registration: SDJ1608R
Printed: 03/05/2019 12:51 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	18/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W211)
Sub Model:	220 CDI
Model Sheet Number:	03 41 12
Registration:	SDJ1608R
VIN number:	WDB2110522B326336
Odometer:	

Model Specs

EQUIPMENT AVANTGARDE	HEAVY DUTY COOLING	FROM VIN B296713	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CC	CD AUTO CHANGER	BI-XENON HEADLAMPS	HEADLAMP WASHERS
LEATHER UPHOLSTERY	MEMORY PACKAGE	ILLUM SUN VISORS	DIPPING MIRROR
L/F MEMORY SEAT ADJ	LEATHER STRG WHEEL	KEYLESS GO	EQUIP CURLED MAPLE
EMISSION STD EURO 4	H/DUTY ALTERNATOR	7 SPEED AUTOMATIC	PARAMETER STEERING
TYRES 245/45 WR 17	SPARE WHEEL	EXTENDED FUEL TANK	ALU WHEEL 8 J X 17
MODEL 2008	TWO COAT METALLIC	PREPARE OFF VEHICLE	CLEAR COAT HARD

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: SIN00014
Version: 1810
Date calculated: 03/05/2019 12:51 PM

Full Report
Registration: SDJ1608R
Printed: 03/05/2019 12:51 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)		9.0	40.50
88-1102 01)	R + R FRONT BUMPER CPL (FRONT PARTITION SECTIONS REMOVED)		12.0	54.00
88-1144 ZAX	DISMANTLE/RE-ASSEMBLE BUMPER BAR REPLACE AS NECESSARY: PARTS (REMOVED)		7.0	31.50
88-2506 01	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS		20.0	90.00
82-4608 01)	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)		4.0	18.00
88-3816 01	RENEW L/F WING INCLUDES: R + R PARTITION CPL		15.0	67.50
20-1140 01	DRAIN AND REFILL COOLANT		6.0	27.00
20-3865 05)	R + R RADIATOR		7.0	31.50

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 03/05/2019 12:51 PM

Full Report

Registration: SDJ1608R

Printed: 03/05/2019 12:51 PM

Code	Description	WU	Price SGD
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	3.0	13.50
83-6543 ZAX	RENEW CONDENSER	9.0	40.50
09-6810 02	R + R AIR INTERCOOLER	6.0	27.00
60-1302 ZAX	R + R ATTACHED PARTS OF THE ENG COMP R + R FOR RENEWAL FRONT CROSSMEMBER	4.0	18.00
NO NUMBER	RENEW L/F AND CENTRE REINFORCEMENT BETWEEN WHEELHOUSES	9.0	40.50
62-1263 01	R + R FRONT CROSSMEMBER CPL (BUMPER REMOVED) INCLUDES: R + R ATTACHED PARTS	13.0	58.50
94-5310 01	R + R FRONT LOWER ENGINE COMPARTMENT COVER	3.0	13.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.70	127.0
Total of Labour			571.50

Paint

Paint Work

Time Basis 10WU/h

Code	Description - CLEAR COAT HARD	WU	Price SGD
98-1681 01	FRONT BUMPER COVER PAINTING	10.0	45.00
98-2808 01	BONNET PAINTING STAGE I-M	24.0	108.00
98-2418 01	L/F WING PAINTING STAGE I-M	7.0	31.50
98-4020 01	LEFT FRONT DOOR PAINTING STAGE III	20.0	90.00
98-5523 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	31.50
98-1342 01	PREPARATION WORK FOR SCRATCHPROOF PAINTING OF FITTED BODY PARTS	15.0	67.50
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	13.50
Total Paint		Hrs 8.60	WU 86.0
			Price SGD 387.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 03/05/2019 12:51 PM

Full Report

Registration: SDJ1608R

Printed: 03/05/2019 12:51 PM

Material Cost - Paint
 Repair Painting
 Material-constant Metal
Total

Price SGD
34.98
13.47
219.45

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0260	FRT NO PLATE BACKG	211 817 0178		115.00
0283	FRONT BUMPER COVER	211 880 1640		980.00
0303	L/F OUT BUMP GRILLE	211 885 0922		16.00
0309	L/F COVER	211 885 1174		56.00
0313	L/F BUMPER MOULDING	211 885 2321		53.00
0314	R/F BUMPER MOULDING	211 885 2421		53.00
0340	FRT CTR BUMPER REINF	211 880 0703		24.00
0341	L/F BUMPER REINF	211 880 0503		36.00
0345	L/F BUMPER BRACKET	211 880 1114		35.00
0347	L/OUT IMPACT DAMPER	211 885 1137		31.00
0349	FRT/CTR IMPACT DAMP	211 885 1037		40.00
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		30.00
0405	GRILLE	211 880 1783 9040		430.00
0432	FRONT STAR EMBLEM	221 880 0086		47.00
0471	BONNET	211 880 0457 28		1,020.00
0503	L/BONNET CATCH	211 880 0360		32.50
0504	R/BONNET CATCH	211 880 0360		32.50
0515	L/BONNET LOCK	219 880 0160 (A)		84.00
0561	LEFT HEADLAMP ASSY	211 820 4961		520.00
0605	L/HEADLAMP WASH TRIM	211 880 1705 9197		26.00
0625	L/HEADLAMP WASH JET	211 860 2147		139.00
0637	L/F FOG LAMP	169 820 1556		105.00
0741	L/F WING	211 880 1318		355.00
0785	L/F WING BADGE	211 817 4820		0.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS		30.00
0839	L/F W-HOUSE CVR FRT	211 698 0130		48.00
0930	CTR FRT REINF	211 620 0916		74.00
1001	FRT LWR CROSSMEMBER	211 620 2834		325.00
1179	L/F UPP REINF	211 620 0316		72.00
1447	H-LAMP WASH PIPE KIT	211 860 0392		65.00
4465	CONDENSER	211 500 1154 (A)		550.00
7751	UPPER AIR GUIDE	211 500 1216		51.00
7752	LOWER AIR GUIDE	211 505 0830		80.00
1003	Bonnet Ins Clip	Bonnet		38.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 03/05/2019 12:51 PM

Full Report

Registration: SDJ1608R

Printed: 03/05/2019 12:51 PM

Code	Description	Part Number	Supplier	Price SGD
1004	Frt Grille Logo	Grille		27.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,620.00
u: Used parts	Addition(+10.00%)			562.00
	Total			6,182.00

Extras

Code	Description	Price SGD
1000	Frt Number Plate	35.00*
1001	Air Cond Gas	50.00*
1002	Radiator Coolant	20.00*
	Total Extras	105.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SIN00014
 Version: 1810
 Date calculated: 03/05/2019 12:51 PM

Full Report
 Registration: SDJ1608R
 Printed: 03/05/2019 12:51 PM

Final Calculation

	SGD	SGD
Parts	5,620.00	
Addition(+10.00%)	562.00	
Total Parts		6,182.00
Labour Time Base 10 WU/h		
Total 127.0 WU X 45.00 SGD/h	571.50	
Total of Labour		571.50
Total Of Extras		105.00
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 45.00 SGD/h	387.00	
Material Cost	219.45	
Total Paint Including Material		606.45
Repair Cost Excludes GST		7,464.95
GST (+7.00%)		522.55
Repair Cost Included GST		7,987.50
Deductions (Excludes GST)		
Deduction For Excess	-400.00	
Total Of Deductions (Excludes GST)		-400.00
Grand Total Excludes GST		7,064.95
GST (+7.00%)		494.55
Grand Total Included GST		7,559.50

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

FINALIZATION REPORT

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Ethoz Bukit Batok 02
Claim Reference:
Estimated Repair Time:
Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
Currency: SGD
Date of Incident: 18/03/19
Hire Car Start:
Hire Car End:

Vehicle Details

Vehicle

Manufacturer: MERCEDES-BENZ
Model: E-CLASS (W211)
Sub Model: 220 CDI
Model Sheet Number: 03 41 12
Registration: SDJ1608R
VIN number: WDB2110522B326336
Odometer:

Model Specs

EQUIPMENT AVANTGARDE	HEAVY DUTY COOLING	FROM VIN B296713	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CC	CD AUTO CHANGER	BI-XENON HEADLAMPS	HEADLAMP WASHERS
LEATHER UPHOLSTERY	MEMORY PACKAGE	ILLUM SUN VISORS	DIPPING MIRROR
L/F MEMORY SEAT ADJ	LEATHER STRG WHEEL	KEYLESS GO	EQUIP CURLED MAPLE
EMISSION STD EURO 4	H/DUTY ALTERNATOR	7 SPEED AUTOMATIC	PARAMETER STEERING
TYRES 245/45 WR 17	SPARE WHEEL	EXTENDED FUEL TANK	ALU WHEEL 8 J X 17
MODEL 2008	TWO COAT METALLIC	PREPARE OFF VEHICLE	CLEAR COAT HARD

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Vehicle Condition

Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All

Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)		9.0	40.50
88-1102 01)	R + R FRONT BUMPER CPL (FRONT PARTITION SECTIONS REMOVED)		12.0	54.00
88-1144 ZAX	DISMANTLE/RE-ASSEMBLE BUMPER BAR REPLACE AS NECESSARY: PARTS (REMOVED)		7.0	31.50
88-2506 01	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS		20.0	90.00
82-4608 01)	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)		4.0	18.00
88-3816 01	RENEW L/F WING INCLUDES: R + R PARTITION CPL		15.0	67.50
20-1140 01	DRAIN AND REFILL COOLANT		6.0	27.00
20-3865 05)	R + R RADIATOR		7.0	31.50

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Code	Description	WU	Price SGD
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	3.0	13.50
83-6543 ZAX	RENEW CONDENSER	9.0	40.50
09-6810 02	R + R AIR INTERCOOLER	6.0	27.00
60-1302 ZAX	R + R ATTACHED PARTS OF THE ENG COMP	4.0	18.00
NO NUMBER	R + R FOR RENEWAL FRONT CROSSMEMBER BETWEEN WHEELHOUSES	9.0	40.50
62-1263 01	R + R FRONT CROSSMEMBER CPL (BUMPER REMOVED)	13.0	58.50
94-5310 01	INCLUDES: R + R ATTACHED PARTS R + R FRONT LOWER ENGINE COMPARTMENT COVER	3.0	13.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.70	127.0
Total of Labour			571.50

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - CLEAR COAT HARD	WU	Price SGD
98-1681 01	FRONT BUMPER COVER PAINTING	10.0	45.00
98-2808 01	BONNET PAINTING STAGE I-M	24.0	108.00
98-2418 01	L/F WING PAINTING STAGE I-M	7.0	31.50
98-4020 01	LEFT FRONT DOOR PAINTING STAGE III	20.0	90.00
98-5523 01	L/OUTER A-PILLAR PAINTING STAGE III	7.0	31.50
98-1342 01	PREPARATION WORK FOR SCRATCHPROOF PAINTING OF FITTED BODY PARTS	15.0	67.50
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	13.50
Total Paint		Hrs 8.60	WU 86.0
			Price SGD 387.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Material Cost - Paint
 Repair Painting
 Material-constant Metal
Total

Price SGD
34.98
13.47
219.45

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0260	FRT NO PLATE BACKG	211 817 0178		115.00
0283	FRONT BUMPER COVER	211 880 1640		980.00
0303 <i>check item</i>	L/F OUT BUMP GRILLE	211 885 0922		16.00
0309 <i>check item</i>	L/F COVER	211 885 1174		56.00
0313	L/F BUMPER MOULDING	211 885 2321		53.00
0314	R/F BUMPER MOULDING	211 885 2421		53.00
0340 <i>check item</i>	FRT CTR BUMPER REINF	211 880 0703		24.00
0341	L/F BUMPER REINF	211 880 0503		36.00
0345	L/F BUMPER BRACKET	211 880 1114		35.00
0347	L/OUT IMPACT DAMPER	211 885 1137		31.00
0349 <i>check item</i>	FRT/CTR IMPACT DAMP	211 885 1037		40.00
0351	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		30.00
0405	GRILLE	211 880 1783 9040		430.00
0432	FRONT STAR EMBLEM	221 880 0086		47.00
0471	BONNET	211 880 0457 28		1,020.00
0503	L/BONNET CATCH	211 880 0360		32.50
0504	R/BONNET CATCH	211 880 0360		32.50
0515 <i>SUPPLEMENTARY</i>	L/BONNET LOCK	219 880 0160 (A) <i>st</i>		84.00
0561	LEFT HEADLAMP ASSY	211 820 4961		520.00
0605	L/HEADLAMP WASH TRIM	211 880 1705 9197		26.00
0625	L/HEADLAMP WASH JET	211 860 2147		139.00
0637 <i>check item</i>	L/F FOG LAMP	169 820 1556		105.00
0741	L/F WING	211 880 1318		355.00
0785	L/F WING BADGE	211 817 4820		0.00
0789	L/F WING CLAMP KIT	USE SINGLE PARTS		30.00
0839	L/F W-HOUSE CVR FRT	211 698 0130		48.00
0930	CTR FRT REINF	211 620 0916		74.00
1001 <i>check item</i>	FRT LWR CROSSMEMBER	211 620 2834		325.00
1179	L/F UPP REINF	211 620 0316		72.00
1447	H-LAMP WASH PIPE KIT	211 860 0392		65.00
4465 <i>SUPPLEMENTARY</i>	CONDENSER	211 500 1154 (A) <i>st</i>		550.00
7751	UPPER AIR GUIDE	211 500 1216		51.00
7752 <i>check item</i>	LOWER AIR GUIDE	211 505 0830		80.00
1003	Bonnet Ins Clip	Bonnet		38.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Code	Description	Part Number	Supplier	Price SGD
1004	Frt Grille Logo	Grille		27.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,620.00
u: Used parts	Addition(+ 10.00%)			562.00
	Total			6,182.00

Extras

Code	Description	Price SGD
1000	Frt Number Plate	35.00*
1001	Air Cond Gas	50.00*
1002	Radiator Coolant	20.00*
	Total Extras	105.00

ETHOZ Automotive Solutions Ltd
30 Bukit Batok Crescent
658075

Claim Reference:

Assessment number: SIN00014

Version: 1810

Date calculated: 26/04/2019 10:30 AM

Full Report

Registration: SDJ1608R

Printed: 26/04/2019 10:30 AM

Final Calculation

	SGD	SGD
Parts	5,620.00	
Addition(+10.00%)	562.00	
Total Parts		6,182.00
Labour Time Base 10 WU/h		
Total 127.0 WU X 45.00 SGD/h	571.50	
Total of Labour		571.50
Total Of Extras		105.00
Paint Work Time Base 10 WU/h		
Labour Cost 86.0 WU X 45.00 SGD/h	387.00	
Material Cost	219.45	
Total Paint Including Material		606.45
Repair Cost Excludes GST		7,464.95
GST (+7.00%)		522.55
Repair Cost Included GST		7,987.50
Deductions (Excludes GST)		
Deduction For Excess	-400.00	
Total Of Deductions (Excludes GST)		-400.00
Grand Total Excludes GST		7,064.95
GST (+7.00%)		494.55
Grand Total Included GST		7,559.50

COR: \$5,950.00 (45 REPAIR)

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

PARTS - \$5,620.00 + 10%
 - \$6,182.00
 31N - \$105.00
 LABOUR - \$1,177.95
 \$7,464.95
 - 20% (45 REPAIR)

EXCESS: \$400.00

5 DAYS REPAIR

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 30/04/2019
To : AXA INSURANCE PTE LTD

SUPPLEMENTARY

Attn : Motor Claim Department

FAX :

Owner : LILY LAU
: AXA INSURANCE PTE LTD
Certificate No : GA344180 Accident Date : 18/03/2019
Vehicle No : SDJ-1608-R Make & Model : MERCEDES BENS E230

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 400.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BONNET LOCK LH <i>BT</i>	84.00	
1	CONDENSER ASSY <i>BT</i>	550.00	
	Sub Total	634.00	
	Add 10% On Parts	63.40	

Remarks:

SUB TOTAL 697.40
GST 7.0 % 48.82
TOTAL 746.22

Surveyor's name: _____

Principal's name: LILY LAU

Survey Date & Time: _____

PAGE :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 May 2019 2:40 PM
To: Lee Chen Sin; SUR
Subject: RE: FINALIZATION REPORT OF SDJ-1608-R MERCEDES E220 (OD)(AXA)

Dear Chen Sin,

Confirmed Lump Sum \$5950 before excess \$400 @ 5 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Tuesday, 30 April 2019 3:11 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: FINALIZATION REPORT OF SDJ-1608-R MERCEDES E220 (OD)(AXA)

Dear Veron,

Please find attached file for your reference.

Thank you.

Warmest Regards,
Lee Chen Sin

From: Lee Chen Sin
Sent: Friday, April 26, 2019 11:10 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: FINALIZATION REPORT OF SDJ-1608-R MERCEDES E220 (OD)(AXA)

Hi Rasul,

Attached are the finalization report, check item photo, supplementary item photo and photo after paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 5,950.00 (Lump Sum Repair)

Repair days : 5
Excess : \$ 400.00

Kindly revert.

Thank you.

Warmest Regards,
Lee Chen Sin
Motor Claims Operations

ETHOZ
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339

www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

<< Service Request Details

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information	
Incident Vehicle Registration #	SDJ1608R
Make	MERCEDES
Model	E230
Service Address	
30 Bukit Batok Crescent, , 658075	
Primary Contact/Insured	
LILY LAU	
132A HILLVIEW AVENUE, #04-05 MONTROSA, 669604, Singapore	
LILYLAUPOON@YAHOO.COM	
Claim Handler	
ANG Yvonne	
6568804461	
yvonne.ang@axa.com.sg	

Claim	S9M01HEV
Reference	CS/ASM19005124/R1vd3s2
Loss Date	March 18, 2019
Report Date	Mar 20, 2019 4:00:00 PM
Request Date	March 20, 2019
Due Date	March 21, 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Additional Instructions EXCESS \$400 PEND EST REPAIRER : ETHOZ (BT BATOK)

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type

Document SubType

+

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

<< Service Request Details

Claim	S9M01HEV
Reference	CS/ASM19005124/R1vd3s2
Loss Date	March 18, 2019
Report Date	Mar 20, 2019 4:00:00 PM
Request Date	March 20, 2019
Due Date	March 21, 2020
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information	
Incident Vehicle Registration #	SDJ1608R
Make	MERCEDES
Model	E230
Service Address	30 Bukit Batok Crescent, , , 658075
Primary Contact/Insured	LILY LAU 132A HILLVIEW AVENUE, #04-05 MONTROSA, 669604, Singapore
	LILYLAUPOON@YAHOO.COM
Claim Handler	ANG Yvonne 6568804461 yvonne.ang@axa.com.sg

Additional Instructions

EXCESS \$400 PEND EST REPAIRER : ETHOZ (BT BATOK)

Messages Invoices History Documents Assessment Metrics Notes

Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	5/10/19 4:14 PM	5550	5550	Open	Share	Clone



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Workshop Details						
Involving	1 2008 MERCEDES E230 (SDJ1608R)		Total Rebate Amount		35558	
Date of Loss	March 18, 2019		Nett Loss Amount		\$25,442.00	
Time of Loss	8.00		Assigned Workshop		LKK AUTO CONSULTANTS PTE LTD (OD)	
Loss Description	SDJ1608R (INSD) C/W REAR OF SMB1532K (TP)		Days of work completion		7	
Comment						

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SDJ1608R	
Registration State	SINGAPORE	
Mileage	198495	
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2008	2008
Make	MERCEDES	MERCEDES BENZ
Model	E230	E230
Type		
Type of Paint		
Chassis No	WDB2110522B326336	WDB2110522B326336
Engine No	27292230923696	27292230923696
Engine Capacity		2497 cc

Purchase Date	mm/dd/yyyy	
Registration Date *	05/28/2008	
Age of Vehicle	10	
Driver Details		
CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	POON CHAY KUAN	
Date of Birth	September 9, 1954	mm/dd/yy
Age	64	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	36	
Driver License #		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

03/21/2019



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unarmed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/45R17

Rear Tyre Size

245/45R17

Front left side

PIRELLI 6mm

Rear left side

PIRELLI 6mm

Front right side

PIRELLI 6mm

Rear right side

PIRELLI 6mm

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Parts

	EDIT	S/N	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BITTR%	DISCOUNT%	SALVAGE%	PART PRICE(Net)	ACTION (PARTS)	REMOVE
☐		1	1			FRT NO PLATE BACKG (10%) (WCP)			Cracked	126.5				126.5	Reviewing	
☐		2	1			FRONT BUMPER COVER (10%) (WCP)			Damaged	1078				1078	Reviewing	
☐		3	1			L/F OUT BUMP GRILLE (10%) (WCP)			Cracked	17.6				17.6	Reviewing	
☐		4	1			FRONT BUMPER GRILLE (WCP)			Serviceable	0				0	Reviewing	
☐		5	1			L/F COVER (10%) (WCP)			Cracked	61.6				61.6	Reviewing	
☐		6	1			L/F BUMPER MOULDING (10%) (WCP)			Cracked	58.3				58.3	Reviewing	
☐		7	1			R/F BUMPER MOULDING (10%) (WCP)			Necessary	58.3				58.3	Reviewing	
☐		8	1			FRT CTR BUMPER REINF (10%) (WCP)			Bent	26.4				26.4	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ BITTN	DISC COUNTN	SALV AGEN	PART PRICENET)	ACTION (PARTS)	REMOVE
	22	1			L/BONNET CATCH (10%) (WCP)			Necessary	35.75				35.75	Reviewing	
	23	1			R/BONNET CATCH (10%) (WCP)			Necessary	35.75				35.75	Reviewing	
	24	1			LEFT HEADLAMP ASSY (10%) (WCP)			Broken	572				572	Reviewing	
	25	1			L/HEADLAMP WASH TRIM (10%) (WCP)			Missing	28.6				28.6	Reviewing	
	26	1			L/HEADLAMP WASH JET (10%) (WCP)			Missing	152.9				152.9	Reviewing	
	27	1			L/F FOG LAMP (10%) (WCP)			Cracked	115.5				115.5	Reviewing	
	28	1			L/F WING (10%) (WCP)			Buckled	390.5				390.5	Reviewing	
	29	1			L/F WING MOULDING (WCP)			Serviceable	0				0	Reviewing	
	30	1			L/F WING BADGE (WCP)			Serviceable	0				0	Reviewing	
	31	1			L/F WING CLAMP KIT (10%) (WCP)			Necessary	33				33	Reviewing	
	32	1			L/F W-HOUSE CVR FRT (10%) (WCP)			Cut	52.8				52.8	Reviewing	
	33	1			L/F W-HOUSE CVR REAR (WCP)			Serviceable	0				0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BITTR%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	46	1			CONDENSER (10%) (WCP) (ADDITIONAL)			Bent	605				605	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR PER	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TOTAL OF LABOUR	571.5	0	0	Reviewing		
	2		PAINT WORK	367	0	0	Reviewing		
	3		PAINT MATERIAL	219.45	0	0	Reviewing		

<< Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		5	
	2	FRT NUMBER PLATE	Reviewing	35	BENT	
	3	AIR COND GAS	Reviewing	50	NECESSARY	
	4	RADIATOR COOLANT	Reviewing	20	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount		\$7,064.95			Claim Amount		\$7,064.95	
CATEGORY		ESTIMATE			REVISED AMOUNT			
Spare Parts		\$6,182.00			\$6,182.00			
Labour		\$1,177.95			\$1,177.95			
Miscellaneous		\$105.00			\$105.00			
Excess		-\$400.00			-\$400.00			
Submit for Review								



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

AddApproveDenySubmit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	FINAL LUMP SUM	Reviewing	5950		
--	---	----------------	-----------	------	--	--



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount	\$5,550.00	Claim Amount	\$5,550.00
CATEGORY	ESTIMATE	REVISED AMOUNT	
Miscellaneous	\$5,950.00	\$5,950.00	
Excess	-\$400.00	-\$400.00	

Submit for Review