Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005130/GCD3E2

Date: 08/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SJU1536K Insured Vehicle No: SGV2447H

Date of Loss: 19/03/2019 Nature of Claim: TP Claim No: 9015245727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU1536K

Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR4485265

Reg. Date: 20/11/2009 (Man. Year: 2009) Chassis No: JTDKN36U001106321

Colour: Black Odometer: 228304 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm
Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/03/2019

Date Inspected: 21/03/2019 Inspected At: 51 Ubi Ave 1 #01-25 Paya Ubi Ind Park

S408933

Repairer: Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041

Singapore 537041

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4 Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Buckled	0.00 F	*- F
2	1		*FRT LH DOOR WING MIRROR	Cracked	0.00 F	*- F
3	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
4	1		*FRT LH FENDER	Repair	0.00 F	*- F
5	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00
				,		
			Report was unsubmitted of	during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >