

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SFY5356M
Chassis No : JHMGK3850JX220935
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : JIN QIAN
Ins Policy No. :
Date of Accident : 20/3/2019

Document No. : SQT19001292
Date : 20. Mar 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L13B11030701
Date | Time : 20. Mar 2019 8:21:49 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item Description

TP DIRECT SETTLEMENT (J/NO:)
OWNER:
OWNER INSURER:
ACC DATE:
SURVEYED BY:
DATE:
REF NO:
TP INSURER:
TP VEH:

LKK Auto Consultants hence notify
On Repair Price Discrepancy:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. X	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. X	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID X	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID X	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP X	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ	TAILGATE COMP ✓ 00	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE ?	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE ?	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE X	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01	EMBLEMRR. ✓ ALK	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARN ASSY,RR LICE X	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSYLICENCE X	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ	FACE,RR.BUMPER ✓ 00	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN X	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50	GARNISH,RR.BUMPER X	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER X	1	20.70	25	15.52	1.09	16.61

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SFY5356M

Chassis No : JHMGK3850JX220935

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : JIN QIAN

Ins Policy No. :

Date of Accident : 20/3/2019

Document No. : SQT19001292

Date : 20. Mar 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L13B11030701

Date | Time : 20. Mar 2019 8:21:49 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE ✓ <i>ALC</i>	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE ✓ <i>ALC</i>	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER ✓ <i>ALC</i>	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR. ? <i>ALC</i>	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR X	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL ?	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET X	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER ✓ <i>ALC</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER ✓ <i>ALC</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 ✓ <i>ALC</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ <i>ALC</i>	2	60.00		120.00	8.40	128.40
Sum Item					3251.58	227.62	3,479.20
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	?	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00	✓	80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	X	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	280	560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	✓	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	✓	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. <i>4 2 p-1 chys 560 p</i>	1	5000.00	1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>X3</i>	1	3000.00	1350	3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	X	450.00	31.50	481.50

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SFY5356M

Chassis No : JHMGK3850JX220935

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : JIN QIAN

Ins Policy No. :

Date of Accident : 20/3/2019

Document No. : SQT19001292

Date : 20. Mar 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L13B11030701

Date | Time : 20. Mar 2019 8:21:49 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00		480.00	33.60	513.60
Sum Labor					11970.00	837.90	12,807.90

Survey By

Date & Time

Excess

Status

Signature

Steve Chin 8322 8813

24/4/19 12.10 pm

5 days

w/L Prejudice

P/P

Ry before my

Total Amount 15,221.58 1,065.52 16,287.10

Total (Inclusive of GST) **16,287.10**

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.