



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SFY5356M
Chassis No : JHMGK3850JX220935
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : JIN QIAN
Ins Policy No. :
Date of Accident : 20/3/2019

Document No. : SQT19001292
Date : 20. Mar 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L13B11030701
Date | Time : 20. Mar 2019 8:21:49 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc%	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? X NAI	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X NAI	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. X NAI	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. X NAI	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSY,R.LID X NAI	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID X NAI	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSYHIGH MOUNT STOP X NAI	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ (1)	TAILGATE COMP ✓ DD	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE ? X NAI	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE ? X NAI	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE X NAI	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01 (2)	EMBLEMRR. ✓ ALK	1	10.90	25	8.17	0.57	8.74
74890-T5A-A11	GARN ASSY,RR LICE X NAI	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSYLICENCE X NAI	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ (3)	FACE,RR.BUMPER ✓ DD	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER X NAI	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN X NAI	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50 (11)	GARNISH,RR.BUMPER X ✓ DR	1	38.30	25	28.72	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER X NAI	1	20.70	25	15.52	1.09	16.61

LKK Auto Consultants hence notify

Qty Repair Price Disc%

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SFY5356M

Chassis No : JHMGK3850JX220935

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : JIN QIAN

Ins Policy No. :

Date of Accident : 20/3/2019

Document No. : SQT19001292

Date : 20. Mar 2019

Customer No. : WZA006

Svc Advisor :

Engine No : L13B11030701

Date | Time : 20. Mar 2019 8:21:49 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T5A-J50	(4) SPACER,R.RR.BUMPER SIDE ✓ <i>MLC</i>	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	(5) SPACER,L.RR.BUMPER SIDE ✓ <i>MLC</i>	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	(6) CLIP,BUMPER ✓ <i>MLC</i>	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPR. ? <i>X NAI</i>	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>X NAI</i>	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL ? <i>X NAI</i>	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET <i>X NAI</i>	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	(7) RUBBER CWINDSHIELD DAMPER ✓ <i>MLC</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	(8) RUBBERWINDSHIELD DAMPER ✓ <i>MLC</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	(9) DAMPERSTD 5X5 ✓ <i>MLC</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	(10) WINDSCREEN SEALANT (N) ✓ <i>MLC</i>	2	60.00		120.00	8.40	128.40
Sum Item					3251.58	227.62	3,479.20
BOSUN	(12) SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	(13) REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 ✓		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ? <i>X</i>		80.00	5.60	85.60
BOJSE	(14) SEALANT FOR TAILGATE	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>X</i>		80.00	5.60	85.60
BML02I	(15) INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 ✓		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 <i>X</i>		560.00	39.20	599.20
BMI02D	(16) REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00 <i>280</i>		560.00	39.20	599.20
BKTG02R	(17) REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>280</i>		560.00	39.20	599.20
BG02D	(18) REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00 ✓		560.00	39.20	599.20
BODAMKIT	(19) WINDSCREEN DAM KIT.	1	100.00 ✓		100.00	7.00	107.00
BKRP02M	(20) CUT OFF & RENEW RR PANEL. <i>x 3 chgs 560 p.</i>	1	5000.00 <i>1680</i>		5000.00	350.00	5350.00
BP06R	(21) SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>x 3</i>	1	3000.00 <i>1350</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 <i>X</i>		450.00	31.50	481.50

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SFY5356M
Chassis No : JHMGK3850JX220935
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : JIN QIAN
Ins Policy No. :
Date of Accident : 20/3/2019

Document No. : SQT19001292 Page 3
Date : 20. Mar 2019
Customer No. : WZA006
Svc Advisor :
Engine No : L13B11030701
Date | Time : 20. Mar 2019 8:21:49 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKBU01R	(22) REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	480.00 ✓		480.00	33.60	513.60
Sum Labor					<u>11970.00</u>	<u>837.90</u>	<u>12,807.90</u>

Survey By

Steve Chin 8322 8813

Date & Time

24/4/19 12.10 pm

Excess

Status

Signature

Total Amount 15,221.58 1,065.52 16,287.10

Total (Inclusive of GST) 16,287.10

5 days
w/lt prejudice
P/P
By before sign

Printed on 20/3/2019 8:46:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.