



Your Ref : S9M01H00

Date: 22nd January 2020

Our Ref : CC4/ASM19005151/K1pa3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Richard Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHA 4114D
ACCIDENT ON 13/03/2019 INSURED VEHICLE SJZ 6080Z**

Instruction was received to inspect the vehicle Reg. No. SHA 4114D. The inspection was conducted on 21/03/2019 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:


Registration Number	: SHA 4114D
Make/Model	: Hyundai Sonata
Year of Registration	: 2011
Body Colour	: Blue
Chassis Number	: KMHET41VMBA811422
Engine Capacity	: 1991 cc

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Book Value	S\$ 9,978.06 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 9,819.00) (est)
Nett Liability	<u>S\$ 159.06 (est)</u>

Vehicle Inspected By:



KALVIN ANG WEI KUN
Automotive Assessor / Investigator



K.K. LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.