



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1780A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|----------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER (CONSISTENT) | TO REPAIR SEE LABOUR | 497.50 | - |
| 1 | REAR BUMPER CLIP (CONSISTENT) | NOT NECESSARY | 40.00 | - |
| 1 | REAR BUMPER SIDE RETAINER LH (CONSISTENT) | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER SIDE RETAINER RH (CONSISTENT) | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT) | DENTED /CUT | 582.60 | 582.60 |
| 1 | REAR BUMPER LOWER GARNISH LH (CONSISTENT) | SERVICEABLE | 149.70 | - |
| 1 | REAR BUMPER LOWER GARNISH RH (CONSISTENT) | SERVICEABLE | 149.70 | - |
| 1 | REAR BUMPER TOW COVER (CONSISTENT) | MISSING | 31.70 | 31.70 |
| 1 | TAIL END PANEL (CONSISTENT) | TO REPAIR SEE LABOUR | 596.60 | - |
| 1 | TAIL END PANEL GARNISH (CONSISTENT) | SERVICEABLE | 151.60 | - |
| 10 | TAIL END PANEL GARNISH CLIP (CONSISTENT) | NOT NECESSARY | 35.00 | - |
| 1 | BOOT WEATHERSTRIP (CONSISTENT) | SERVICEABLE | 353.10 | - |
| | LESS 25% DISCOUNT | | -703.23 | -153.58 |
| | | | 2,109.67 | 460.72 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REVERSE SENSOR (CONSISTENT) (SN) | SERVICEABLE | 200.00 | - |
| | | | 200.00 | - |
| <u>LABOUR</u> | | | | |
| | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER ,END PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER AND TAIL END PANEL . | | 600.00 | 200.00 |
| | TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(REAR BUMPER ,END PANEL). | | 600.00 | 220.00 |
| | TO CHECK WIRING. | | 50.00 | 10.00 |
| | TO REMOVE & REFIT REVERSE SENSOR . | | 120.00 | 50.00 |
| | TO TUFF COAT. | NOT NECESSARY | 100.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|---------------|---------------------------|-------------------|
| | TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD. | NOT NECESSARY | 150.00 | - |
| | | | 1,620.00 | 480.00 |
| GRAND TOTAL | | | 3,929.67 | 940.72 |
| RECOMMENDED COST OF REPAIRS | | | | 940.72 |

Report Ref No. CC4/ASM19005157/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.