

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7615A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL SUB-ASSY ,REAR DOOR ,LH (CONSISTENT)	BENT	1,258.30	1,258.30
1	PANEL QUARTER WHEEL HOUSE ,OUTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	290.50	-
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	817.50	-
	LESS 25%DISCOUNT		-591.58	-314.57
			1,774.72	943.73
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
			80.00	60.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,000.00	440.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL QUARTER WHEEL HOUSE ,OUTER LH AND REAR FENDER LH .		3,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			6,900.00	990.00
	GRAND TOTAL		8,754.72	1,993.73

RECOMMENDED COST OF REPAIRS 1,993.7

Report Ref No. CC3/ASM19005193/Kba3q2

KONG SENG CHEONG

Licensed Appraiser