

n2

ASS. REC. BY: REP: CS/FC19005205/ksd3 Special Instruction:

Surveyor: Kenneth ASSIGMENT (Office)

From (Person): Joanne Yong of FCI Date/Time: 5:51pm @ 2/13/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 577B Insured: SH 6717J

at Workshop in/s: -transcab Tel: 6287 6666

of No. 2 AMK St. 63

Policy No: Claim No: D19001941MPH

Sum Insured: Excess:

Make of Veh. (Client's Record) D.O.A. 17/3/2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 2/13/2019 15:00 Person Contacted: Amanda Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 577B - CC3 / ASM12017904 / G1b3 D.O.A - 30/9/2018
	SH 6717J - CS / FCI 16022638 / kvbn2 D.O.A - 24/11/2016
2/13/19 @ 15:34 pm	revised PA to Joanne Yong via email.

ASS. REC. BY:

REF: TP/PCI

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHF 577B Yr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: M. White / RW A/C: Insured / Std / NI / NA

Sp. Reading: 40591 T/Radio: Insured / Std / NI / NA

Eng/No: 783364

C/No: VIFIABL15AUC 278416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 9 mm R/Bal. 8 mm

L/Bal. 9 mm L/Bal. 8 mm

D.O.A. 17/3/19 D.O.I. 21/3/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to L1 Rep @ 6300 (R + 1,393.46 Red - 87%)</u>

RECEIVED 27 MAR 2019

Date/Time, File Pass to? 24/03/19  
1) Typist  
Date/Time, File Return to?

: Prell. Report  
 : Final Report

Days Of Repair: 5  
Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee:	<u>350</u>
Transportation:	
S + RS: SI	
Fuel/OS	
Others	
TOTAL	<u>350</u>

Report Format :  
Lump Sum / I.B.I. (\$) 6,300/- HS



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001941MFSH

Date: 25 March 2019

Our Ref: CS/FCI19005205/Ksd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 577B .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/03/2019 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 47,693.46</u> .
Revised Estimate Amount	: <u>S\$ 7,845.66</u> .
"Check" Items Amount	: <u>S\$</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 5 Days

Yours faithfully,  
Kenneth Kong  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	20-03-2019	<b>Our Ref No.</b> D19001941MFSH
<b>Accident Date</b>	17-03-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SH6717J	<b>Third Party Vehicle.</b> SHF577B
<b>Survey Location</b>	NO. 2 ANG MO KIO STREET 63	
<b>Contact Person.</b>	AMANDA TAY	
<b>Contact No.</b>	62876666/ 0	<b>Fax No.</b> 62571330
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TRANS-CAB AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 26 March 2019 1:07 PM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Cc:** 'SUR'  
**Subject:** FW: TCS REF: AAD1903-115--Accident involving SHF 577B & SH 6717J on 17.03.2019  
**Attachments:** ESTIMATE MARKED.pdf

Hi Shirley

We confirmed COR amount \$6,300 (before GST).

Will send you photo when we receive from our workshop.

Thank You  
Best Regards,  
*Ng Wai Yin*  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shirley Hiew (LKK Auto) [mailto:[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)]  
**Sent:** Tuesday, 26 March, 2019 9:06 AM  
**To:** 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** TCS REF: AAD1903-115--Accident involving SHF 577B & SH 6717J on 17.03.2019

Dear Wai Yin,

Please confirm final fig \$ 6,300.00 (lump sum) @ 5 days of repairs before GST.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 25 March 2019 3:34 PM  
**To:** 'Joanne Yong Lai fong'; 'CWS Motor Claims'  
**Cc:** 'assignments'; 'SUR'; 'Admin-D (LKKAuto)'  
**Subject:** RE: SURVEY ASSESSMENT - D19001941MFSH/1  
**Attachments:** SHF 577B - Preli Advise -.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SHF 577B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 22 March 2019 9:16 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19001941MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Thursday, 21 March 2019 5:51 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001941MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHF577B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001647
Chassis No.:	VF1ABL15AUC278416
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$23,313.00
<b>Total Rebate Amount:</b>	<b>\$32,686.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Mar 2019.

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B****AAD1903-115***Not Authored  
L/Sy 8630d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHF 577B**

VF1ABL15AUC278416

RENAULT

LATITUDE

17.3.2019

**FCIL**

20/6/2014

<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>R</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Bul/nd</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>S</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>S</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>S</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>S</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>D/I</i> 135.97 ✓
8	1 BUMPER RETAINER LH REAR	\$	<i>D/I</i> 44.99 ✓
9	1 BUMPER REFLECTOR LH	\$	<i>C/M</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>S</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>S</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>S</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>S</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
19	1 BOOT BADGE	\$	<i>nn</i> 225.36
20	1 BOOT STRUT LH	\$	<i>S</i> 276.08
21	1 BOOT STRUT RH	\$	<i>S</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>S</i> 586.45
25	1 BOOT SWITCH	\$	<i>S</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>S</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>S</i> 221.81

**Trans-cab Auto Services Pte Ltd**

AAD1903-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

30	1 FENDER PANEL REAR RH	\$	R 3,299.13 X
31	1 WHEELARCH REAR RH	\$	SL 543.47 X
32	1 FENDER PANEL REAR LH	\$	Bu 3,299.13 ✓
33	1 WHEELARCH REAR LH	\$	SL 543.47
34	1 TAILLAMP LH	\$	SL 552.55
35	1 TAILLAMP PANEL LH	\$	R 986.70
36	1 TAILLAMP RH	\$	SL 552.55
37	1 TAILLAMP PANEL RH	\$	R 986.70
38	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL 404.56
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88
41	1 SPARE WHEEL PANEL TRIM	\$	SL 612.21
42	1 EXHAUST REAR	\$	R 7,489.05
43	1 EXHAUST CAP REAR	\$	R 230.49

02

<b>TOTAL</b>	\$	<b>34,526.04</b>
<b>10%</b>	\$	<b>3,452.60</b>
	\$	<b>31,073.44</b>

**Special Nett**

1	1SET PARKING AID	\$	ND 700.00 Good
2	1SET REAR BUMPER CLIP	\$	na 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00 ✓
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	SL 17.82 X
11	1SET BOOT FINISHER CLIP	\$	na 24.20 X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	na 80.00 X
13	1 REAR BOOT STICKER '6555-3333'	\$	na 80.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1903-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

14	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
15	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
16	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18	1 TAILLAMP CLIP RH	\$	na	5.00	X
19	1 TAILLAMP CLIP LH	\$	na	5.00	X
20	2 REAR WINDSCREEN SELANT	\$	na	80.00	405m
21	1 WINDSCREEN MOULDING	\$	na	100.00	—
22	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	305m
23	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sm	385.00	X
24	1 SPARE TYRE	\$	sm	330.00	X

**TOTAL \$ 2,280.02**

**TOTAL PARTS \$ 33,353.46**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1903-115**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 577B**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>100%</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>120%</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>14,340.00</b>	

**Over All Total \$ 47,693.46**

**(LUMP SUM)**

**Repair Days**

*20 DAYS*

*5 days*

*48073.44*

*LKK Auto Consultants* hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005205/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-04-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6717J	Veh. Inspected	SHF 577B
Policy No.		Coverage (\$)	0.00
Claim No.	D19001941MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	21/03/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278416	Colour	METALLIC WHITE / RED
Odometer	783364	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/03/2019	Inspection Date	21/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 577B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	BUCKLED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER LH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FCI19005205/Ksd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,452.60	-617.85
			<b>31,073.42</b>	<b>5,560.67</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	DENTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/FC119005205/Ksd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TRYE (SN)	SERVICEABLE	330.00	-
			2,280.02	935.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR RH, TAILLAMP PANEL LH, TAILLAMP PANEL RH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			14,720.00	1,350.00
	<b>GRAND TOTAL</b>		<b>48,073.44</b>	<b>7,845.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,300.00</b>

Report Ref No. CS/FCI19005205/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.