



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. YK 4334G

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
2	TAIL LAMPS	CRACKED	520.00
1	TAIL END CROSS MEMBER	DENTED	680.00
	LESS 10% DISCOUNT		-120.00
			1,080.00
	<b><u>SPECIAL NETT ITEMS</u></b>		
1	TAIL BUMPER (SN)	BENT	350.00
2	TAIL BUMPER BRACKET (SN)	DENTED	380.00
			730.00
	<b><u>LABOUR</u></b>		
	TO LIFT-UP THE REAR CARGO BOX ,STRAIGHTEN THE CHASSIS FRAME,REPLACE THE REAR CARGO BOX BASE PANEL,AND CROSS PANEL.		1,500.00
	FIX BACK THE BOX,TOUCH -UP THE PAINT WORK,ANTI-RUST COMPOUND.		500.00
			2,000.00
<b>GRAND TOTAL</b>			<b>3,810.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>3,050.00</b>
---	-----------------

Report Ref No. CC7/AIG13012382/Cpq2-1

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.