

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19005254/UGA3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0000335
Claimant Vehicle No : GBE1850G **Insured Vehicle No :** SJM9761R
 Date of Loss: 04/03/2019 Nature of Claim: TP Claim No: MPC2019D0000218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE1850G**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2452365
 Reg. Date: 28/09/2015 (Man. Year: 2014) Chassis No: JTFHT02PX00151942
 Colour: White Odometer: 178720 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	917.20	658.57	258.63	28.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	750.00	350.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,017.20	1,408.57	608.63	30.17
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	2,017.20	1,100.00	917.20	45.47
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		1,460.00		
Liabe Amount (50.00%) (S\$)		730.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		732.00		

INSPECTION

Date of Assignment: 23/03/2019
 Date Inspected: 23/03/2019 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
 Estimated Period of Repair: 4.0 days BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2020)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE1850G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAIL LAMP	Scratched	365.10 F	*365.10 FL
2	1		*REAR LH BUMPER	Cut	465.00 F	*465.00 FL
3	2		*SET REAR LH BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
4	1		*REAR LH BUMPER BRACKET	Not Necessary	39.10 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	917.20	878.10
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	219.53
Total Parts (S\$)	917.20	658.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	300.00
3	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	400.00	400.00
4	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	30.00
Gross Labour Cost (\$)			1,100.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >