

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE1850G190304

Estimate

Customer		Date:	25-03-19
Name:	India International Insurance Pte Ltd	Vehicle No:	GBE1850G
Address	Motor Claims Department	Model/Make:	Toyota Hiace
	64 Cecil Street #04-00 & #05-00		Van Turbo 5 DR Manual
	IOB Building		
	Singapore 049711		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tail Lamp <i>scr</i>	\$ 365.10	
2	Bumper <i>cu7</i>	\$ 465.00	
3	Bumper Clips 2 set <i>mu</i>	\$ 48.00	
4	Bumper Bracket <i>11</i>	\$ 39.10	
	To check all wiring & electrical component for proper function	\$ 50.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 600.00	
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 400.00	
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 2,017.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Authorised
hla
h/s \$1100
23/3/19
the phd after rep
4 day

2-878/
1008-57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: