

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG17024731/ETD3S2-1**Date:** 29/03/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100452439
Claimant Vehicle No :	FBD9751L	Insured Vehicle No :	SDJ4522J
Date of Loss:	08/11/2017	Nature of Claim:	TP
		Claim No:	1468705889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD9751L	Engine No:	0
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	5YP301636
Reg. Date:	14/10/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,449.00	668.70	1,780.30	72.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	360.00	230.00	130.00	36.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,809.00	898.70	1,910.30	68.01
Approved Total (Overridden) (S\$)		700.00		
Nett Amount (S\$)	2,809.00	700.00	2,109.00	75.08

INSPECTION

Date of Assignment:	29/12/2017	
Date Inspected:	29/12/2017	Inspected At: Sanfu Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: COR SUBJECT TO REVIEW UPON ADDITIONAL PHOTOGRAPHS PROVIDED

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT TYRE	Not Necessary	87.00 F	*- FL
2	1		*FRONT & REAR RIMS	Not Necessary	280.00 F	*- FL
3	1		*LOWER STAND	Not Necessary	220.00 F	*- FL
4	1		*LEFT & RIGHT FORKS	Not Necessary	360.00 F	*- FL
5	1		*FAIRINGS	Cut	420.00 F	*300.00 FL
6	1		*FRONT FAIRING BRACKET	Not Necessary	110.00 F	*- FL
7	1		*CON BEARING	Not Necessary	56.00 F	*- FL
8	1		*HANDLE BAR	Bent	60.00 F	*60.00 FL
9	1		*BALANCER	Cut	38.00 F	*38.00 FL
10	1		*THROTTLE GRIP	Not Necessary	18.00 F	*- FL
11	1		*LEFT & RIGHT SIGNAL LIGHT	Not Necessary	50.00 F	*- FL
12	1		*HEADLIGHT	Not Necessary	58.00 F	*- FL
13	1		*REAR BOX	Cut	260.00 F	*260.00 FL
14	1		*BOX BRACKET	Bent	85.00 F	*85.00 FL
15	1		*FRONT NO. PLATE	Not Necessary	18.00 F	*- FL
16	1		*BRAKE LEVER	Not Necessary	18.00 F	*- FL
17	1		*CLUTCH LEVER	Not Necessary	18.00 F	*- FL
18	1		*FRONT BRAKE PAD	Not Necessary	45.00 F	*- FL
19	1		*SET MIRROR	Not Necessary	45.00 F	*- FL
20	1		*LEFT & RIGHT FOOTPEG	Not Necessary	38.00 F	*- FL
21	1		*FOOTPEG BRACKET	Not Necessary	65.00 F	*- FL
22	1		*GEAR PEDAL	Not Necessary	45.00 F	*- FL
23	1		*EXHAUST PIPE COVER	Not Necessary	55.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,449.00	743.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	74.30
Total Parts (\$)	2,449.00	668.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICES	New	60.00	30.00
2	LABOUR COST	New	300.00	200.00
Gross Labour Cost (S\$)			360.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >