



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5760X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	MISSING	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	DISTORTED	135.97	135.97
1	BUMPER RETAINER RH REAR (CONSISTENT)	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	DISTORTED	135.97	135.97
1	BUMPER RETAINER LH REAR (CONSISTENT)	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR LH (CONSISTENT)	CRACKED	43.61	43.61
1	BUMPER BEAM REAR (CONSISTENT)	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	DISTORTED	225.95	225.95
1	BOOT REAR (CONSISTENT)	BENT	2,872.68	2,872.68
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	DISTORTED / CUT	323.05	323.05
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	BROKEN	493.35	493.35
1	BOOT BADGE "RENAULT" (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT BADGE (CONSISTENT)	NECESSARY	225.36	225.36
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	DEFORMED	586.45	586.45
1	BOOT SWITCH (CONSISTENT)	SERVICEABLE	168.13	-
1	BOOT LOCK (CONSISTENT)	DENTED	202.67	202.67
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	DEFORMED	671.45	671.45
1	FENDER PANEL REAR LH (CONSISTENT)	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	BROKEN	552.55	552.55
1	TAILLAMP PANEL LH (CONSISTENT)	BENT	986.70	986.70
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	DENTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	DEFORMED	612.21	612.21
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y (CONSISTENT)	SERVICEABLE	343.57	-
1	WHEEL HOUSING PANEL REAR LH (CONSISTENT)	SERVICEABLE	4,682.09	-
1	BUMPER COVER FRT (CONSISTENT)	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT (CONSISTENT)	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT (CONSISTENT)	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT LH (CONSISTENT)	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	DISTORTED	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	SERVICEABLE	914.08	-

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	RADIATOR GRILLE (CONSISTENT)	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT" (CONSISTENT)	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME (CONSISTENT)	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	177.22	-
1	HORN (CONSISTENT)	SERVICEABLE	314.17	-
1	HORN BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	405.73	-
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	AIR CLEANER LOWER (CONSISTENT)	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE (CONSISTENT)	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY (CONSISTENT)	SERVICEABLE	363.40	-
1	AIR CLEANER BOX (CONSISTENT)	SERVICEABLE	464.20	-
1	TURBO DUCT (CONSISTENT)	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE (CONSISTENT)	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT (CONSISTENT)	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH (CONSISTENT)	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY (CONSISTENT)	SERVICEABLE	564.98	-
1	A/C CONDENSER (CONSISTENT)	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER(CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER(CONSISTENT)	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH (CONSISTENT)	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH (CONSISTENT)	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPANSION VALVE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR (CONSISTENT)	SERVICEABLE	334.29	-
1	A/C PIPE (CONSISTENT)	SERVICEABLE	658.72	-
1	A/C COMPRESSOR (CONSISTENT)	SERVICEABLE	2,684.61	-
1	AIR COOLER (CONSISTENT)	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER (CONSISTENT)	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD (CONSISTENT)	SERVICEABLE	17.96	-
1	RADIATOR (CONSISTENT)	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER (CONSISTENT)	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER (CONSISTENT)	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER (CONSISTENT)	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING (CONSISTENT)	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH (CONSISTENT)	SERVICEABLE	967.36	-

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN MOTOR RH (CONSISTENT)	SERVICEABLE	1,479.46	-
1	RADIATOR TANK (CONSISTENT)	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER (CONSISTENT)	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER (CONSISTENT)	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE (CONSISTENT)	SERVICEABLE	61.18	-
	LESS 10% DISCOUNT		-7,985.79	-2,877.96
			71,872.13	25,901.68
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (CONSISTENT)(SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (CONSISTENT)(SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (CONSISTENT)(SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (CONSISTENT)(SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (CONSISTENT)(SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (CONSISTENT)(SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (CONSISTENT)(SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (CONSISTENT)(SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (CONSISTENT)(SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (CONSISTENT)(SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (CONSISTENT)(SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (CONSISTENT)(SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (CONSISTENT)(SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (CONSISTENT)(SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (CONSISTENT)(SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (CONSISTENT)(SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (CONSISTENT)(SN)	NECESSARY	28.00	28.00
1	FENDER INNER TRIM CLIP RH (CONSISTENT)(SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (CONSISTENT)(SN)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (CONSISTENT)(SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (CONSISTENT)(SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (CONSISTENT)(SN)	NECESSARY	100.00	100.00

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)(SN)	NECESSARY	100.00	30.00
1	SPARE TRYE RIM (ROUE 7J 16H 2547) (CONSISTENT) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (CONSISTENT)(SN)	SERVICEABLE	330.00	-
1	SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)(SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (CONSISTENT)(SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (CONSISTENT)(SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (CONSISTENT)(SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (CONSISTENT)(SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (CONSISTENT)(SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (CONSISTENT)(SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (CONSISTENT)(SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (CONSISTENT)(SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT) (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (CONSISTENT)(SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (CONSISTENT)(SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (CONSISTENT)(SN)	NECESSARY	100.00	100.00
1	SET FRONT LICENCE PLATE WITH HOLDER (CONSISTENT)(SN)	BENT	80.00	45.00
			2,787.52	1,244.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,760.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	80.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	100.00

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULTION PADDING.		380.00	80.00
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	REPEATED	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	REPEATED	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	REPEATED	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	REPEATED	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }		380.00	250.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR. }		380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-

Report Ref No. CC3/ASM19005281/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		6,000.00	2,500.00
	INCLUSIVE OF THE REPAIR OF BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK CATCH,TAILLAMP PANEL RH,EXHAUST REAR,EXHAUST CAP REAR,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK AND FENDER PANEL FRT LH. }		-	-
			19,720.00	5,220.00
GRAND TOTAL			94,379.65	32,365.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				25,900.00

Report Ref No. CC3/ASM19005281/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.