

ASS. REC. BY: REP: CS/FCI 1900 5356/Gqd3ⁿ² Special Instruction:

Atty/Off: ASSIGNMENT (Office)

From Person: Keiren Tan of FCI Date/Time: 11:29am @ 26/3/14

Estimated Cost: Bill to:

OD/TT/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SBS 3976R Insured: SHC 3906G

at Workshop m/s: Soon Bee Vehicle Tel: 90036715

of: 10 Anson Rd # 33-17

Policy No: Claim No: D19002041MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 15/3/2014
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12:58pm @ 26/3/14 Person Contacted: paul H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate Insp: 2 loggers way.
	SBS 3976R - x
	SHC 3906G - CS/FCI 14010162 / 11 gbu 2 D.O.A - 18/5/2014
<u>27/3/14 @ 1:44pm</u>	<u>revised to Keiren Tan by email.</u>

RECEIVED 09 JUL 2014

EXPENSE

600

REF:

Fci

C1900C

ASSIGNMENT

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

at Workshop m/s

Seen Bel

of

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value

IDAC Accident Rpt

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

days

Res.

Yes or No

Lum Sum

20 %

3 Val

Yes or No

CA / REV / REP / 24 HRS

Vehicle IN / OUT

Date

Person Contacted

Veh No

BS3576R

Yr Regn

02 Jun 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Volvo B9TL

9364

Colour

Green

A/C

Insured / Std / NI / NA

Sp. Reading

238912.3

T/Radio

Insured / Std / NI / NA

Eng/No

C/No

YV354P925FA171339

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD A/Rim or

Tyre Size

F:

275/70R22.5

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal

6

mm

R/Bal

6/6

mm

L/Bal

6

mm

L/Bal

6/6

mm

D.O.A

D.O.A

26-03-19

Survey held at

W/S

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fit N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

08/28/3

Finalized \$ 8500 with Paul (Red \$ 6128.81, 42%)

08/27/19

GR ve-finalized 10626.13 with Paul. (Red \$ 4002.63, 27%)

08/27/19

ve-open ref. for amend report. Call 8/27/19.

8/21/15

after re-open pass back to handler.

re-open ref only * 1st close date 23/4/19 *

Date/Time: File Pass to?

☐

Prel. Report

11/2/14 tyro

☐

Final Report

Date/Time: File Return to?

2)

Report Format:

Lump Sum /

1-b. 10626.13

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation

1) S + RS \$

Photo

1) Copy

13/4/19

TOTAL

4x15: 60

170+60

50

50+50

41

41

41

41

41

41

41

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903 hence notify
GST Registration No: 53076555A Email: paul@soonbee-vehicle.com.sg

Quotation No.: SB-GA-TCC18041

COMFORT TRANSPORTATION PTE LTD

Gas Building
383 Sin Ming Drive
Singapore 575717

Dear Sir/Mdm,

Estimated Cost of Repair Job for:

Accident on 15/03/2019, along / at JLN LANGGAR BEDOK X BEDOK RD involving SBS3976R and SHC3906G

- To resurvey before/after spray painting
- To display damaged part(s) for confirmation
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 26-Mar-19

Acknowledged by Repairer:

Signature:

Date:

SBS3976R

We are pleased to submit the below estimated quotation for your consideration.

1)	Vehicle No Model	SBS3976R B9TL-9.4 D AUTO TURBO ABS (A)																																																																																								
2)	<table><thead><tr><th>List Item:</th><th>Qty</th><th>Nett Unit Price: (S\$)</th><th>Sub Total: (S\$)</th></tr></thead><tbody><tr><td>Near side front quarter glass</td><td>1</td><td>\$250.95</td><td>\$250.95</td></tr><tr><td>Near side front corner bumper</td><td>1</td><td>\$623.86</td><td>\$623.86</td></tr><tr><td>Near side front deflector</td><td>1</td><td>\$216.12</td><td>\$216.12</td></tr><tr><td>Near side front light bezel</td><td>1</td><td>\$190.88</td><td>\$190.88</td></tr><tr><td>lower deck front dome</td><td>1</td><td>\$4,163.58</td><td>\$4,163.58</td></tr><tr><td>Entrance door lower frame metal stripe</td><td>1</td><td>\$452.68</td><td>\$452.68</td></tr><tr><td>Main beam headlamp</td><td>1</td><td>\$280.74</td><td>\$280.74</td></tr><tr><td>Paint Material (Green/ white/ grey/ black/ thinner/ lacquer)</td><td>1</td><td>\$1,100.00</td><td>\$1,100.00</td></tr><tr><td colspan="3">Parts Total Sum:</td><td>\$7,278.81</td></tr><tr><td colspan="4">Labour:</td></tr><tr><td>Labour charges to remove and refit near side front corner bumper, near side front deflector, near side front light bezel</td><td></td><td rowspan="3">\$4,800.00</td><td rowspan="3">580 x 15 = 2900</td></tr><tr><td>Labour charges to remove and refit near side front quarter glass with sealant, lower deck front dome</td><td></td></tr><tr><td>Labour charges to remove and refit entrance door lower frame metal stripe</td><td></td></tr><tr><td>Labour charges to remove and refit near side main beam headlamp, dipped beam headlamp, front indicator, near side front corner bumper bracket holder</td><td></td><td></td><td></td></tr><tr><td>Labour charges to check and rectify wiring</td><td></td><td>\$150.00</td><td></td></tr><tr><td>Labour charges to re-spray and polishing</td><td></td><td>\$2,400.00</td><td></td></tr><tr><td colspan="3">Labour Total Sum:</td><td>\$7,350.00</td></tr><tr><td colspan="3">Parts and Labour Total Cost:</td><td>\$14,628.81</td></tr><tr><td colspan="3">GST (7%) :</td><td>\$1,024.02</td></tr><tr><td colspan="3">Total :</td><td>\$15,652.83</td></tr><tr><td colspan="3">Repair Duration:</td><td>9 Working Day</td></tr><tr><td colspan="3">Term of Payment:</td><td>30 Days Upon Invoice</td></tr></tbody></table>	List Item:	Qty	Nett Unit Price: (S\$)	Sub Total: (S\$)	Near side front quarter glass	1	\$250.95	\$250.95	Near side front corner bumper	1	\$623.86	\$623.86	Near side front deflector	1	\$216.12	\$216.12	Near side front light bezel	1	\$190.88	\$190.88	lower deck front dome	1	\$4,163.58	\$4,163.58	Entrance door lower frame metal stripe	1	\$452.68	\$452.68	Main beam headlamp	1	\$280.74	\$280.74	Paint Material (Green/ white/ grey/ black/ thinner/ lacquer)	1	\$1,100.00	\$1,100.00	Parts Total Sum:			\$7,278.81	Labour:				Labour charges to remove and refit near side front corner bumper, near side front deflector, near side front light bezel		\$4,800.00	580 x 15 = 2900	Labour charges to remove and refit near side front quarter glass with sealant, lower deck front dome		Labour charges to remove and refit entrance door lower frame metal stripe		Labour charges to remove and refit near side main beam headlamp, dipped beam headlamp, front indicator, near side front corner bumper bracket holder				Labour charges to check and rectify wiring		\$150.00		Labour charges to re-spray and polishing		\$2,400.00		Labour Total Sum:			\$7,350.00	Parts and Labour Total Cost:			\$14,628.81	GST (7%) :			\$1,024.02	Total :			\$15,652.83	Repair Duration:			9 Working Day	Term of Payment:			30 Days Upon Invoice	
List Item:	Qty	Nett Unit Price: (S\$)	Sub Total: (S\$)																																																																																							
Near side front quarter glass	1	\$250.95	\$250.95																																																																																							
Near side front corner bumper	1	\$623.86	\$623.86																																																																																							
Near side front deflector	1	\$216.12	\$216.12																																																																																							
Near side front light bezel	1	\$190.88	\$190.88																																																																																							
lower deck front dome	1	\$4,163.58	\$4,163.58																																																																																							
Entrance door lower frame metal stripe	1	\$452.68	\$452.68																																																																																							
Main beam headlamp	1	\$280.74	\$280.74																																																																																							
Paint Material (Green/ white/ grey/ black/ thinner/ lacquer)	1	\$1,100.00	\$1,100.00																																																																																							
Parts Total Sum:			\$7,278.81																																																																																							
Labour:																																																																																										
Labour charges to remove and refit near side front corner bumper, near side front deflector, near side front light bezel		\$4,800.00	580 x 15 = 2900																																																																																							
Labour charges to remove and refit near side front quarter glass with sealant, lower deck front dome																																																																																										
Labour charges to remove and refit entrance door lower frame metal stripe																																																																																										
Labour charges to remove and refit near side main beam headlamp, dipped beam headlamp, front indicator, near side front corner bumper bracket holder																																																																																										
Labour charges to check and rectify wiring		\$150.00																																																																																								
Labour charges to re-spray and polishing		\$2,400.00																																																																																								
Labour Total Sum:			\$7,350.00																																																																																							
Parts and Labour Total Cost:			\$14,628.81																																																																																							
GST (7%) :			\$1,024.02																																																																																							
Total :			\$15,652.83																																																																																							
Repair Duration:			9 Working Day																																																																																							
Term of Payment:			30 Days Upon Invoice																																																																																							

Regards,

Surveyor Name:

Surveyor NRIC:

1st Signature /Date:

2nd Signature / Date:

3rd Signature / Date:

Appointed Surveyor confirmation & agreed:

Surveyor Name: Kevin Giam

Surveyor NRIC: 82880282

1st Signature /Date: 6/26/3/19

2nd Signature / Date:

3rd Signature / Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 3976R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NEAR SIDE FRONT QUARTER GLASS	CRACKED	250.95	250.95
1	NEAR SIDE FRONT CORNER BUMPER	CRACKED	623.86	623.86
1	NEAR SIDE FRONT DEFLECTOR	CRACKED	216.12	216.12
1	NEAR SIDE FRONT LIGHT BEZEL	CRACKED	190.88	190.88
1	LOWER DECK FRONT DOME	BROKEN	4,163.58	4,163.58
1	ENTRANCE DOOR LOWER FRAME METAL STRIPE	TO REPAIR SEE LABOUR	452.68	-
1	MAIN BEAM HEADLAMP	CRACKED	280.74	280.74
			6,178.81	5,726.13
	LABOUR			
	PAINT MATERIAL (GREEN/WHITE/GREY/BLACK/THINNER/LACQUER).		1,100.00	1,100.00
	LABOUR CHARGES TO REMOVE AND REFIT NEAR SIDE FRONT CORNER BUMPER,NEAR SIDE FRONT DEFLECTOR,NEAR SIDE FRONT LIGHT BEZEL. }		4,800.00	2,900.00
	LABOUR CHARGES TO REMOVE AND REFIT NEAR SIDE FRONT QUARTER GLASS WITH SEALANT,LOWER DECK FRONT DOME. }		-	-
	LABOUR CHARGES TO REMOVE AND REFIT ENTRANCE DOOR LOWER FRAME METAL STRIPE. }		-	-
	LABOUR CHARGES TO REMOVE AND REFIT NEAR SIDE MAIN BEAM HEADLAMP,DIPPED BEAM HEADLAMP,FRONT INDICATOR,NEAR SIDE FRONT CORNER BUMPER BRACKET HOLDER. }		-	-
	LABOUR CHARGES TO CHECK AND RECTIFY WIRING.		150.00	30.00
	LABOUR CHARGES TO RE-SPRAY AND POLISHING.		2,400.00	870.00
	-		-	-
	-		-	-
	-		-	-
			8,450.00	4,900.00
	GRAND TOTAL		14,628.81	10,626.13
RECOMMENDED COST OF REPAIRS				10,626.13

Report Ref No. CS/FCI19005356/Gqd3n2



Report Ref No. CS/FCI19005356/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.