## XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933 Tel : 6844-1985 Fax : 6844-5185 Reg : 201838521G

## Repair Estimate

Date: 26/03/2019

Reference: MERCEDES

Make: E250

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SDE6869Y

CHASSIS NO.: WDD2120362B128793

ENGINE NO.: 27492030354227

Name of insured .: FAIZAL GAFFOOR

Date of accident.: 23/03/2019

TO AXA.

Xino Tony

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

## **Parts**

4	Qty	- Fait Description	
1	1	IKK BUMPER ONSELL A	Price (SGD)
2	1	RR BUMPER SIDE RETAINER RH	\$ 2,706.10 - 178
3	1	RR BUMPER BRACKET RH	\$ 96.30 *.
4	1	RR BUMPER LOW BRACKET RH	\$ 81.90 +
5	1		\$ 93.10 4
6	1	IRR BUMPER CUROME MURQUUI	\$ 184.50
7	1	RR BUMPER LOW	\$ 184.50 4
8	1	PP BLIMPED TOWN	101.00
9	1	DD DI IMPED DEL IE	
0	1	RR BUMPER REVERSE SENSOR I piece de d	100.00
1	1	THE BUILDING EXHAUST FINISHED DU XI.	20 1.10
2	1	RR BUMPER REINFORCEMENT )	110.20 1
3	1	RR BOOTLID	\$ 1,035.80 +
4	1	RR BOOTLID REFLECTOR RH	\$ 3,345.70 +
5	1	RR TAILLAMP RH RR END PANEL	\$ 745.90 +
_	1	RR END PANEL	\$ 929.50
6	1	RR FENDER RH	\$ 1,614.50 \$
7	1	RR FENDER AIR DUCT RH	\$ 1,809.80
8	1	RR FENDER INNERSHILED	\$ 506.80 ×
			\$ 381.10 *

3340.5-10% = 3006.45

Parts Total: \$

15,601.20

Less10%: \$

1,560.12

Total: \$

14,041.08

## Labour

Labour Description
--------------------

1	To dismantle / renew the accident damaged portion,to panel		Price (SGD)	
	beating,reshape,straighten,orientate and align repair /replacement parts.	\$ 1,000.	1,000.00	

350

3,040.00

17,141.08

Carry out spray painting on affected area, RR BUMPER, RR BOOTLID, RR END PANEL, RR FENDER RH \$ 1,000.00 3 To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair \$ 120:00 4 Remove and refix seat cushion/upholstery & roof lining to facilitate repairs \$ 200.00 5 To remove and refix reverse sensor and conduct test \$ 50. 160,00 6 To conduct transfer of parts from old bootlid to new bootlid \$ 180.00 7 To remove and replace exhaust pipe \$ 180.00 8 To conduct reset of engine light on \$ 200.00 830

**Others** 

Other Description

No. 1 10 RR BUMPER CLIP		Pri \$	ice (SGD) 69:00 37	
	30		30.00	
		Other Total:	60.00	
		TOTAL:	17,141.08	

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor Kelvin Chew

HP: 8292 5595 Fax: 68445185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total: \$

GRAND TOTAL :

total: #3866.45 = Part by Part SDE68694