



Accident Sketch Plan Pg.1



POLICE REPORT Pg.1

24-MAR-2013 14:48

INFORM HIN BHRDWHRE

T00 01400002

P.00

Police Station Of Origin:

Kampong Ubi NPP

9 Eunos Crescent #01-2687 SINGAPORE 40000

Tel No: 1800-7479999



T/20130418/4092

1 of 4

Report No. T/20130418/4092

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/04/2013 14:48			Vide Report No.:		Station Diary No.: 5
Name of Informant: SIM TECK GUAN			Address: APT BLK 353C ADMIRALTY DRIVE #12-268 SINGAPORE 753353		
ID Type / ID No.: NRIC NO / S1448576G			Contact No.:		
Nationality: SINGAPORE CITIZEN			Home/Office:		Mobile/Pager: 98379735
Email:					
Sex: Male	Age: 53	Date of Birth: 30/05/1960	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Driver			Driving Licence Information: Class: 3,4,5		
Date of Expiry:					

Type of Accident:	Non-Injury Government Property	Drink Drive:	No	Date/Time of Accident:	17/04/2013 15:50	Type of Location:	Straight Road
Location: Along Road 1 PATERSON ROAD HEADING TOWARDS NEWTON CIRCLE							
Weather: Clear		Road Surface: Dry		Road Speed Limit:			
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy			
Type of Collision: Between Moving Vehicles - Head To Rear						Anyone conveyed by ambulance: No	

GZ9505G	Van	RENAUL T	WHITE	Slightly Damaged	2				
XB3520B	Lorry	MITSUBI SHI	BLUE	Slightly Damaged	0	AXA INSURAN CE SINGAPO RE PTE LTD	VCB/P09 73077	11/05/2012	10/05/2013
YM178G	Lorry	MITSUBI SHI	WHITE	Slightly Damaged	1				

POLICE REPORT Pg.1

24 APR 2013 14:44

PULAU PINANG

100 01400002

1.07

Police Station Of Origin:

Kampong Ubi NPP

9 Eunos Crescent #01-2687 SINGAPORE 40000

Tel No: 1800-7479999



T/20130418/4092

2 of 4

Report No. T/20130418/4092

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ISKANDARUDDIN BIN SHADAT KADARISMAN	ID No.	S7017524Z
Related Vehicle	GZ9505G (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
Name	SIM TECK GUAN	ID No.	S1448576G
Related Vehicle	XB3520B (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
Name	WONG THIA HENG	ID No.	S7524468A
Related Vehicle	YM178G (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

On 17/04/2013 at about 1551hrs, I was travelling in my lorry with a crane loaded on the rear deck along Paterson Road heading towards Newton Circle along lane 1, while approaching the junction with Orchard Boulevard, I spotted the traffic light signal was red, as such I stepped on my brake to slow my vehicle down. However, I discovered that my vehicle's brake pedal was not functioning, and my vehicle continued to travel forward. As such, I changed to lane 2 (extreme left lane) as there were lesser vehicles in that lane ahead of me, compared to lane 1. I tried to step on the brake again, however, the brake is still not functioning. Thus, the front side of my vehicle hit onto the rear of the van (GZ9505G) in front of my vehicle, which subsequently hit onto the rear of the lorry (YM178G) which is in front of the van. My vehicle then continued to mount the kerb on the left side, and hit onto a switch box as well as the traffic light post. The switch box then was detached from the ground, and the traffic light post was slanting to the side. No one was injured to the best of my knowledge. Damages to my lorry as follows: 1) both headlight smashed, 2) front bumper slightly dented, 3) both front wheel mudguard was damaged, 5) driver's

POLICE REPORT Pg.1

24-APR-2013 14:46

THIAM AIK HARDWARE

+65 67430882

P.06

Police Station Of Origin:

Kampong Ubi NPP

9 Eunos Crescent #01-2687 SINGAPORE 40000

Tel No: 1800-7479999



T/20130418/4092

3 of 4

Report No. T/20130418/4092

CONTINUATION OF REPORT

door is jammed and unable to open, 6) the front windscreen cracked.

POLICE REPORT Pg.1

24-APR-2013 14:43

THIAM AIK HARDWARE

+65 67430882

P. 03

Police Station Of Origin:

Kampong Ubi NPP

9 Eunos Crescent #01-2687 SINGAPORE 40000

Tel No: 1800-7479999



T/20130418/4092

4 of 4

Report No. T/20130418/4092

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

MUHAMMAD HAFIZ BIN MOHD EKBAL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date:

18/04/2013 14:48

Officer In Charge Of Case:

TP /

Contact No.:

Classification Of Case:

Authentication Stamp

NP168



JN 019

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Stve Pte Ltd
No. 5 Old Toh Tuck Road
Singapore 597647

Date : 22/05/2013
Invoice No : IV13-05057/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle GZ 9505G (Inclusive Of Photographs And Transport Charges) Our reference : CAS/13-05/057	\$1,102.00
Total	\$1,102.00

E. & O E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Stve Pte Ltd
No. 5 Old Toh Tuck Road
Singapore 597647

Date : 22/05/2013

Reference No : CAS/13-05/057

General Information

Registration No. : GZ 9505G
Accident Date : 17/04/2013

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Renault Kangoo DCI70
Engine Capacity	: 1461 cc	Pre-Accident Condition	: Fair
Mileage (KM)	: 129353	Engine No.	: K9KW714D083795
Chassis No.	: VF1FC1EAF36539067	Steering	: In Order
Registration Date	: 13/11/2006	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	175/65R14	Dunlop	80%
L/H Front Tyre	175/65R14	Dunlop	80%
R/H Rear Tyre	175/65R14	Dunlop	80%
L/H Rear Tyre	175/65R14	Dunlop	80%

Inspection

Repairer : Yeo & Partner
20 Kranji Way, Singapore 739431

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$35,413.51
Revised Amount : \$23,750.00
Less Excess : -
Nett Total : \$23,750.00

Remarks

- (A) Survey was done on 25/04/2013
(B) Re-survey was done on 04/05/2013
(C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
(D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : GZ 9505G

Our ref : CAS/13-05/057

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Rear windscreen glass LH	Broken	345.00	345.00
2	1pc	Rear windscreen rubber LH	Cut	262.00	262.00
3	1pc	Rear windscreen rubber RH	Serviceable	196.00	-
4	1pc	Rear tailgate LH	Dented	1,065.00	1,065.00
5	1pc	Rear tailgate third brake light LH	Broken	132.50	132.50
6	1pc	Rear tailgate licence lamp LH	Cracked	182.60	182.60
7	1pc	Rear tailgate outer garnish LH	Broken	341.20	341.20
8	1pc	Rear tailgate top inner lock LH	Bent	121.50	121.50
9	1pc	Rear tailgate lower inner lock LH	Bent	121.50	121.50
10	1pc	Rear tailgate lock striker top LH	Bent	48.50	48.50
11	1pc	Rear tailgate lock striker lower LH	Bent	48.50	48.50
12	1pc	Rear tailgate wiper motor LH	Damaged	281.90	281.90
13	1pc	Rear tailgate wiper arm LH	Bent	68.50	68.50
14	1pc	Rear tailgate weatherstrip LH	Necessary	142.60	142.60
15	1pc	Rear tailgate checker LH	Bent	105.00	105.00
16	2pcs	Rear tailgate hinge LH @ \$115.00	Bent	230.00	230.00
17	1pc	Rear tailgate inner trim LH	Broken	142.00	142.00
18	1pc	Rear bumper	Dented/Cut	615.00	615.00
19	1pc	Rear bumper reflector	Necessary	42.00	42.00
20	1pc	Rear taillamp LH	Broken	489.00	489.00
21	1pc	Rear taillamp filler panel LH	Dented	1,085.00	1,085.00
22	1pc	Rear taillamp filler panel inner LH	Dented	596.00	596.00
23	1pc	Rear fender LH	Dented/Buckled	2,865.00	2,865.00
24	1pc	Rear fender inner trim LH	Distorted	246.00	246.00
25	1pc	Rear fender inner panel LH	Dented/Buckled	1,065.00	1,065.00
26	1pc	Rear fender wheel housing LH	Repair	1,325.00	-
27	1pc	Rear fender wheel housing trim LH	Deformed	182.00	182.00
28	1pc	Rear sliding door LH	Bent/Twisted	1,862.00	1,862.00
29	1pc	Rear sliding door rail track LH	Bent	189.00	189.00
30	1pc	Rear sliding door inner lock LH	Bent	241.50	241.50
31	1pc	Roof top panel	Dented/Buckled	2,165.50	2,165.50
32	1pc	Roof top upholstery trim	Distorted	1,026.50	1,026.50
33	1pc	Roof top moulding LH	Bent	142.60	142.60

Constant Appraiser Services

Vehicle No : GZ 9505G

Our ref : CAS/13-05/057

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>			8020.80
34	1pc	Front bonnet	Dented/Buckled	754.50	754.50
35	1pc	Front bonnet insulator	Distorted	241.20	241.20 X sue
36	1pc	Front bonnet lock	Bent	126.50	126.50
37	1pc	Front bonnet lock cable	Jammed	68.50	68.50 X sue
38	1pc	Front bonnet inner air vent	Broken	82.60	82.60 X sue
39	2pcs	Front bonnet hinge @ \$55.00 1pc	Bent	110.00	110.00 55
40	1pc	Front grille base	Broken	281.60	281.60
41	1pc	Front grille logo	Broken	89.20	89.20
42	1pc	Front grille apron	Bent/Twisted	265.00	265.00
43	2pcs	Front headlamp @ \$578.00	Broken	1,156.00	1,156.00 578
44	1pc	Front bumper	Broken	645.00	645.00
45	2pcs	Front bumper side cover @ \$82.00	N/S Broken	164.00	82.00
46	1pc	Front bumper reinforcement	Bent	435.00	435.00
47	2pcs	Front bumper side bracket @ \$46.50	Bent	93.00	93.00 46.50
48	2pcs	Front fender @ \$615.00	N/S Buckled	1,230.00	615.00
49	2pcs	Front fender inner shield @ \$132.50	Serviceable	265.00	-
50	1pc	Front fender inner panel LH	Repair	562.00	-
51	1pc	Front support panel	Bent/Twisted	765.00	765.00
52	1pc	Air con condenser	Dented	741.60	741.60
53	1pc	Air con discharge pipe	Serviceable	341.50	-
54	1pc	Air con suction pipe	Serviceable	281.60	-
55	1pc	Air con liquid pipe	Serviceable	195.00	-
56	1pc	Radiator assy	Dented	680.90	680.90
57	1pc	Radiator top hose	Bent	55.60	55.60 X sue
58	1pc	Radiator bottom hose	Bent	58.90	58.90 X sue
59	1pc	Radiator electrical fan assy	Scratched/Jammed	595.00	595.00
60	1pc	Radiator spare tank	Serviceable	126.20	-
61	1pc	Air cleaner intake	Dented	121.20	121.20 X sue
62	1pc	Power steering pump	Serviceable	1,485.90	-
63	1pc	Air intercooler assy	Dented	1,265.00	1,265.00
				20759.80	
				10%	
				18683.82	
		Less 10%		31,253.90	25,778.70
				(3,125.39)	(2,577.87)
		Sub total		28,128.51	23,200.83

Constant Appraiser Services

Vehicle No : GZ 9505G

Our ref : CAS/13-05/057

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1set	Rear reverse sensor	Cut	280.00	220.00
2	1set	Rear no plate with holder	Bent	50.00	35 45.00
3	1set	Front bonnet insulator clip	Necessary	35.00	35.00
4	1set	Front no plate with holder	Bent	50.00	35 45.00
5	1pc	Battery	Cut (50%)	250.00	125.00
6	1bot	Air con oil	Necessary	65.00	65.00
7	1bot	Radiator coolant	Necessary	45.00	45.00
Sub total				28,903.51	23,780.83
<u>LABOUR & MISC. CHARGES</u>					
1		To tow accident vehicle to workshop		100.00	80.00 60
2		To checkup electrical wiring		80.00	60.00 30
3		To remove, refix rear windscreen glass & sliding door glass		240.00	220.00 80
4		To remove, refix reverse sensor		60.00	40.00
5		To respray undercoating		250.00	220.00 80
6		To respray painting & etc		2,000.00	1,800.00 1200
7		To remove, refix A/C condenser & refill A/C gas		130.00	120.00 80
8		To remove, refix interior upholstery to assist repair		150.00	120.00 60
9		Panel beating, remove & replacing		3,500.00	3,200.00 2000
Grand total				35,413.51	29,640.83
Recommended cost of lump sum repair (To its pre-accident condition)					23,750.00

18683.82

560.00

3630.00

22,873.82

20%

18,299.05

2/1-18,300

12 days

Constant Appraiser Services

Vehicle No : GZ 9505G

Our ref : CAS/13-05/057

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$23,750.00 on a contractual basis. Under normal circumstances, the repair period would be about 14 (Fourteen) working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 9505G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN GLASS LH	BROKEN	345.00	345.00
1	REAR WINDSCREEN RUBBER LH	CUT	262.00	262.00
1	REAR WINDSCREEN RUBBER RH	SERVICEABLE	196.00	-
1	REAR TAILGATE LH	DENTED	1,065.00	1,065.00
1	REAR TAILGATE THIRD BRAKE LIGHT LH	BROKEN	132.50	132.50
1	REAR TAILGATE LICENCE LAMP LH	CRACKED	182.60	182.60
1	REAR TAILGATE OUTER GARNISH LH	BROKEN	341.20	341.20
1	REAR TAILGATE TOP INNER LOCK LH	BENT	121.50	121.50
1	REAR TAILGATE LOWER INNER LOCK LH	BENT	121.50	121.50
1	REAR TAILGATE LOCK STRIKER TOP LH	BENT	48.50	48.50
1	REAR TAILGATE LOCK STRIKER LOWER LH	BENT	48.50	48.50
1	REAR TAILGATE WIPER MOTOR LH	SERVICEABLE	281.90	-
1	REAR TAILGATE WIPER ARM LH	SERVICEABLE	68.50	-
1	REAR TAILGATE WEATHERSTRIP LH	NECESSARY	142.60	142.60
1	REAR TAILGATE CHECKER LH	BENT	105.00	105.00
2	REAR TAILGATE HINGE LH @ \$115.00	BENT	230.00	230.00
1	REAR TAILGATE INNER TRIM LH	BROKEN	142.00	142.00
1	REAR BUMPER	DENTED / CUT	615.00	615.00
1	REAR BUMPER REFLECTOR	SERVICEABLE	42.00	-
1	REAR TAILLAMP LH	BROKEN	489.00	489.00
1	REAR TAILLAMP FILLER PANEL LH	DENTED	1,085.00	1,085.00
1	REAR TAILLAMP FILLER PANEL INNER LH	DENTED	596.00	596.00
1	REAR FENDER LH	DENTED / BUCKLED	2,865.00	2,865.00
1	REAR FENDER INNER TRIM LH	DISTORTED	246.00	246.00
1	REAR FENDER INNER PANEL LH	DENTED / BUCKLED	1,065.00	1,065.00
1	REAR FENDER WHEEL HOUSING LH	TO REPAIR SEE LABOUR	1,325.00	-
1	REAR FENDER WHEEL HOUSING TRIM LH	DEFORMED	182.00	182.00
1	REAR SLIDING DOOR LH	SERVICEABLE	1,862.00	-
1	REAR SLIDING DOOR RAIL TRACK LH	SERVICEABLE	189.00	-

Report Ref No. CS3/AXA13007521/R1sd3s2-2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SLIDING DOOR INNER LOCK LH	SERVICEABLE	241.50	-
1	ROOF TOP PANEL	DENTED / BUCKLED	2,165.50	2,165.50
1	ROOF TOP UPHOLSTERY TRIM	SERVICEABLE	1,026.50	-
1	ROOF TOP MOULDING LH	BENT	142.60	142.60
1	FRONT BONNET	DENTED / BUCKLED	754.50	754.50
1	FRONT BONNET INSULATOR	SERVICEABLE	241.20	-
1	FRONT BONNET LOCK	BENT	126.50	126.50
1	FRONT BONNET LOCK CABLE	SERVICEABLE	68.50	-
1	FRONT BONNET INNER AIR VENT	SERVICEABLE	82.60	-
2	FRONT BONNET HINGE @ \$55.00	BENT 1PC ONLY	110.00	55.00
1	FRONT GRILLE BASE	BROKEN	281.60	281.60
1	FRONT GRILLE LOGO	BROKEN	89.20	89.20
1	FRONT GRILLE APRON	BENT / TWISTED	265.00	265.00
2	FRONT HEADLAMP @ \$578.00	BROKEN 1PC ONLY	1,156.00	578.00
1	FRONT BUMPER	BROKEN	645.00	645.00
2	FRONT BUMPER SIDE COVER @ \$82.00	N/S BROKEN	164.00	82.00
1	FRONT BUMPER REINFORCEMENT	BENT	435.00	435.00
2	FRONT BUMPER SIDE BRACKET @ \$46.50	BENT 1PC ONLY	93.00	46.50
2	FRONT FENDER @ \$615.00	N/S BUCKLED	1,230.00	615.00
2	FRONT FENDER INNER SHIELD @ \$132.50	SERVICEABLE	265.00	-
1	FRONT FENDER INNER PANEL LH	TO REPAIR SEE LABOUR	562.00	-
1	FRONT SUPPORT PANEL	BENT / TWISTED	765.00	765.00
1	AIR CON CONDENSER	DENTED	741.60	741.60
1	AIR CON DISCHARGE	SERVICEABLE	341.50	-
1	AIR CON SUCTION PIPE	SERVICEABLE	281.60	-
1	AIR CON LIQUID PIPE	SERVICEABLE	195.00	-
1	RADIATOR ASSY	DENTED	680.90	680.90
1	RADIATOR TOP HOSE	SERVICEABLE	55.60	-
1	RADIATOR BOTTOM HOSE	SERVICEABLE	58.90	-
1	RADIATOR ELECTRICAL FAN ASSY	SCRATCHED / JAMMED	595.00	595.00

Report Ref No. CS3/AXA13007521/R1sd3s2-2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR SPARE TANK	SERVICEABLE	126.20	-
1	AIR CLEANER INTAKE	SERVICEABLE	121.20	-
1	POWER STEERING PUMP	SERVICEABLE	1,485.90	-
1	AIR INTERCOOLER ASSY	DENTED	1,265.00	1,265.00
	LESS 10% DISCOUNT		-3,125.39	-2,075.98
			28,128.51	18,683.82
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	CUT	280.00	220.00
1	SET REAR NO PLATE WITH HOLDER (SN)	BENT	50.00	35.00
1	SET FRONT BONNET INSULATOR CLIP (SN)	NECESSARY	35.00	35.00
1	SET FRONT NO PLATE WITH HOLDER (SN)	BENT	50.00	35.00
1	BATTERY (50%) (SN)	CUT	250.00	125.00
1	BOT AIR CON OIL (SN)	NECESSARY	65.00	65.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	45.00	45.00
			775.00	560.00
	<u>LABOUR</u>			
	TO TOW ACCIDENT VEHICLE TO WORKSHOP.		100.00	60.00
1	TO CHECKUP ELETRICAL WIRING.		80.00	30.00
	TO REMOVE, REFIX REAR WINDSCREEN GLASS & SLIDING DOOR GLASS.		240.00	80.00
	TO REMOVE, REFIX REVERSE SENSOR.		60.00	40.00
	TO RESPRAY UNDERCOATING.		250.00	80.00
	TO RESPRAY PAINTING & ETC.		2,000.00	1,200.00
	TO REMOVE, REFIX A/C CONDENSER & REFILL A/C GAS.		130.00	80.00
	TO REMOVE, REFIX INTERIOR UPHOLSTERY TO ASSIST REPAIR.		150.00	60.00
	PANEL BEATING REMOVE & REPLACING. INCLUSIVE OF THE REPAIR OF REAR FENDER WHEEL HOUSING LH AND FRONT FENDER INNER PANEL LH.		3,500.00	2,000.00
			6,510.00	3,630.00
	GRAND TOTAL		35,413.51	22,873.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,300.00

Report Ref No. CS3/AXA13007521/R1sd3s2-2



Report Ref No. CS3/AXA13007521/R1sd3s2-2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.