

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19005488/GRA3Q2**Date:** 03/02/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994421
Claimant
Vehicle No : GBD7070G **Insured Vehicle No :** SME7570U
Date of Loss: 09/01/2019 Nature of Claim: TP Claim No: 1719126955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD7070G**
Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) Engine No: K9KC400D054230
Reg. Date: 10/03/2015 (Man. Year: 2014) Chassis No: VSKYBAM20Z0092675
Colour: Blue Odometer: 51010 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Neuton 5 mm Rear Left Side: Neuton 5 mm
Front Right Side: Neuton 5 mm Rear Right Side: Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	958.00	150.00	808.00	84.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	350.00	400.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,708.00	500.00	1,208.00	70.73
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		747.00		

INSPECTION

Date of Assignment: 28/03/2019
Date Inspected: 28/03/2019 Inspected At: Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR LH TAIL LAMP	Not Necessary	80.00 FL	*- FL	
2	4		*DOOR HINGE	Not Necessary	180.00 FL	*- FL	
3	1		*STICKER (REAR LH FENDER,REAR BUMPER)	Necessary	750.00 FS	*150.00 FS	
					Sub Total (\$)	1,010.00	150.00
					- List Item Discount on L Items 20.00/20.00% (\$)	52.00	0.00
					Total Parts (\$)	958.00	150.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR REAR DOOR	New	250.00	200.00
2	REPAIR REAR LH FENDER	New	300.00	0.00
3	REPAIR REAR BUMPER	New	200.00	150.00
Gross Labour Cost (\$\$)			750.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >