

22/03/2002

ASS. REC. BY:

REF: CS/MSG19005502/AGQ d30d Special Instruction:

SUNAJOR: GQ

ASSIGNMENT (Office)

Merrin

From (Person): Christina Wong

of MSI

Date/Time: 28.3.2019 9.539.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLB 3816 R

Insured: SDM7827 U

at Workshop m/s Modern Automotive

Tel: 67484422 / 6747 4422

of BLK 3023A Ubi Road 1, #01-61 & # 01-58

Policy No: 80449118

Claim No: 588620

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 28.3.19 10.309.m

Person Contacted: Grace

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 3816 R X SDM 7827 U X
28/3/19 @ 12pm	Informed Christina Wong, we are pending estimate from repairer.
12/4/19 @ 12.15pm	Revised to Christina Wong via Merrin.
	US \$5550, 6 days (incl \$5009.40, 42%)

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB3816R Yr Regn: 2016 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c. 1986Colour Black A/C: Insured / Std / NI / NASp. Reading 76256 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU600071713Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/65R17R: 225/65R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/03/19Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16.

RECEIVED 15 APR 2019

mv:

PV:

Nett:

Date/Time, File Pass to?

1) 15/4 2019

3)

5)

Preli Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2019		28 Mar 2019 09:53 Assign				New Assignment Cancel Case

Main Reference Claim Details Documents Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WONG CHEE KIN , ID: S7140109Z, Tel: +6596889619		
Main Claimant:	WONG LING PAU , ID: S7170995G		
Vehicle Reg. No.:	SLB3816R	Date of Loss:	24/03/2019 18:00 - :59 [35 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 588620	Policy/Cover Note No.:	80449118 (Comprehensive) Coverage: 08/12/2018 - 07/12/2019
Vehicle Reg. No. (Insured):	SDM7827U	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/03/2019]		
Driver/Custodian (Insured):	HENG BOON PING MICAH (), NRIC: S7143328E, Tel: +6598152883 Email:		
Adj Asg. Remarks:	Liability unclear. TP want to use LKK as the SJE. Contact Person: Grace Chin / 6748 4422. On WP.		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Apr 2019

Preliminary Advice

Insured Vehicle No	: SDM7827U	Accident Date	: 24/03/2019
TP Vehicle No	: SLB3816R	Assignment Date	: 28/03/2019
Make	: TOYOTA HARRIER 2.0	Est. Duration of Repair	: 6.00
Date of Inspection	: 27/03/2019		
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,559.40
Revised Amount	:S\$	6,941.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,941.03
Lump Sum Repair	:S\$	5,550.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0995G
Vehicle Details	
Vehicle No.:	SLB3816R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB724190
Chassis No.:	ZSU600071713
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$30,993.00
Original Registration Date:	05 Apr 2016
First Registration Date:	05 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$30,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2026
PARF Rebate Amount:	\$22,793.00
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$32,453.00
Total Rebate Amount:	\$55,246.00

The information contained herein is correct as at 12 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 13:31
Date Of Accident	24/03/2019 18:15
Exact Location Of Accident	WESTGATE BASEMENT CARPARK FROM B2 TO B3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB3816R
Insured/Policyholder	
Name Of Registered Owner	WONG LING PAU
NRIC No	S7170995G
Email Address	GEORGEWLP8771@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94505948
Alternative Phone No	OTHERS-94505948

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5078807730-02
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	WONG LING PAU
NRIC No	S7170995G
Date Of Birth	08/07/1971
Occupation	INDOOR
Date Of Driving Pass	21/09/1990
Driving Experience	28 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94505948
Fax Number	
Contact Number	OTHERS-94505948
Email Address	GEORGEWLP8771@GMAIL.COM

Address	BLK 665 JALAN DAMAI #04-107
Postcode	410665
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	SHELTERED
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHEN SIEW YING GENDER: : FEMALE
Passenger 2	NAME: : RACHEL WONG REE EN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDM7827U
Vehicle Make/Model/Colour	VW SHARAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HENG BOON PING MICAH
NRIC/Passport Number	S7143328E
Contact Number	98152883
Address	BLK 297 YISHUN ST 20 #10-71

Sketch Plan Pg. 1

NTUC Income Singapore Accident Report

Vehicle No. SLB3816R

Report Date: 25/03/2019 Report Time: 1:50PM

Report No. MT

Docu 24 03 2019

Make/Model Toyota Prius

Reporting Person TP

Accident No. 5098890

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies **to repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

25/3/2019 13:19

Policyholder's Signature / Date & Time

25/3/2019 13:19


Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

Thomas Chen
25/03/2019 5098890

Sketch Plan



**WESTGATE BASEMENT CARPARK
DOWNWARD RAMP FROM B2 TO B3**

Vehicle A: SLB3816R

Vehicle B: SDM7827U

Describe Circumstances of the Accident

I was driving inside Westgate Carpark and when I was proceeding from Basement 2 to Basement 3 (at the down slope ramp), the car in front of me stopped. I stopped behind the car, and shortly after, Vehicle B collided onto the rear of my car.



Declaration

I/We declare the foregoing particulars are true in every respect.



25/3/2019 13:19

Policyholder's Signature / Date &
Time

25/3/2019 13:19

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

Thomas Chen 5018820
25/03/2019

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 29 March 2019 12:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SLB 3816R (YOUR REF: 588620)

This mail is associated with :

***SLB3816R (588620)**

[SDM7827U]

TP

WONG LING PAU

Mar 24 2019 6:00PM

[WONG CHEE KIN]

Modern Automotive Pte Ltd

Dear Christina,

Please be informed that we have inspected the vehicle SLB 3816R on 27/03/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7630

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 28.03.2019

VEH NO : SLB3816R

MODEL : Toyota Harrier

D O A : 24.03.2019

YR REF : SDM7827U

254600071713

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLB3816R (TOYOTA HARRIER)

Item	Description	Qty	Am't
NO	LIST ITEMS		
1	Rear Bumper <i>behind</i>	1	1,381.10 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Retainer - LH & RH <i>new</i>	2	170.20 ✓
4	Rear Bumper Sponge <i>new</i>	1	150.60 ✓
5	Rear Bumper Lower Garnish <i>behind</i>	1	419.70 ✓
6	Rear Bumper Side Reflector - RH <i>new</i>	1	96.80 +
7	Rear End Panel <i>behind</i>	1	601.50 ✓
8	Rear End Panel Top Garnish <i>behind</i>	1	360.80 ✓
9	Tail Lamp - RH <i>new</i>	1	398.70 +
10	Tailgate <i>Distorted</i>	1	1,490.70 ✓
11	Tailgate Lock <i>Damaged</i>	1	418.60 ✓
12	Tailgate Weatherstripe <i>cut</i>	1	390.50 ✓
13	Tailgate Lamp - RH <i>new</i>	1	390.60 +
14	Tailgate Inner Trim Board	1	345.10 +
15	Tailgate Inner Trim Board Clips <i>new</i>	1 set	6094.70 30.00 +
16	Tailgate Glass Moulding <i>new</i>	1	4571.02 180.50 ✓
17	Harrier Emblem <i>new</i>	1	72.10 ✓
18	Utility Tray - RH <i>behind</i>	1	268.70 ✓
19	Rear Fender Inner Trim Board Clips - RH <i>new</i>	1 set	30.00 +
20	Floor Panel Top Cover <i>new</i>	1	561.60 +
21	Rear Exhaust Pipe <i>new</i>	1	638.80 +
22	Rear Exhaust Mounting <i>new</i>	1	32.90 +
23	Rear End Panel Lock Sensor <i>Damaged</i>	1	159.70 ✓
Less 25%			\$ 8,759.50 8919.20
			(2,189.88) (274.80)
			\$ 6,569.63 6689.40
S/NET ITEMS			
1	Reverse Sensor <i>Damaged</i>	1	\$ 280.00 200

RE: ESTIMATE FOR ACCIDENT REPAIR SLB3816R (TOYOTA HARRIER)

2	Rear End Panel Sealant	1	\$	60.00 ✓
3	Tailgate Glass Sealant	1	\$	60.00 ✓
			\$	400.00

Total parts \$ 6,969.63

LABOUR CHARGE

1	To knocking & pull out rear portion & re new above parts	\$	1,200.00 800
2	To putty and spray up paint works	\$	1,200.00 800
3	To check wiring system	\$	50.00 30
4	To underseal	\$	150.00 60
5	To remove reverse sensor	\$	100.00 50
6	To remove rear camera	\$	100.00 50
7	To remove rear upholstery	\$	150.00 60
8	To transfer tailgate fittings	\$	150.00 80
9	To remove tailgate glass	\$	180.00 120
10	To remove exhaust pipe	\$	190.00 X
		\$	<u>3,470.00</u>

GRAND TOTAL

\$ 10,439.63

10559.40

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 6941.02
A/S: 5550
06 Days.



































...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Mar 2019		28 Mar 2019 09:53 Edit Adj Rpt	S\$5,550.00 Edit Estimates	S\$5,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WONG CHEE KIN , ID: S7140109Z, Tel: +6596889619								
Main Claimant:	WONG LING PAU , ID: S7170995G								
Vehicle Reg. No.:	SLB3816R	Date of Loss:	24/03/2019 18:00 - :59 [35 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 588620	Policy/Cover Note No.:	80449118 (Comprehensive) Coverage: 08/12/2018 - 07/12/2019						
Vehicle Reg. No. (Insured):	SDM7827U	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 27/04/2019]								
Driver/Custodian (Insured):	HENG BOON PING MICAH (), NRIC: S7143328E, Tel: +6598152883 Email:								
Adj Asg. Remarks:	Liability unclear. TP want to use LKK as the SJE. Contact Person: Grace Chin / 6748 4422. On WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB3816R (588620)
[SDM7827U]
TP
WONG LING PAU
Mar 24 2019 6:00PM
[WONG CHEE KIN]
Modern Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/19 16:04	Accident Statement From:OD - Reg. No: SDM7827U, Claimant: WONG CHEE KIN	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 12:15	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/04/19 10:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/04/19 10:53	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/04/19 10:53	General View	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/04/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/03/19 16:03	Email - PRI	 Load PDF	
2	27/03/19 16:03	SLB3816R GIA Rpt	 Load PDF	
3	27/03/19 16:04	TP want to use LKK as the SJE	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail Print
4	01/04/19 12:45	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Preliminary Loss Advise From: OD - Reg. No: SDM7827U, Claimant: WONG CHEE KIN		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19005502/AGQD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80449118

Claimant Vehicle No : SLB3816R

Insured Vehicle No : SDM7827U

Date of Loss: 24/03/2019

Nature of Claim:

TP

Claim No: 588620

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3816R**

Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)

Engine No: 3ZRB724190

Reg. Date: 05/04/2016 (Man. Year: 2015)

Chassis No: ZSU600071713

Colour: Black

Odometer: 76256 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,089.40	4,891.02	2,198.38	31.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	2,050.00	1,420.00	40.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,559.40	6,941.02	3,618.38	34.27
Approved Total (Overridden) (S\$)		5,550.00		
(S\$)	10,559.40	5,550.00	5,009.40	47.44
+ GST 7.00/7.00% (S\$)	739.16	388.50	350.66	47.44
Nett Amount (S\$)	11,298.56	5,938.50	5,360.06	47.44

INSPECTION

Date of Assignment: 28/03/2019

Date Inspected: 27/03/2019 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Apr 2019)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB3816R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,381.10 FL	*1,381.10 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE RETAINER - LH & RH	Necessary	170.20 FL	*170.20 FL
4	1		*REAR BUMPER SPONGE	Cracked	150.60 FL	*150.60 FL
5	1		*REAR BUMPER LOWER GARNISH	Deformed	419.70 FL	*419.70 FL
6	1		*REAR BUMPER SIDE REFLECTOR - RH	Not Necessary	96.80 FL	*- FL
7	1		*REAR END PANEL	Dented	601.50 FL	*601.50 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	360.80 FL	*360.80 FL
9	1		*TAIL LAMP - RH	Not Necessary	398.70 FL	*- FL
10	1		*TAILGATE	Distorted	1,490.70 FL	*1,490.70 FL
11	1		*TAILGATE LOCK	Damaged	418.60 FL	*418.60 FL
12	1		*TAILGATE LAMP - RH	Not Necessary	390.60 FL	*- FL
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	645.10 FL	*- FL
14	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FL	*- FL
15	1		*TAILGATE GLASS MOULDING	Necessary	180.50 FL	*180.50 FL
16	1		*HARRIER EMBLEM	Necessary	72.10 FL	*72.10 FL
17	1		*UTILITY TRAY - RH	Deformed	268.70 FL	*268.70 FL
18	1		*SET REAR FENDER INNER TRIM BOARD CLIPS - RH	Not Necessary	30.00 FL	*- FL
19	1		*FLOOR PANEL TOP COVER	Not Necessary	561.60 FL	*- FL
20	1		*REAR EXHAUST PIPE	Not Necessary	638.80 FL	*- FL
21	1		*REAR EXHAUST MOUNTING	Not Necessary	32.90 FL	*- FL
22	1		*REAR END PANEL LOCK SENSOR	Damaged	159.70 FL	*159.70 FL
23	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
24	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
26	1		*TAILGATE WEATHERSTRIPE	Cut	390.50 FL	*390.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,319.20	6,414.70
- List Item Discount on L Items 25.00/25.00% (S\$)	2,229.80	1,523.68
Total Parts (S\$)	7,089.40	4,891.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE REAR UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	190.00	0.00
Gross Labour Cost (S\$)			3,470.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >