



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1043H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SEAL	NECESSARY	386.25	386.25
1	SEAL	NECESSARY	572.20	572.20
1	MOULDING	DEFORMED	846.35	846.35
1	RUBBER	DEFORMED	150.25	150.25
1	PANEL	TO REPAIR SEE LABOUR	1,974.83	-
	LESS 10% DISCOUNT		-	-195.50
			3,929.88	1,759.55
	<u>SPECIAL NETT ITEMS</u>			
1	STICKER SMRT (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL.		1,590.00	1,325.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	528.00
			2,206.00	1,853.00
	GRAND TOTAL		6,210.88	3,687.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC19005507/Jsd3s2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.