

ASS. REC. BY:

REF: CS/FCI 1900551/J+d3

Special Instruction:

Surveyor: Huxie Jie.

ASSIGNMENT (Office)

From (Person): CWS Marina chia San San of FCI

Date/Time: 28.3.19 1256p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SGT 1704H

Insured: SHA 9905 E

at Workshop m/s Y&W Tex Automobile

Tel: 67653373

of Blk 6 woodlands Road 399F Y&W Tex Industrial

Policy No:

Claim No: D19002003 MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

21.3.2019

21.3.19 @ 10.30a.m

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.3.19 1.59p.m

Person Contacted: Winnie

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 1704H - CFI/1607003961/gw D.O.A - 19/11/2007
	SHA 9905 E - CS/CTI 18012680/ Dsd3n2 D.O.A - 09/07/2018
1/4 @ 4:20pm	revised via predi advise

Surveyor Hwee Jie

REF: PC1

ASSIGNMENT

From Date: 29.3.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGT 1704 H

at Workshop m/s Yew Tee Automobile
of Blk 6 Woodlands Road 399F Yew Tee

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: (10.30 a.m) Owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP, / 24 HRS "wp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGT 1704 H Yr Regn: 2 Apr 2007

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer C.C. 1584

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 243480 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSTCS3A7U008422

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firestone

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/3/19 D.O.I. 29/3/19

Survey held at Yew Tee Auto

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Hwee Jie

PLS see me.

MV - \$17800
LTA - \$14855
NV - \$2945

2/5/19 Confirmed L/S \$2500t 5days with visio.
CRed: 10184-10: 8027

RECEIVED 06 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) 315 Typist

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

2x15=30

170+30
50
50
30
330



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002040MFSH

Date: 1/4/2019

Our Ref: CS/FCI19005521/Jtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGT 1704H

Please be informed that we had conducted the inspection of the abovementioned vehicle 29/3/2019 at the premises of M/s Yew Tee Automotive have the following to report: -

Workshop Estimate Amount	: S\$ 12,684.10
Revised Estimate Amount	: S\$ 3,488.20
"Check" Items Amount	: S\$ 1,896.00
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-03-2019	Our Ref No. D19002003MFSH
Accident Date	21-03-2019	Claim Type. Third Party
Insured Vehicle	SHA9905E	Third Party Vehicle. SGT1704H
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	VINNIE LIM	
Contact No.	67653373/ 0	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

T: 1.43p m
 P: Winnie
 V: out
 C: ✓
 24/3/19 @ 10:30am

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 1 April 2019 4:25 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002003MFSH/1
Attachments: PRELI ADVISED SGT 1704H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SGT 1704H**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 28 March 2019 2:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002003MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 29/3/19.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 28 March, 2019 12:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002003MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2547H

Vehicle Details

Vehicle No.: SGT1704H
Vehicle to be Exported: Yes
Intended Deregistration Date: 29 Mar 2019
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 1.6 A
Primary Colour: Red
Manufacturing Year: 2006
Engine No.: 4G18HX1059
Chassis No.: JMYSTCS3A7U008422
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$11,108.00
Original Registration Date: 02 Apr 2007
First Registration Date: 02 Apr 2007
Transfer Count: 1
Actual ARF Paid: \$8,740.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$24,715.00
COE Rebate Amount: \$14,855.00
Total Rebate Amount: \$14,855.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Mar 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1903/009
Policy No:	P 27282975 DMA	Date of Loss:	21/08/2019
Vehicle Reg. No.:	SGT1704H	Driveable?	yes
Driver Age:	25/03/2019	Third Party Vehicle No.:	SHA9905E
Any Injuries?	no	Contact No:	93852697
Insured/Claimant:	SUZANA BINTE JAFFAR	Driver:	MUHAMMAD HAZMIL BIN JAINAL

Make/Model:	Mitsubishi, Lancer	Vehicle Reg. Date:	02/04/2007
Vehicle Colour:	RED	Engine Number:	4G18HX1059
Chassis No:	JMYSTCS3A7U008422	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION-HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	8,324.10
Miscellaneous Items	1,075.00
Labour	2,080.00
Paintwork Labour	1,205.00
Towing	0.00
Gross Total(S\$):	12,684.10
GST 7.00%(S\$):	887.89
Nett Amount(S\$):	13,571.99

This claim is handled by: Sky Toh T C

65073848
First Cap

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR TAILAMP RH <i>CRA ✓</i>	0.00	374.00	-10.00	336.60
2	1	REAR TAILAMP LOWER BRACKET RH <i>? nux</i>	0.00	55.00	-10.00	49.50
3	1	REAR TAILAMP PANEL RH <i>? nux</i>	0.00	95.00	-10.00	85.50
4	1	REAR BUMPER <i>CUT ✓</i>	0.00	643.00	-10.00	578.70
5	1	REAR BUMPER RETAINER RH <i>DEF ✓</i>	0.00	38.00	-10.00	34.20
6	1	REAR BUMPER BRACKET RH <i>? nux</i>	0.00	35.00	-10.00	31.50
7	1	REAR BUMPER REINFORCEMENT <i>? nux</i>	0.00	220.00	-10.00	198.00
8	1	BOOT LID <i>Repair x</i>	0.00	690.00	-10.00	621.00
9	1	BOOT LID HINGE RH <i>nux</i>	0.00	110.00	-10.00	99.00
10	1	BOOT LID HINGE LH <i>nux</i>	0.00	110.00	-10.00	99.00
11	1	BOOT LID LOCK <i>nux</i>	0.00	105.00	-10.00	94.50
12	1	BOOT LID LOCK CATCH <i>nux</i>	0.00	28.00	-10.00	25.20
13	1	BOOT LID RUBBER <i>nux</i>	0.00	145.00	-10.00	130.50
14	1	BOOT LID LANCER EMBLEM <i>nec ✓</i>	0.00	35.00	-10.00	31.50
15	1	BOOT LID GLX EMBLEM <i>nec ✓</i>	0.00	35.00	-10.00	31.50
16	1	BOOT LID MITSUBISHI LOGO <i>nec ✓</i>	0.00	35.00	-10.00	31.50
17	1	BOOT LID CKC EMBLEM <i>nec ✓</i>	0.00	38.00	-10.00	34.20
18	1	REAR END PANEL <i>? nux</i>	0.00	490.00	-10.00	441.00
19	1	REAR END PANEL INNER GARNISH <i>? nux</i>	0.00	165.00	-10.00	148.50
20	1	REAR WINDSCREEN GLASS <i>nux</i>	0.00	600.00	-10.00	540.00
21	1	REAR WINDSCREEN GLASS MOULDING <i>nux</i>	0.00	40.00	-10.00	36.00
22	1	REAR AXLE BEAM <i>nux</i>	0.00	1,800.00	-10.00	1,620.00
23	1	REAR KNUCKLE ARM RH <i>? nux</i>	0.00	493.00	-10.00	443.70
24	1	REAR KNUCKLE ARM BEARING RH <i>? nux</i>	0.00	280.00	-10.00	252.00
25	1	REAR SHOCK ABSORBER RH <i>? nux</i>	0.00	180.00	-10.00	162.00
26	1	REAR EXHAUST PIPE <i>nux</i>	0.00	220.00	-10.00	198.00
27	1	REAR EXHAUST SILENCER <i>nux</i>	0.00	510.00	-10.00	459.00
28	1	REAR FENDER RH <i>Repair x</i>	0.00	920.00	-10.00	828.00
29	1	REAR FENDER INNER TRIM BOARD RH <i>nux</i>	0.00	240.00	-10.00	216.00
30	1	REAR FENDER INNER PANEL RH <i>? nux</i>	0.00	520.00	-10.00	468.00

Total Parts (\$\$) 8,324.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>nec ✓</i>	0.00	45.00	0.00	30 45.00
2	1	REAR TYRE RH <i>nux</i>	0.00	220.00	0.00	220.00
3	1	REAR SPORTS RIMS RH <i>nux</i>	0.00	450.00	0.00	450.00
4	1	REAR WINDSCREEN GLASS SEALANT <i>nux</i>	0.00	60.00	0.00	60.00
5	2	REAR EXHAUST MOUNTING <i>nux</i>	0.00	40.00	0.00	40.00
6	1	REAR BUMPER SENSORS <i>shorted ✓</i>	0.00	260.00	0.00	200 260.00

Sub Total (\$\$) 1,075.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 <i>X</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	30 80.00 <i>✓</i>
3	1	To Dismantle and Refit Rear Undercarriage.	180.00	180.00	0.00	100 180.00
4	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	60 80.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 X
6	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	60.00	60.00	0.00	40 60.00
7	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,400.00	1,400.00	0.00	1,400.00 900

Gross Labour Cost (\$\$) 2,080.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 X
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	100.00	100.00	0.00	50 100.00 ✓
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,000.00	1,000.00	0.00	1,000.00 700

Gross Labour Cost (\$\$) 1,205.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature] 2/5/19.
Hwee Jie - LKK
29/3/19
L/s 5days
[Signature]

Total - \$2500/-

12684-10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005521/Jtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9905E	Veh. Inspected	SGT 1704H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002003MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	28/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JMYSTCS3A7U008422	Colour	RED	
Odometer	243480	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	FIRESTONE	6 mm	
L/H Front Tyre	195/60 R15	FIRESTONE	6 mm	
R/H Rear Tyre	195/60 R15	FIRESTONE	6 mm	
L/H Rear Tyre	195/60 R15	FIRESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/03/2019	Inspection Date	29/03/2019	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 1704H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILLAMP RH	CRACKED	374.00	374.00
1	REAR TAILLAMP LOWER BRACKET RH	NOT NECESSARY	55.00	-
1	REAR TAILLAMP PANEL RH	NOT NECESSARY	95.00	-
1	REAR BUMPER	CUT	643.00	643.00
1	REAR BUMPER RETAINER RH	DEFORMED	38.00	38.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	35.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	220.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	690.00	-
1	BOOT LID HINGE RH	NOT NECESSARY	110.00	-
1	BOOT LID HINGE LH	NOT NECESSARY	110.00	-
1	BOOT LID LOCK	NOT NECESSARY	105.00	-
1	BOOT LID LOCK CATCH	NOT NECESSARY	28.00	-
1	BOOT LID RUBBER	NOT NECESSARY	145.00	-
1	BOOT LID LANCER EMBLEM	NECESSARY	35.00	35.00
1	BOOT LID GLX EMBLEM	NECESSARY	35.00	35.00
1	BOOT LID MITSUBISHI LOGO	NECESSARY	35.00	35.00
1	BOOT LID CKC EMBLEM	NECESSARY	38.00	38.00
1	REAR END PANEL	NOT NECESSARY	490.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	165.00	-
1	REAR WINDSCREEN GLASS	NOT NECESSARY	600.00	-
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	40.00	-
1	REAR AXLE BEAM	NOT NECESSARY	1,800.00	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	493.00	-
1	REAR KNUCKLE ARM BEARING RH	NOT NECESSARY	280.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	180.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	220.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	510.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	920.00	-
1	REAR FENDER INNER TRIM BOARD RH	NOT NECESSARY	240.00	-

Report Ref No. CS/FCI19005521/Jtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER PANEL RH	NOT NECESSARY	520.00	-
	LESS 10% DISCOUNT		-924.90	-119.80
			8,324.10	1,078.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
1	REAR TYRE RH (SN)	NOT NECESSARY	220.00	-
1	REAR SPORTS RIMS RH (SN)	NOT NECESSARY	450.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
2	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	40.00	-
1	REAR BUMPER SENSORS (SN)	SHORTED	260.00	200.00
			1,075.00	230.00
	<u>LABOUR</u>			
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	30.00
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE.		180.00	100.00
	TO CONDUCT COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	180.00	-
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		60.00	40.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR FENDER RH.		1,400.00	900.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	60.00	-
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	45.00	-
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		100.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,000.00	700.00
			3,285.00	1,880.00
GRAND TOTAL			12,684.10	3,188.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/FCI19005521/Jtd3n2

MARKET VALUE: \$17,800.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,855.00=NETT VALUE: \$2,945.00

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.