



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3741U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE (CONSISTENT) (WCP) (NPA)	BENT	-	-
1	L/R LAMP ASSY (CONSISTENT) (WCP)	CUT	90.00	90.00
1	RR BOX DOOR LOCK (CONSISTENT) (WCP)	TO REPAIR SEE LABOUR	1,100.00	-
	COST PLUS 15%		178.50	13.50
			1,368.50	103.50
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	180.00	180.00
1	RR NUMBER PLATE NUMBER PLATE (SN) (CONSISTENT)	BENT	35.00	35.00
1	REAR BOX 70KM STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	AUDATEX FEE (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	42.00	42.00
			277.00	277.00
	<u>LABOUR</u>			
	REDRAW COMPANY LOGO COMPANY LOGO .		400.00	200.00
	TO KNOCK ,WELD ,REMOVE & FIX ABOVE PART.INCLUSIVE OF THE REPAIR OF RR BOX DOOR LOCK.		300.00	200.00
	TO SPRAY ABOVE PARTS.		600.00	300.00
	5.0 WU X 45.00 SGD/H.		45.00	45.00
			1,345.00	745.00
GRAND TOTAL			2,990.50	1,125.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CC4/ASM19005536/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.