

ST&T AUTOMOTIVE PTE LTD

48 Toh Guan Road East Enterprise Hub
 #05-139, Singapore 608586
 Tel: (65) 98779879 Fax: (65) 63565541

Customer Vehicle detail

Car Number : SMJ8246Z Car Model : Honda Shutter 1.5A
 Chassis Number : GP72004070 Registration Year : 21-Mar-2019
 EngineNumber : LEB7105267
 Insurance Company : NTUC Income Insurance Co-Operative Ltd

Third Party Vehicle detail

Car Number : SKX8315H Car Model : Subaru
 Insurance Company :

Estimation of repair cost

Item	Part Description	Qty	Unit Price	Price	
1	Rear bumper <i>DE</i>	1	\$ 986.50	\$ 986.50	
2	Rear bumper side bracket LH <i>NE</i>	1	\$ 39.60	\$ 39.60	
4	Rear bumper side bracket RH <i>NE</i>	1	\$ 39.60	\$ 39.60	
5	Rear bumper reflector garnish LH <i>?</i>	1	\$ 35.60	\$ 35.60	
6	Rear bumper reflector garnish RH <i>?</i>	1	\$ 35.60	\$ 35.60	
7	Rear bumper towing cover <i>X</i>	1	\$ 25.10	\$ 25.10	
8	Clip, bumper <i>NE</i>	6	\$ 4.50	\$ 27.00	
9	Rear end panel <i>PA</i>	1	\$ 769.10	\$ 769.10	
10	Rear end panel top garnish <i>DE</i>	1	\$ 181.20	\$ 181.20	
11	Tailgate assy <i>PA</i>	1	\$ 1,062.80	\$ 1,062.80	
12	Tailgate weathestrip <i>NE</i>	1	\$ 189.10	\$ 189.10	
13	Tailgate lock <i>bt</i>	1	\$ 285.90	\$ 285.90	
14	Emblem "Shuttle" <i>NE</i>	1	\$ 42.70	\$ 42.70	
15	Emblem "Hybrid" <i>NE</i>	1	\$ 47.30	\$ 47.30	
16	Tailgate windscreen <i>X</i>	1	\$ 1,050.00	\$ 1,050.00	
17	Tailgate windscreen molding <i>NE</i>	1	\$ 175.60	\$ 175.60	
18	Tail lamp inner LH <i>CA</i>	1	\$ 545.10	\$ 545.10	
19	Tail lamp inner RH <i>SC</i>	1	\$ 545.10	\$ 545.10	
20	Tail lamp outer LH <i>SC</i>	1	\$ 586.00	\$ 586.00	
21	Tail lamp outer RH <i>CA</i>	1	\$ 586.00	\$ 586.00	
				Sub Total	\$ 7,254.90
				Less 20%	\$ 1,450.98
				Total	\$ 5,803.92

Special Nett

1	Supply 1 set of reverse sensor <i>NE</i>	1	\$ 250.00	\$ 250.00 ²²⁰	
2	Supply windscreen sealant kit <i>NE</i>	1	\$ 45.00	\$ 45.00	
3	Supply joint/seam rubberised seal <i>NE</i>	1	\$ 60.00	\$ 60.00 ⁴⁰	
				Total	\$ 355.00

Labour

1	Remove, dismantling and replace damage parts. Pull, cut and weld on rear end panel. Repair and strenghten rear floor panel and towing hook panel, strenghten and repair side extension member, LH & RH rear fender, align body panel gap & fittings.			\$ 1,500.00
				1000 700

2	Supply paint and consumable material, carry out sanding, masking and cleaning on affected area.	\$ 1,500.00
	Conduct spray painting on tailgate (inner & outer), rear bumper, rear end panel, floor panel LH and RH rear fender. (2K metallic silver)	1250 800
3	Set up and tightening vehicle on pulling work bench.	(photo) 100 \$ - 150.00
4	Remove & reinstall rear upholstery to facilitate repair.	\$60 120.00
5	Remove and replace rear windscreen and conduct water leaking test.	\$ 180.00 120
6	Remove & transfer tailgate attachment parts and wiring onto new tailgate panel.	\$60 100.00
7	Remove and replace reverse sensor	\$ 50.00
8	Apply rust coating on underside accident affected area	\$ 60.00
9	Check lightings, wiring and light socket connection	\$ 40.00
	Total	\$ 3,700.00

Grand Total \$ 10,954.90

Spare tyre bond cover ✓
 Quarter panel garnish LH/RH - DE ✓ x2
 Tailgate handle - DE ✓

Resur
 Hp 90010068
 7 days
 P/P
 29/03/19 @ 1200hrs
 Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: