

22/03/2002

REF: CS/CT1 19005590 / Attd 38

Special Instruction:

ASS. REC. BY:

Supervisor: Adrian
From (Person): Ong chin Kiat

ASSIGNMENT (Office)

of CT1

Date/Time: 28.03.19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SLK 6593R

To Inspect Vehicle No: SLR 53702

Tel: 63416789

at Workshop m/s Dynamic Autowork

of 8 Kaki Bukit Ave 4, #08-09

Policy No: DMPCSN-300 56719000

Claim No: SNM190201375(02)

Sum Insured:

Excess:

D.O.A. 28.3.2019

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 29.3.19 9.00am

Person Contacted: Michelle

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLR53702 - MA/CT1 19005544/K4	D.O.A. - 28/03/2019
	SLK 6593R - MA/CT1	
	lump sum \$8000 (red. 9786.80, 55%)	

Surveyor

REF: CTZ

ASSIGNMENT

From: _____ Date: 29.3.2019
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLR 5370L
 at Workshop m/s Dynamic Autowork
 of 8 kaki Bukit Mre 4, # 08-09
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLR5370L Yr Regn: 2017, August
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Subaru XV c.c 1600
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 27168 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JFIGP3KCSH6204556
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/55R17
 R: 225/55R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

	
N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**
 GIA / PR Seen: _____ Consistent? : **Yes** or **No**
 Est. Repairs: _____ days Res.: **Yes** or **No**
 Lum Sum: _____ % 3 Val.: **Yes** or **No**
 CA / REV / REP. / 24 HRS (rwp)
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Front 06 mm R/Bal. 06 mm
 L/Bal. 06 mm Rear 06 mm
 D.O.A. _____ D.O.I. 29/03/19
 Survey held at Dynamic
 Des. of Damages : **Fr** / **Rear** / O/S / N/S / U/C / Rooftop or _____
 The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>TP Clinic</u>
RECEIVED 1 8 APR 2019	

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 1014 Tyms
 Date/Time, File Return to? _____
 2) _____
 Report Format : TP
 Lump Sum / I.B.I: (\$) 8000 / -

Days Of Repair: 8
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Survey Fee: 210
 Transportation: _____ \$ + RS, \$
 Photos _____
 Others _____
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2019		28 Mar 2019 17:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	EC WORLD ASSET MANAGEMENT PTE LTD , Co. Reg. No.: 201523015N								
Main Claimant:	MR LI WAN , ID: S8877720D								
Vehicle Reg. No.:	SLR5370L	Date of Loss:	28/03/2019 07:00 - :59 [19 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201375C02	Policy/Cover Note No.:	DMPCSN30056719000 (Comprehensive) Coverage: 23/01/2019 - 22/01/2020						
Vehicle Reg. No. (Insured):	SLK6593R	Policy No. (Claimant):	DMPCSN1754371801						
		Excess:	S\$0.00						
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/04/2019]								
Driver/Custodian (Insured):	LEE BOON HWEE BERNARD (LI WENHUI) (40 / Male), NRIC: S7808770F Email:								
Adj Asg. Remarks:	please assign Mr Adrian Ling for SJE. thank you.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/03/2019 15:21
Date Of Accident	28/03/2019 07:30
Exact Location Of Accident	PIE TWDS TUAS (B4 JALAN EUNOS EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLR5370L
Insured/Policyholder	
Name Of Registered Owner	MR LI WAN
NRIC No	S8877720D
Email Address	CAPTAINLIWAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81386456
Alternative Phone No	OTHERS-81386456
Vehicle Particulars	
Manufacturer	SUBARU
Model	SUBARU XV 1.6I-S AWD CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1754371801
Cover Note Number	
Driver	
Name of Driver	MR LI WAN
NRIC No	S8877720D
Date Of Birth	16/12/1988
Occupation	INDOOR
Date Of Driving Pass	04/08/2017
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81386456
Fax Number	
Contact Number	OTHERS-81386456
E-Mail Address	CAPTAINLIWAN@GMAIL.COM

Address	BLK 774 BEDOK RESERVOIR VIEW #15-117
Postcode	470774
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK6593R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MR LI WAN
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	SLR5370L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

28/3/2019

Sketch Plan #2

SKETCH PLAN



A = SLR5370L

B = SLK6593R

PIE towards Teras

(Before Jalan Eunos Exit)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 - 28/3/2019
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #3

On 28.03.19 at about 07:30 hours along PIE towards Tuas (Before Jalan Eunus Exit). I was travelling straight on the lane 2, suddenly I heard a loud bang from behind and felt an impact, subsequently follow by a second bang and impact. When I alighted I realised it was vehicle (B) collided onto rear portion of my vehicle (A). After that I went to see doctor and was given two days MC.

Vehicle (A): SLR 5370L

Vehicle (B): SLK 6593R

A handwritten signature in black ink, appearing to be 'V. S.', located below the vehicle information.

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLR5370L
 MODEL : SUBARU XV
 DATE OF ACCIDENT : 28.03.19
 TIME OF ACCIDENT : 07:40HRS

31	REAR FLOOR PANEL TOP TRAY (SPONGE) <i>cont</i>	1	\$ 294.10	\$ 294.10	✓
32	REAR FLOOR PANEL SIDE COVER GARNISH <i>new</i>	2	\$ 110.60	\$ 221.20	+
33	REAR FLOOR PANEL TOP BOARD <i>Rehnd</i>	1	\$ 399.40	\$ 399.40	277.20
34	CENTRE EXHAUST <i>Best</i>	1	\$ 1,269.30	\$ 1,269.30	844.
35	CENTRE EXHAUST GASKET (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
36	CENTRE EXHAUST INSULATOR <i>new</i>	1	\$ 238.60	\$ 238.60	+
37	REAR EXHAUST MUFFLER <i>Best Dented</i>	1	\$ 946.60	\$ 946.60	676.
38	REAR EXHAUST PIPE MOUNTING <i>new</i>	2	\$ 32.30	\$ 64.60	+
39	REAR EXHAUST INSULATOR <i>coupled</i>	1	\$ 182.40	\$ 182.40	✓
40	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	✓

8170.50 TOTAL PRICE \$ 12,108.50
 653640 LESS 20% \$ 2,421.70
 SUB TOTAL PRICE \$ 9,686.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
3	REAR BUMPER INNER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
5	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
6	TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
7	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
8	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
9	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	40
10	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
11	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	80
13	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10
14	REAR FLOOR PANEL SIDE COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
15	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00	+
16	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200
17	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	480

TOTAL \$ 1,950.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1800

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLR5370L
 MODEL : SUBARU XV
 DATE OF ACCIDENT : 28.03.19
 TIME OF ACCIDENT : 07:40HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	900
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50
8	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
9	REAR CHASSIS ALIGNMENT	\$ 250.00	x
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
13	REMOVE AND REFIX FUEL TANK TO FACILITATE REPAIR FLOOR PANEL	\$ 120.00	x
14	REMOVE AND REFIX EXHAUST PIPE	\$ 180.00	160
15	SPECIAL COATING	\$ 680.00	500 300
16	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2980.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after repairs commencing
- To display an **ESTIMATE REPORT**
- Parts prices on a no profit or loss basis
- Third party liability on a no profit or loss basis
- No illegal modifications
- Supplemental repairs are subject to final approval from Insurance Company

Acknowledged by: _____
 Signature: _____
 Date: _____

TOTAL 6150

ESTIMATE REPORT
 TOTAL PARTS COST : \$11,636.80
 TOTAL LABOUR COST : \$6,150.00
 TOTAL REPAIR COST : \$17,786.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian King
 L/S 29/03/19
 08 Days. total 9586.40
 h/s: 8k.
 (8k)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2019		28 Mar 2019 17:35 Edit Adj Rpt	S\$8,000.00 Edit Estimates	S\$8,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EC WORLD ASSET MANAGEMENT PTE LTD , Co. Reg. No.: 201523015N		
Main Claimant:	MR LI WAN , ID: S8877720D		
Vehicle Reg. No.:	SLR5370L	Date of Loss:	28/03/2019 07:00 - :59 [19 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201375C02	Policy/Cover Note No.:	DMPCSN30056719000 (Comprehensive) Coverage: 23/01/2019 - 22/01/2020
Vehicle Reg. No. (Insured):	SLK6593R	Policy No. (Claimant):	DMPCSN1754371801
		Excess:	S\$0.00
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/04/2019]		
Driver/Custodian (Insured):	LEE BOON HWEE BERNARD (LI WENHUI) (40 / Male) , NRIC: S7808770F Email:		
Adj Asg. Remarks:	please assign Mr Adrian Ling for SJE. thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR5370L (SNM19D201375C02)
[SLK6593R]
TP
MR LI WAN
Mar 28 2019 7:00AM
[EC WORLD ASSET MANAGEMENT PTE LTD]
Dynamic Autowork Pte. Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page

No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/03/19 15:39	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/04/19 15:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/04/19 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	09/04/19 15:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail Print
33	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
77	09/04/19 15:20	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	28/03/19 17:30	PRI notification		Load PDF <input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
2	28/03/19 17:30	INSD SLK6593R GIA Report		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/03/19 15:39	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	28/03/19 15:34	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
14	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
15	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
16	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
17	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
18	28/03/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	28/03/19 15:33	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	28/03/19 15:33	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>
3	28/03/19 15:33	Sketch Plan #3		Load JPG <input checked="" type="checkbox"/>
4	28/03/19 15:33	Sketch Plan #4		Load JPG <input checked="" type="checkbox"/>
5	28/03/19 15:37	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005590/ATD3S2
Date: 06/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30056719000
Claimant Vehicle No :	SLR5370L	Insured Vehicle No :	SLK6593R
Date of Loss:	28/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201375C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR5370L	Engine No:	FB16Y570039
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GP3KC5HG204596
Reg. Date:	18/08/2017 (Man. Year: 2016)	Odometer:	27168 km
Colour:	Black		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,636.80	7,016.40	4,620.40	39.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	2,980.00	3,170.00	51.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,786.80	9,996.40	7,790.40	43.80
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	17,786.80	8,000.00	9,786.80	55.02
+ GST 7.00/7.00% (S\$)	1,245.08	560.00	685.08	55.02
Nett Amount (S\$)	19,031.88	8,560.00	10,471.88	55.02

INSPECTION

Date of Assignment:	28/03/2019		
Date Inspected:	29/03/2019	Inspected At:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5370L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	682.00 FL	*682.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Cracked	49.80 FL	*49.80 FL
3	1		*REAR BUMPER THIRD BRAKE LAMP	Cracked	196.40 FL	*196.40 FL
4	1		*REAR BUMPER REINFORCEMENT	Distorted	486.20 FL	*247.20 FL
5	1		*REAR BUMPER INNER SIDE GARNISH RH	Cracked	96.30 FL	*96.30 FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	75.20 FL	*75.20 FL
7	1		*REAR BUMPER LOWER BRACKET RH	Not Necessary	39.50 FL	*- FL
8	1		*TAILLAMP RH	Cut	437.40 FL	*437.40 FL
9	1		*TAIL LAMP LOWER BRACKET RH	Cracked	37.90 FL	*37.90 FL
10	1		*REAR FENDER INNER COWLING RH	Torn	121.80 FL	*121.80 FL
11	1		*REAR FENDER INNER TRIM	O/s Cracked	795.20 FL	*397.60 FL
12	1		*TAILGATE	Dented	1,210.80 FL	*1,210.80 FL
13	1		*TAILGATE DETECTOR	Cracked	295.60 FL	*295.60 FL
14	1		*TAILGATE OUTER MOULDING	Cracked	358.20 FL	*192.10 FL
15	1		*TAILGATE LOGO	Necessary	103.30 FL	*80.00 FL
16	1		*TAILGATE EMBLEM SUBARU	Necessary	79.20 FL	*79.20 FL
17	1		*TAILGATE EMBLEM XV	Necessary	57.80 FL	*57.80 FL
18	1		*TAILGATE EMBLEM AWD	Necessary	69.40 FL	*69.40 FL
19	1		*TAILGATE INNER LOCK	Damaged	220.10 FL	*220.10 FL
20	1		*TAILGATE LOWER LOCK	Not Necessary	24.00 FL	*- FL
21	2		*TAIL GATE HINGE	Not Necessary	192.60 FL	*- FL
22	1		*TAILGATE INNER HOLDER	Not Necessary	75.10 FL	*- FL
23	2		*TAILGATE STOPPER	Not Necessary	38.40 FL	*- FL
24	1		*TAILGATE WEATHER STRIP	Cut	168.90 FL	*168.90 FL
25	1		*TAILGATE INNER TRIM (LOWER)	Cracked	297.40 FL	*297.40 FL
26	2		*TAIL GATE DAMPER	Not Necessary	353.60 FL	*- FL
27	1		*TAILGATE WINDSCREEN MOULDING	Necessary	169.50 FL	*169.50 FL
28	1		*REAR END PANEL	Distorted	478.10 FL	*478.10 FL
29	1		*REAR FLOOR PANEL	Repair	986.30 FL	*- FL
30	1		*REAR END PANEL TOP GARNISH	Deformed	176.30 FL	*176.30 FL
31	1		*REAR FLOOR PANEL TOP TRAY (SPONGE)	Cracked	294.10 FL	*294.10 FL
32	2		*REAR FLOOR PANEL SIDE COVER GARNISH	Not Necessary	221.20 FL	*- FL
33	1		*REAR FLOOR PANEL TOP BOARD	Deformed	399.40 FL	*277.20 FL
34	1		*CENTRE EXHAUST	Bent	1,269.30 FL	*844.00 FL
35	1		*SET CENTRE EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
36	1		*CENTRE EXHAUST INSULATOR	Not Necessary	238.60 FL	*- FL
37	1		*REAR EXHAUST MUFFLER	Dented	946.60 FL	*676.00 FL
38	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	64.60 FL	*- FL
39	1		*REAR EXHAUST INSULATOR	Crumpled	182.40 FL	*182.40 FL
40	1		*SET REAR EXHAUST GASKET	Necessary	60.00 FL	*60.00 FL
41	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
42	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET REAR BUMPER INNER SIDE GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
44	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*10.00 FS
45	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
46	1		*SET TAILGATE OUTER MOULDING CLIP	Necessary	30.00 FS	*10.00 FS
47	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	60.00 FS	*30.00 FS
48	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
49	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
50	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
51	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
52	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
54	1		*SET REAR FLOOR PANEL SIDE COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
55	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
56	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
57	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,058.50	8,650.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,421.70	1,634.10
Total Parts (\$\$)	11,636.80	7,016.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS.	New	1,800.00	1,100.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,600.00	900.00
3	TUFF COAT.	New	250.00	60.00
4	WIRING AND BULB CHECK.	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.	New	350.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA.	New	80.00	50.00
8	REMOVE AND REFIX VIDEO RECORDER.	New	80.00	50.00
9	REAR CHASSIS ALIGNMENT.	New	250.00	0.00
10	TRANSFER TAILGATE MECHANISM.	New	80.00	80.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN.	New	120.00	120.00
12	CONDUCT WATER LEAKAGE TEST.	New	120.00	0.00
13	REMOVE AND REFIX FUEL TANK TO FACILITATE REPAIR FLOOR PANEL.	New	120.00	0.00
14	REMOVE AND REFIX EXHAUST PIPE.	New	180.00	160.00
15	SPACIAL COATING.	New	680.00	300.00
16	MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (\$\$)			6,150.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >