



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 559U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH BI XENON HEADLIGHT (CONSISTENT)	* CHECK	2,119.70	-
1	RH BI XENON HEADLIGHT (CONSISTENT)	NOT NECESSARY	2,119.70	-
1	FRT BUMPER PANEL PRIMED (CONSISTENT)	* CHECK	1,047.80	-
1	FLAP TOWING EYE PRIMED (CONSISTENT)	NOT NECESSARY	43.25	-
1	LH COVER SPRAY NOZZLE PRIMED (CONSISTENT)	NOT NECESSARY	43.25	-
1	RH COVER SPRAY NOZZLE PRIMED (CONSISTENT)	NOT NECESSARY	43.25	-
1	INSERT AIR INLET MIDDLE (CONSISTENT)	NOT NECESSARY	119.65	-
1	MOUNTING SIDE PANEL FRT TOP LH (CONSISTENT)	* CHECK	19.20	-
1	MOUNTING SIDE PANEL FRT TOP RH (CONSISTENT)	* CHECK	19.20	-
1	MOUNTING SIDE PANEL FRT BOTTOM LH (CONSISTENT)	* CHECK	19.20	-
1	MOUNTING SIDE PANEL FRT BOTTOM RH (CONSISTENT)	* CHECK	19.20	-
1	MOUTING SUPPORT (CONSISTENT)	* CHECK	14.05	-
1	SUPPORT CENTER (CONSISTENT)	* CHECK	11.35	-
20	RIVET (CONSISTENT)	NECESSARY	10.00	10.00
1	SUPPORT FOG LAMP LH (CONSISTENT)	NOT NECESSARY	41.85	-
1	REPAIR KIT HOLDER BUMPER FRT (CONSISTENT)	* CHECK	86.55	-
1	LH FINISHER ROD (CONSISTENT)	* CHECK	99.45	-
1	RH FINISHER ROD (CONSISTENT)	NOT NECESSARY	99.45	-
1	PARTIALLY OPEN GRID LH (CONSISTENT)	* CHECK	77.10	-
1	PARTIALLY OPEN GRID RH (CONSISTENT)	NOT NECESSARY	77.10	-
1	GRILLE FRT LH (CONSISTENT)	* CHECK	128.00	-
1	GRILLE FRT RH (CONSISTENT)	* CHECK	128.00	-
1	LICENCE PLATE BASE (CONSISTENT)	NOT NECESSARY	69.25	-
1	FRT BUMPER TOP CARRIER (CONSISTENT)	* CHECK	415.50	-
1	SHOCK ABSORBER FRT (CONSISTENT)	* CHECK	45.00	-
1	FRT LH DEFORMATION ELEMENT (CONSISTENT)	* CHECK	111.90	-
1	FRT RH DEFORMATION ELEMENT (CONSISTENT)	NOT NECESSARY	111.90	-
1	FRT BUMPER BOTTOM CARRIER (CONSISTENT)	* CHECK	147.50	-
1	DEFORMATION ELEMENT FRT LH (CONSISTENT)	* CHECK	94.95	-
1	DEFORMATION ELEMENT FRT RH (CONSISTENT)	NOT NECESSARY	94.95	-
1	DAMPER FOR CURB DESCENT (CONSISTENT)	* CHECK	5.00	-

Report Ref No. CC4/ASM19005600/Epa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT LH AXLE SUPPORT (CONSISTENT)	* CHECK	32.20	-
1	FRT RH AXLE SUPPORT (CONSISTENT)	NOT NECESSARY	32.20	-
1	SUPPORT (CONSISTENT)	NOT NECESSARY	9.75	-
1	SUPPORT FOG LAMP RH (CONSISTENT)	NOT NECESSARY	41.85	-
			7,598.25	10.00
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	30.00
			150.00	30.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE, REALIGN, REPLACE AND REPAIR FRONT BUMPER LH FRONT FENDER, LH HEADLAMP ASSY AND ALL AFFECTED AREAS.		2,400.00	340.00
	LABOUR TO PUTTY AND RESPRAY FRONT BUMPER AND LH FRONT FENDER AND ALL AFFECTED AREAS.		1,800.00	440.00
	TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS.		120.00	60.00
	TO CONDUCT ECU PROGRAMMING CHECK & CLEAN FAULT CODES, RESTORE ALL PROGRAMME MODULE.		600.00	600.00
	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.		200.00	200.00
			5,120.00	1,640.00
GRAND TOTAL			12,868.25	1,680.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$4,682.70 NETT)				1,680.00

Report Ref No. CC4/ASM19005600/Epa3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.