



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS3/SPF18019896/Gsd3s2-1		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 02-07-2019		
ATTN: HAFIZUL FARHAN		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 3230M	Veh. Inspected	SKP 3737Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/153	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	27/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZ16ZEM035344	Colour	WHITE	
Odometer	115204	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40R19	MICHELIN	6 mm	
L/H Front Tyre	235/40R19	MICHELIN	6 mm	
R/H Rear Tyre	235/40R19	MICHELIN	6 mm	
L/H Rear Tyre	235/40R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2018	Inspection Date	01/11/2018	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		