

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.26197 Date: 08th April 2019

Our Ref: CS3/AXA18003956/Esd3s2-1

## M/s AXA Insurance Pte Ltd

C/o: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJM 1845K INSURED VEHICLE: SHD 9538R ACCIDENT DATE: 27/02/2018

We thank you for your instruction on 28/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJM 1845K from M/s Constant Appraiser Services.
- b) Final Repair Bill of SJM 1845K from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJM 1845K and SHD 9538R.
- d) Damaged vehicle photographs of SJM 1845K.

Pre-Repair Inspection Date: 01/03/2018 at M/s TwinCar Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number Make & Model

: SJM 1845K : Toyota Allion

Year of Registration

: 2008

Chassis Number

: NZT26003032976

Engine Capacity

: 1496 cc

- We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.