

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

Claimant Insurer: FWD Singapore Pte. Ltd.

LPK
11:30

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/03/2019
Vehicle Reg. No.:	SKZ1456U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	HOW TEOH TONG		
Make/Model:	MAZDA BIANTE, 2.0 BIANTE 5-DOOR WAGON SP.6E (A)	Vehicle Reg. Date:	11/01/2016
Vehicle Colour:	BLACK	Chassis No:	JM6CC1071G0109116
Engine No:	PE30848645		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2 days		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Not Not hail
Presony B4 print

COST OF CLAIMS	Amount
Parts	6,082.80
Miscellaneous Items	10.00
Labour	2,670.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	8,762.80
+ GST 7.00% (\$)	613.40
Nett Amount (\$)	9,376.20

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2019)

Parts: M1-MPV MAZDA BIANTE 2.0 BIANTE 5-DOOR WAGON SP.6E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*TAILGATE	20.00	0.00	*1,618.70 FL	X
2	2		*TAILGATE HINGE LH & RH	20.00	0.00	*68.20 FL	X
3	1		*TAILGATE CTR REFLECTOR	20.00	0.00	*1,922.40 FL	X
4	1		*TAILGATE NO PLATE GARNISH (CHROME)	20.00	0.00	*528.80 FL	X
5	1		*TAILGATE SKYACTIVE TECHNOLOGU LOGO	20.00	0.00	*111.50 FL	X
6	1		*TAILGATE INNER LOCK	20.00	0.00	*252.00 FL	X
7	1		*TAILGATE INNER TRIMBOARD	20.00	0.00	*406.00 FL	X
8	1		*TAILGATE RUBBER	20.00	0.00	*207.90 FL	X
9	1		*TAILAMP RH	20.00	0.00	*1,064.00 FL	X
10	1		*REAR BUMPER	20.00	0.00	*540.00 FL	X
11	2		*REAR BUMPER SIDE RETAINERS LH & RH	20.00	0.00	*92.80 FL	X
12	15		*REAR BUMPER CLIPS	20.00	0.00	*60.00 FL	X
13	1		*REAR BUMPER CHROME MOULDING CTR	20.00	0.00	*123.90 FL	X
14	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH	20.00	0.00	*163.80 FL	X
15	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	*118.50 FL	X
16	1		*INNER SEAL	0	0.00	*20.00 FS	X
17	1		*WINDSCREEN SEALANT	0	0.00	*40.00 FS	X
18	1		*REVERSE SENSOR	0	0.00	*200.00 FS	X

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 7,538.50
 - List Item Discount on L Items (\$\$) 1,455.70

Total Parts (\$\$) 6,082.80

Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			10.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			151
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	New	150.00 X
3	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	120.00 X
4	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	80.00 X
5	TO REMOVE & REINSTALL REVERSE CAMERA	New	80.00 X
6	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	80.00 501
7	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	120.00 X
8	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR END PANEL;REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2001 1,000.00
9	TO SPRAY TAILGATE;REAR BUMPER;END PANEL;REAR FENDER RH.	New	2201 1,000.00
Gross Labour Cost (S\$)			2,670.00

Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >