

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III19005682/KGA3Q2
Date: 28/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHD931Y	Insured Vehicle No :	SHC8865H
Date of Loss:	27/03/2019	Nature of Claim:	TP
		Claim No:	MCT19030714

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD931Y		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C003362
Reg. Date:	08/12/2017 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283294
Colour:	Metallic White/Red	Odometer:	217218 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,867.35	11,782.92	27,084.43	69.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,000.00	1,470.00	11,530.00	88.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	51,867.35	13,252.92	38,614.43	74.45
+ GST 7.00/7.00% (S\$)	3,630.71	927.70	2,703.01	74.45

Nett Amount (\$\$)	55,498.06	14,180.62	41,317.44	74.45
+ Loss of Use (6.0 x S\$40.00/day) (\$\$)		240.00		
+ Car Rental (6.0 x S\$103.60/day) (\$\$)		621.60		
Nett Liability (\$\$)		15,042.22		

INSPECTION

Date of Assignment: 29/03/2019

Date Inspected: 29/03/2019

Estimated Period of Repair: 4.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD931Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Cracked	266.80 FL	*266.80 FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
17	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1		*FRAME FULL SUPPORT BRACKET	Bent	89.79 FL	*89.79 FL
19	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
20	1		*HORN	Serviceable	314.17 FL	*- FL
21	1		*HORN BRACKET	Repair	40.45 FL	*- FL
22	1		*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP HARNESS	Serviceable	928.29 FL	*- FL
24	1		*HEADLAMP PANEL FRT RH	Bent	152.15 FL	*152.15 FL
25	1		*BONNET	Bent	1,941.63 FL	*1,941.63 FL
26	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
27	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
29	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
30	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
31	1		*BONNET LOCK	Distorted	305.48 FL	*305.48 FL
32	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
33	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
34	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
35	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
36	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
37	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
38	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
39	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
40	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
41	1		*FENDER PANEL INNER FRT LH	Repair	1,693.77 FL	*- FL
42	1		*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
43	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
44	1		*FENDER PANEL INNER FRT RH	Repair	1,693.77 FL	*- FL
45	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
46	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
47	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
48	1		*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*- FL
49	1		*SUBFRAME BRACKET OUTER RH	Serviceable	92.36 FL	*- FL
50	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
51	1		*A/C CONDENSER	Bent	2,020.37 FL	*2,020.37 FL
52	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
53	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
54	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
55	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
56	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
57	1		*A/C PIPE CONDENSER TO EXPANSION VALVE	Serviceable	658.72 FL	*- FL
58	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
59	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
60	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
61	1		*AIR COOLER	Serviceable	792.60 FL	*- FL
62	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
63	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
64	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
65	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
66	1		*RADIATOR	Serviceable	1,202.20 FL	*- FL
67	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
69	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
70	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
71	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
72	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
73	1		*RADIATOR TANK	Serviceable	324.62 FL	*- FL
74	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
75	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
76	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
77	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
78	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
79	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
80	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
81	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
82	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
83	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
84	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
85	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
86	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
87	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
88	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
89	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
90	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	200.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	43,110.11	13,074.02
- List Item Discount on L Items 10.00/10.00% (\$)	4,242.76	1,291.10
Total Parts (\$)	38,867.35	11,782.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,000.00	500.00
2	TOWING FEES.	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,000.00	660.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
8	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC.	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
10	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	0.00
11	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	0.00
12	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	New	480.00	0.00
13	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
14	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	100.00
15	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
16	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
17	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
18	TO TRANSFER OF BONNET FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
19	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (\$\$)			13,000.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >