



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFH 8333Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,040.90	1,040.90
1	FRONT BUMPER SIDE BRACKET RH (CONSISTENT)	NECESSARY	123.50	123.50
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	NOT NECESSARY	377.80	-
1	FRONT BUMPER FOG LAMP COVER RH (CONSISTENT)	NOT NECESSARY	149.55	-
2	FRONT BUMPER PARKING SENSOR RH (CONSISTENT)	NOT NECESSARY	728.30	-
1	FRONT BUMPER NOZZLE RH (CONSISTENT)	NOT NECESSARY	234.90	-
1	FRONT BUMPER NOZZLE COVER RH (CONSISTENT)	NOT NECESSARY	71.55	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	62.40	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	494.80	-
1	FRONT BUMPER FOG LAMP GRILLE RH (CONSISTENT)	NOT NECESSARY	162.55	-
1	FRONT BUMPER LOWER (CONSISTENT)	NOT NECESSARY	390.00	-
1	FRONT HEADLAMP RH (CONSISTENT)	SCRATCHED	3,900.00	3,900.00
1	FRONT HEADLAMP LOWER BRACKET RH (CONSISTENT)	NOT NECESSARY	179.45	-
1	FRONT HEADLAMP PANEL RH (CONSISTENT)	NOT NECESSARY	185.90	-
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	390.00	-
1	FRONT FENDER RH (CONSISTENT)	NOT NECESSARY	910.10	-
1	FRONT FENDER SHIELD RH (CONSISTENT)	NOT NECESSARY	205.45	-
1	FRONT FENDER ARCH GARNISH (CONSISTENT)	SCRATCHED	208.80	208.80
	LESS 10% DISCOUNT		-981.60	-527.32
			8,834.35	4,745.88
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
10	FRONT FENDER SPLASH SHIELD CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
			90.00	30.00
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS ,REPLACED AND REALIGNED HYDRAULIC ,ALIGNED ALL PARTS.		600.00	250.00
	TO RESPRAY AFFECTED AREAS.		800.00	250.00
	TO TUFFCOAT AFFECTED AREA.		150.00	20.00
	TO REMOVE/REFIT WIRING CHECKS.		60.00	30.00

Report Ref No. CC4/ASM19005691/Jgs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REPLACE PARKING SENSORS .		100.00	30.00
			1,710.00	580.00
GRAND TOTAL			10,634.35	5,355.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC4/ASM19005691/Jgs3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.