

ASS. REC. ETC

REF: CS/FCI/9005698/K903n2

Special Instruction:

SA/VS/IV

Kenneth

ASSIGNMENT (Office)

WS

From (Person):

May chuan

of

FCI

Date/Time:

1/4/16 @ 10:06am

Estimated Cost:

Bill to:

OD (TP) WS/TT RES/OD RES/EYA/INV/MTCS

To Inspect Vehicle No:

SHC5292E

Insured:

SH7100G

at Workshop m/s

Transcib

Tel:

02876666

of

No. 2 Amk St. 63

Policy No:

Claim No:

D1900271MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/3/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:54am @ 1/4/2019

Person Contacted:

Candy

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC5292E - CC4/ASM/9005581/Fn3

DOA: 27/3/2019

SH7100G - CC4/ASM/9005581/Fn3

DOA: 27/3/2019

2/4/19 @ 3:21pm - revised via email profi advice.

8/6 C/L Ry @ 950d summt (Red to 37097.97, 80%)

ASS. REC. BY:

REF:

F621

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

06 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHC 5292 E

Yr Regn: _____

03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Renault Latitude

c.c

1895

Colour: _____

White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

711926

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VF1ABL15AUC 276802

Gen. Cond: _____

Good / Fair / Poor / Burnt

Steering: _____

In order / Jammed / Leaked / Burnt or

Brake: _____

In order / Jammed / Leaked / Burnt or

Mod: _____

NII / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

8

mm

L/Bal. _____

9

mm

L/Bal. _____

8

mm

D.O.A. _____

27/3/19

D.O.I. _____

1/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear & side

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 10 JUN 2019

Date/Time, File Pass to?



: Prell. Report



: Final Report

10/6/19

Date/Time, File Return to?

Days Of Repair: _____

6

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

S + RS. SI

Fictos

Others

350

TOTAL

Report Format: _____

TP

Lump Sum / I.B.I. (\$) _____

950

Add Fee: _____



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002171MFSH

Date: 2/4/2019

Our Ref: CS/FCI19005698/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5292E

Please be informed that we had conducted the inspection of the abovementioned vehicle
1/4/2019 at the premises of M/s Chun Ni Motor have the following to report: -

Workshop Estimate Amount	: S\$ 46,597.97
Revised Estimate Amount	: S\$ 9,337.75
"Check" Items Amount	: S\$ 9,527.50
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the
N/S portion and undercarriage.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-03-2019	Our Ref No.	D19002171MFSH
Accident Date	27-03-2019	Claim Type.	Third Party
Insured Vehicle	SH7100G	Third Party Vehicle.	SHC5292E
Survey Location	NO. 2 ANG MO KIO STREET 63		
Contact Person.	CANDY KONG		
Contact No.	62876666/ 0	Fax No.	62571330
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	MAY CHUA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 7 June 2019 10:25 AM
To: Shiau Chan (LKKAUTO)
Subject: FW: TP VEHICLE SHC 5292E (DOA: 27/03/2019) -- AAD1903-215
Attachments: image004.wmz; image001.wmz; image003.wmz; SHC5292 EST.pdf; DSCN3343.JPG; DSCN3341.JPG; DSCN3338.JPG

Hi Shiau Chan

We confirmed COR amount \$ 9,500.00 (b4 GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 6 June, 2019 3:18 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: TP VEHICLE SHC 5292E (DOA: 27/03/2019) -- AAD1903-215

Dear Wai Yin,

As per your requested.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 6 June 2019 2:55 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SHC 5292E (DOA: 27/03/2019) -- AAD1903-215

Hi Shiau Chan

Can send me a copy of the estimate marking?

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 2 April 2019 3:21 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002171MFSH/1
Attachments: PRELI ADVISED SHC 5292E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 5292E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 1 April 2019 11:54 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002171MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 1 April 2019 10:06 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002171MFSH/1

Dear Sir/Mdm,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5292E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000969
Chassis No.:	VF1ABL15AUC276802
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Mar 2014
First Registration Date:	21 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2022
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$21,812.00
Total Rebate Amount:	\$30,560.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Mar 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5292E**AAD1903-215***Not Authored**1/10/19 \$9500. Max*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5292E

VF1ABL15AUC276802

RENAULT

LATITUDE

27.3.2019

FCIL

21/3/2014

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 FENDER PANEL REAR LH
- 14 1 WHEELARCH REAR LH
- 15 1 FENDER PANEL INNER TRIM REAR LH
- 16 1 WHEEL HOUSING PANEL REAR LH
- 17 1 TAILLAMP LH
- 18 1 TAILLAMP PANEL LH
- 19 1 OUTER PANEL REAR (End Panel)
- 20 1 OUTER PANEL REAR (End Panel)TRIM
- 21 1 SPARE WHEEL PANEL (Luggage Floor Panel)
- 22 1 SPARE WHEEL PANEL TRIM
- 23 1 DOOR PANEL REAR LH
- 24 1 KUCKLE ARM REAR LH L70Y
- 25 1 BRAKE DISC REAR L70Y
- 26 1 ABS SENSOR REAR LH L70Y
- 27 1 REAR AXLE L70Y
- 28 1 LOWER ARM REAR LH L70Y
- 29 1 ABSORBER REAR

- | | | | |
|----|-----------|----------|---|
| \$ | <i>Bu</i> | 1,108.46 | ✓ |
| \$ | <i>SL</i> | 768.84 | ✓ |
| \$ | <i>SL</i> | 113.47 | ✓ |
| \$ | <i>SL</i> | 135.97 | ✓ |
| \$ | <i>SL</i> | 44.99 | ✓ |
| \$ | <i>SL</i> | 43.61 | ✓ |
| \$ | <i>CM</i> | 135.97 | ✓ |
| \$ | <i>CM</i> | 44.99 | ✓ |
| \$ | <i>CM</i> | 43.61 | ✓ |
| \$ | <i>R</i> | 777.52 | ✓ |
| \$ | <i>R</i> | 225.95 | ✓ |
| \$ | <i>R</i> | 225.95 | ✓ |
| \$ | <i>R1</i> | 3,299.13 | ✓ |
| \$ | <i>Di</i> | 543.47 | ✓ |
| \$ | <i>SL</i> | 671.45 | ✓ |
| \$ | <i>R</i> | 4,682.09 | ✓ |
| \$ | <i>CM</i> | 552.55 | ✓ |
| \$ | <i>R</i> | 986.70 | ✓ |
| \$ | <i>R</i> | 1,471.77 | ✓ |
| \$ | <i>SL</i> | 404.56 | ✓ |
| \$ | <i>R</i> | 2,189.88 | ✓ |
| \$ | <i>SL</i> | 612.21 | ✓ |
| \$ | <i>R</i> | 2,844.66 | ✓ |
| \$ | <i>R1</i> | 736.67 | ✓ |
| \$ | <i>SL</i> | 525.91 | ✓ |
| \$ | <i>SL</i> | 375.93 | ✓ |
| \$ | <i>R1</i> | 4,167.03 | ✓ |
| \$ | <i>R1</i> | 905.99 | ✓ |
| \$ | <i>R1</i> | 389.75 | ✓ |

Trans-cab Auto Services Pte Ltd

AAD1903-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5292E

30	1 STABILIZER BAR REAR L70Y	\$	Sm 604.65	X
31	1 EXHAUST REAR	\$	N 7,489.05	X
32	1 EXHAUST CAP REAR	\$	N 230.49	X

TOTAL	\$	37,353.28
10%	\$	3,735.33
	\$	33,617.95

Specical Nett

1	1SET PARKING AID	\$	Sm 700.00	X
2	1SET REAR BUMPER CLIP	\$	N 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	N 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	N 10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	N 20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	N 10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	N 20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	N 22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	N 66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82	
11	1SET BOOT FINISHER CLIP	\$	N 24.20	
12	1 REAR BOOT STICKER 'Trans-cab'	\$	N 80.00	
13	1 REAR BOOT STICKER '6555-3333'	\$	N 80.00	
14	1 REAR DOOR STICKER '6555-3333'	\$	N 80.00	
16	1SET FENDER WHEELARCH REAR RH CLIP	\$	N 35.00	} X
17	1SET FENDER WHEELARCH REAR LH CLIP	\$	N 35.00	
18	1 FENDER INNER TRIM CLIP LH	\$	N 28.00	} X
18	1 FENDER INNER TRIM CLIP LH	\$	N 28.00	
18	1 TAILLAMP CLIP LH	\$	N 5.00	✓
18	2 REAR WINDSCREEN SELANT	\$	N 80.00	40sm
19	1 WINDSCREEN MOULDING	\$	N 100.00	✓
20	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	N 100.00	30sm
21	1 LEFT REAR TYRE	\$	Sm 330.00	X
22	1 LEFT REAR TYRE RIM	\$	N 380.00	✓

TOTAL \$ 1,640.02**TOTAL PARTS \$ 35,257.97**

Trans-cab Auto Services Pte Ltd**AAD1903-215**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5292E**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	7001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	} 801
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601

Trans-cab Auto Services Pte Ltd**AAD1903-215**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5292E

To transfer of rear door fittings, attachment and perform water seepage test.

\$ *na* 380.00 *X*

To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.

\$ 380.00 *2401*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *na* 380.00 *X***TOTAL \$ 11,340.00****Over All Total \$ 46,597.97****(LUMP SUM)****Repair Days***48447.96*
30 DAYS*8 days*LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005698/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7100G	Veh. Inspected	SHC 5292E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002171MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	01/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276802	Colour	METALLIC WHITE / RED	
Odometer	711926	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2019	Inspection Date	01/04/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5292E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR ♂	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR ♂	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR ♂	225.95	-
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR LH	DISTORTED	543.47	543.47
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR ♂	4,682.09	-
1	TAILLAMP LH	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR ♂	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR ♂	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR ♂	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR ♂	2,844.66	-
1	KUCKLE ARM REAR LH L70Y	BENT	736.67	736.67
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-

Report Ref No. CS/FCI19005698/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABS SENSOR REAR LH L70Y	SERVICEABLE	375.93	-
1	REAR AXLE L70Y	BENT	4,167.03	4,167.03
1	LOWER ARM REAR LH L70Y	BENT	905.99	905.99
1	ABSORBER REAR	BENT	389.75	389.75
1	STABILIZER BAR REAR L70Y	SERVICEABLE	604.65	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR ↴	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR ↴	230.49	-
	LESS 10% DISCOUNT		-3,735.33	-1,192.76
			33,617.94	10,734.86
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00

Report Ref No. CS/FCI19005698/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	LEFT REAR TYRE (SN)	SERVICEABLE	330.00	-
1	LEFT REAR TYRE RIM (SN)	DENTED	380.00	380.00
			2,350.02	654.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	660.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,WHEEL HOUSING PANEL REAR LH,TAILLAMP PANEL LH,OUTER PANEL REAR (END PANEL),SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),DOOR PANEL REAR LH,EXHAUST REAR AND EXHAUST CAP REAR.		4,500.00	700.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	80.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19005698/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	240.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	-
			12,480.00	2,050.00
GRAND TOTAL			48,447.96	13,438.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,500.00

Report Ref No. CS/FCI19005698/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.