

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19005747/ADA3Q2

**Date:** 08/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** YN2370Z **Insured Vehicle No :** SME5493Y

**Date of Loss:** 25/03/2019 **Nature of Claim:** TP **Claim No:** 7569312221SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YN2370Z</b>		
Make & Model:	ISUZU NJR85AUE6W, 3.0 D (M)	Engine No:	4JJ1106926
Reg. Date:	04/07/2011 (Man. Year: 2011)	Chassis No:	NJR857017712
Colour:	Blue	Odometer:	234719 km
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	195/75 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,794.75	937.50	1,857.25	66.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	830.00	590.00	41.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,214.75</b>	<b>1,767.50</b>	<b>2,447.25</b>	<b>58.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,214.75</b>	<b>1,400.00</b>	<b>2,814.75</b>	<b>66.78</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>Nett Liability (S\$)</b>		<b>2,000.00</b>		

### INSPECTION

Date of Assignment: 29/03/2019

Date Inspected: 29/03/2019 Inspected At:

Chin Meng Motors (HQ)  
1 Kaki Bukit Ave 6 #01-40/63, Autobay  
@ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP R/H	Not Necessary	450.00 FL	*- FL
2	1		*HEADLAMP CLIP R/H	Not Necessary	10.00 FL	*- FL
3	1		*FRONT SIDE LAMP R/H	Cracked	120.00 FL	*120.00 FL
4	1		*FRONT SIDE LAMP HOLDER R/H	Not Necessary	35.00 FL	*- FL
5	1		*HEADLAMP LOWER GARNISH R/H	Not Necessary	35.00 FL	*- FL
6	1		*FRONT R/H CORNER PANEL	Not Necessary	220.00 FL	*- FL
7	1		*FRONT BUMPER	Deformed	480.00 FL	*480.00 FL
8	2		*FRONT BUMPER BRACKETS	Not Necessary	190.00 FL	*- FL
9	1		*FRONT R/H DOOR	Repair	970.00 FL	*- FL
10	1		*FRONT R/H HINGE LOWER	Not Necessary	85.00 FL	*- FL
11	1		*FRONT R/H DOOR SIGNAL LAMP	Cracked	150.00 FL	*150.00 FL
12	1		*FRONT R/H STEP GARNISH	Not Necessary	190.00 FL	*- FL
13	1		*HEADLAMP WIREMESH R/H	Bent	150.00 FS	*150.00 FS
14	1		*FRONT R/H DOOR SIGNAL LAMP WIREMESH	Missing	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,235.00</b>	<b>1,050.00</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$)</b>	440.25	112.50
<b>Total Parts (\$)</b>	<b>2,794.75</b>	<b>937.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE ARTS AS MENTIONED ABOVE ETC	New	600.00	300.00
2	TO RESPRA AFFECTED PART	New	700.00	500.00
3	TO APPLY UNDERSEAL	New	50.00	0.00
4	TO REMOVE AND REFIT FRONT L/H DOOR GLASS	New	40.00	0.00
5	TO REMOVE & REFIT OF WIRINGS	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,420.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >