振明 摩 哆 HIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018 cmmotors@singnet.com.sg

CC6/ALG190UST47/Ada3

Our Ref: EST115/19/CIS Your Ref: To be advised

29-Mar-19

AIG Asia Pacific Insurance Pte Ltd

Tiale.

78 Shenton Way #08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms.

Re: Estinmate cost of repair to Isuzu NJR85 no: YN2370Z

Date of accident: 25-03-2019 Parts supply: 1 pc Headlamp R/h He M 1 pc Headlamp clip R/h AH ~~ 750 1 pc Front side lamp R/h could. 1 pc Front side lamp holder R/h 24 ~ 1 pc Headlamp lower garnish R/h 637.50 1 pc Front R/h corner panel, ~~ 1 pc Front bumper 1 pc Front R/h door Review 1 pc Front R/h hinge lower 1 pc Front R/h door signal lamp 1 pc Front R/h step garnish

> Less 15%: (440.25)150.00

300.

450.00

120.00 35.00 X

10.00

35.00 X.

220.00 4.

190.00 1 970.00**፟**⊀.

85.00+

190.00 4.

150.00

600.00 ZOO.

700.00 500

50.00

150.00

2,935.00

480.00

ESTIMATE

S\$

S/Nett Items

1 pc Headlamp wiremesh R/h (S/Nett)

1 pc Front R/h door signal lamp wiremesh (S/Nett)

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part. To apply underseal.

To remove and refit front L/h door glass

To remove & refit of wirings.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

total: 1767.50 Adrin 67 45: 1.4K 429/03/19

بر 40.00 30.00 4,214.75