

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19005764/GVD3E2
Date: 02/04/2020

REFERENCE

Insured/Claimant: SEAH LI-YEN JOCELYNN Policy No: 1800098340
Date of Loss: 28/03/2019 Nature of Claim: OD Claim No: 1920631635SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR6778A** Engine No: CVK063933
Make & Model: AUDI A4, 2.0 (A) Chassis No: WAUZZZF44JA188316
Reg. Date: 16/08/2018 (Man. Year: 2018) Odometer: 0 km
Colour: Blue
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: General 8 mm Rear Left Side: General 8 mm
Front Right Side: General 8 mm Rear Right Side: General 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	123,179.41	71,982.69	51,196.72	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	48,176.00	39,136.00	9,040.00	18.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	171,355.41	111,118.69	60,236.72	35.15
Approved Total (Overridden) (S\$)		110,000.00		
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	169,755.41	108,400.00	61,355.41	36.14
+ GST 7.00/7.00% (S\$)	11,882.88	7,588.00	4,294.88	36.14
Nett Amount (S\$)	181,638.29	115,988.00	65,650.29	36.14

INSPECTION

Date of Assignment: 02/04/2019
Date Inspected: 01/04/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 40.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,999.00 FS	*1,599.20 FS
2	2		*FRONT BUMPER SECURING STRIP	Necessary	64.00 FS	*50.88 FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Necessary	33.00 FS	*26.08 FS
4	1		*FRONT BUMPER GUIDE SECTION - RH	Necessary	34.00 FS	*27.12 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	178.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	191.00 FS	*152.40 FS
7	1		*FRONT AIR GUIDE - LH	Missing	56.00 FS	*44.40 FS
8	1		*FRONT AIR GUIDE GRILLE - LH / RH	N/S Missing / O/S Not Necessary	246.00 FS	*98.00 FS
9	1		*FRONT FENDER - LH	Distorted	700.00 FS	*559.60 FS
10	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	183.00 FS	*146.40 FS
11	1		*FRONT FENDER BRACE - LH	Distorted	107.00 FS	*85.60 FS
12	1		*FRONT FENDER END PLATE - LH	Distorted	45.00 FS	*36.00 FS
13	1		*FRONT FENDER BRACKET - LH	Distorted	32.00 FS	*25.20 FS
14	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - LH	Distorted	45.00 FS	*35.60 FS
15	1		*FRONT FENDER REAR BRACKET - LH	Distorted	29.00 FS	*22.64 FS
16	1		*FRONT FENDER UPPER BRACKET - LH	Distorted	31.00 FS	*24.16 FS
17	1		*FRONT FENDER CLOSING ELEMENT	Distorted	30.00 FS	*23.76 FS
18	1		*FRONT FENDER PROTECTION FILM - LH	Not Necessary	11.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER - LH	Distorted	223.00 FS	*178.40 FS
20	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART - LH	Distorted	82.00 FS	*65.52 FS
21	1		*FRONT FENDER LINER LOWER COVER - LH	Missing	13.00 FS	*10.16 FS
22	1		*FRONT WHEEL ARC TRIM - LH	Missing	66.00 FS	*52.32 FS
23	1		*FRONT FENDER MOLDING - LH	Not Necessary	32.00 FS	*- FS
24	1		*FRONT STONE CHIP GUARD - LH	Necessary	46.00 FS	*36.64 FS
25	1		*LED HEADLIGHT - LH	Cracked	7,087.00 FS	*5,669.60 FS
26	1		*LED HEADLIGHT POWER MODULE - LH	Not Necessary	716.00 FS	*- FS
27	1		*LED HEADLIGHT CONTROL UNIT - LH	Not Working	685.00 FS	*548.00 FS
28	1		*LED HEADLIGHT DRAIN HOSE - LH	Not Necessary	32.00 FS	*- FS
29	2		*LED HEADLIGHT COMPENSATING PIECE	Not Necessary	77.00 FS	*- FS
30	2		*LED HEADLIGHT ASSEMBLY SPACER	Not Necessary	72.00 FS	*- FS
31	1		*LED HEADLIGHT LIFT CYLINDER - LH	Damaged	192.00 FS	*153.20 FS
32	1		*LED HEADLIGHT LIFT CYLINDER BRACKET - LH	Necessary	6.00 FS	*4.24 FS
33	1		*FRONT DOOR - LH	Buckled	2,152.00 FS	*1,721.60 FS
34	1		*FRONT DOOR OUTER DOOR SEAL - LH	Necessary	185.00 FS	*147.60 FS
35	1		*BONDING AGENT	Necessary	45.00 FS	*36.00 FS
36	1		*CLEANING SOLUTION	Necessary	65.00 FS	*52.00 FS
37	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
38	1		*FRONT DOOR ATTACHMENT PARTS - LH	Necessary	488.00 FS	*390.00 FS
39	1		*FRONT DOOR HINGE HALF UPPER PART - LH UPPER	Bent	41.00 FS	*32.08 FS
40	1		*FRONT DOOR HINGE HALVES - LH UPPER	Bent	42.00 FS	*33.04 FS
41	1		*FRONT DOOR HINGE HALF - LH LOWER	Bent	39.00 FS	*30.80 FS
42	1		*FRONT DOOR HINGE HALVES - LH LOWER	Bent	42.00 FS	*33.04 FS
43	1		*FRONT DOOR CATCH - LH	Bent	96.00 FS	*76.16 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT DOOR CATCH COVER - LH	Necessary	13.00 FS	*10.40 FS
45	1		*FRONT DOOR SEAL INNER - LH	Necessary	185.00 FS	*147.60 FS
46	1		*FRONT DOOR MOUNTING BAR - LH	Necessary	149.00 FS	*118.80 FS
47	1		*FRONT DOOR HANDLE OUTSIDE GASKET - LH	Necessary	4.00 FS	*3.20 FS
48	1		FRONT *FRONT DOOR HANDLE OUTSIDE GASKET - LH	Necessary	4.00 FS	*3.20 FS
49	1		REAR *FRONT DOOR HANDLE EXTERIOR - LH	Necessary	35.00 FS	*27.52 FS
50	1		*FRONT DOOR HANDLE SENSOR - LH	Necessary	208.00 FS	*166.40 FS
51	1		*FRONT DOOR HANDLE TRIM PLATE - LH	Necessary	80.00 FS	*63.52 FS
52	1		*FRONT DOOR HANDLE LOCK COVER - LH	Necessary	6.00 FS	*4.08 FS
53	1		*FRONT DOOR LOCK - LH	Damaged	394.00 FS	*314.80 FS
54	1		*FRONT DOOR INNER PANNEL COVER - LH	Necessary	25.00 FS	*19.76 FS
55	1		*FRONT WINDOW GUIDE - LH	Necessary	412.00 FS	*329.20 FS
56	1		*FRONT WINDOW GUIDE TRIM STRIP - LH	Necessary	235.00 FS	*187.60 FS
57	1		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - LH	Necessary	280.00 FS	*224.00 FS
58	1		*FRONT B-PILLAR TRIM - LH	Necessary	212.00 FS	*169.60 FS
59	1		*FRONT CONER TRIM - LH	Necessary	41.00 FS	*32.80 FS
60	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	Damaged	250.00 FS	*199.60 FS
61	1		*FRONT WINDOW REGULATOR - LH	Jammed	278.00 FS	*222.40 FS
62	1		*FRONT EXTERIOR MIRROR MOUNTING - LH	Not Necessary	999.00 FS	*- FS
63	1		*FRONT MIRROR GLASS - LH	Not Necessary	1,553.00 FS	*- FS
64	1		*FRONT MIRROR CAP - LH	Repair	220.00 FS	*175.60 FS
65	1		*FRONT TURN SIGNAL INDICATOR - LH	Not Working	96.00 FS	*76.72 FS
66	1		*REAR DOOR - LH	Dented	2,152.00 FS	*1,721.60 FS
67	1		*REAR OUTER DOOR SEAL - LH	Necessary	185.00 FS	*147.60 FS
68	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
69	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
70	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
71	1		*REAR DOOR SEALING STRIP - LH	Necessary	15.00 FS	*11.68 FS
72	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	515.00 FS	*- FS
73	1		*REAR DOOR CATCH - LH	Bent	109.00 FS	*87.20 FS
74	1		*REAR DOOR SEAL, INNER - LH	Not Necessary	201.00 FS	*- FS
75	1		*REAR WINDOW SLOT SEAL WITH TRIM STRIP - LH	Cut	335.00 FS	*267.60 FS
76	1		*REAR WINDOW GUIDE TRIM STRIP - LH	Not Necessary	216.00 FS	*- FS
77	1		*REAR B PILLAR TRIM - LH	Not Necessary	127.00 FS	*- FS
78	1		*REAR DOOR WINDOW - LH	Not Necessary	265.00 FS	*- FS
79	1		*FRONT LOCK CARRIER MOUNTING	Cracked	928.00 FS	*742.00 FS
80	1		*A/C DISCHARGE HOSE	Bent	310.00 FS	*248.00 FS
81	1		*A/C RECEIVER DRIER	Bent	227.00 FS	*181.60 FS
82	1		*A/C COMPRESSOR HOSE	Bent	152.00 FS	*121.20 FS
83	1		*A/C HOSE AND TUBE ASSEMBLY	Bent	476.00 FS	*380.40 FS
84	2		*A/C O-SEAL RING	Not Necessary	8.00 FS	*- FS
85	2		*A/C LINE O-RING	Not Necessary	10.00 FS	*- FS
86	1		*FRONT FENDER PROTECTION FILM - LH	Not Necessary	21.00 FS	*- FS
87	1		*FRONT FENDER TOP LEDGE COVER - LH	Not Necessary	28.00 FS	*- FS
88	1		*FRONT FENDER LEDGE COVER - LH	Not Necessary	56.00 FS	*- FS
89	1		*FRONT WIPER CROWL TRIM	Not Necessary	89.00 FS	*- FS
90	1		*FRONT SECTIONAL PART - PILLAR A/B - LH	Distorted	2,443.00 FS	*1,954.40 FS
91	1		*FRONT A-PILLAR-LH OUTER	Distorted	976.00 FS	*780.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
92	1		*WEB PLATE FOR SIDE MEMBER - LH	Bent	134.00 FS	*107.20 FS
93	1		*REINFORCEMENT FOR LOWER SIDE MEMBER - LH	Bent	329.00 FS	*262.80 FS
94	1		*FRONT SENSOR - INNER / OUTER (2PCS)	Missing (1Pc Only)	231.00 FS	*184.80 FS
95	1		*SET FRONT BUMPER WIRING	Not Working	470.00 FS	*376.00 FS
96	1		*FANFARE - HIGH TONE LH	Not Working	37.00 FS	*29.20 FS
97	1		*FANFARE MOUNT BRACKET - LH	Bent	26.00 FS	*20.80 FS
98	1		*FRONT UNDERTRAY	Deformed	520.00 FS	*416.00 FS
99	1		*REAR UNDERTRAY	Deformed	358.00 FS	*286.00 FS
100	1		*FRONT UNDERBODY TRIM - LH	Deformed	37.00 FS	*29.44 FS
101	1		*UNDERBODYTRIM - LH	Missing	289.00 FS	*230.80 FS
102	1		*FRONT BUMPER FOAM FILLER PIECE	Necessary	113.00 FS	*90.40 FS
103	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
104	2		*FRONT BUMPER SUPPORT - LH / RH	Broken	52.00 FS	*40.64 FS
105	1		*FRONT LOCK CARRIER BRACKET	Cracked	125.00 FS	*100.00 FS
106	1		*FRONT SCUFF PLATE - LH	Necessary	109.00 FS	*87.20 FS
107	1		*FRONT SUSPENSION SUBFRAME	Bent	1,726.00 FS	*1,380.80 FS
108	1		*ENGINE BRACKET HOLDER	Cracked	430.00 FS	*343.60 FS
109	1		*FRONT LOWER CONTROL ARM - LH	Bent	491.00 FS	*392.40 FS
110	1		*FRONT SUSPENSION GUIDE - LH	Bent	861.00 FS	*688.40 FS
111	1		*FRONT UPPER CONTROL ARM - LH	Bent	466.00 FS	*372.80 FS
112	1		*REAR UPPER CONTROL ARM - LH	Bent	466.00 FS	*372.80 FS
113	1		*FRONT WHEEL BEARING HOUSING - LH	Bent	884.00 FS	*707.20 FS
114	1		*FRONT SWIVEL JOINT - LH	Bent	175.00 FS	*140.00 FS
115	1		*FRONT WHEEL HUB - LH	Bent	451.00 FS	*360.40 FS
116	2		*FRONT WHEEL BEARING WITH ASSEMBLY PART - LH	Bent	660.00 FS	*370.40 FS
117	1		*FRONT SUSPENSION FORKS - LH	Bent	239.00 FS	*190.80 FS
118	2		*FRONT STABILIZER SWAT BAR END LINK - LH	Bent	245.00 FS	*196.00 FS
119	1		*FRONT STABILIZER BAR	Bent	397.00 FS	*317.60 FS
120	1		*FRONT STABILIZER BAR BUSHING	Bent	20.00 FS	*15.76 FS
121	1		*FRONT STABILIZER BRACKET	Not Necessary	10.00 FS	*- FS
122	1		*FRONT SUSPENSION SHOCK ABSORBER TOP MOUNTING - LH	Bent	84.00 FS	*66.80 FS
123	1		*FRONT SUSPENSION SPRING SUPPORT - LH	Bent	56.00 FS	*44.56 FS
124	1		*FRONT SUSPENSION ABSORBER RUBBER STOP - LH	Necessary	34.00 FS	*26.64 FS
125	1		*FRONT PROTECTIVE SLEEVE	Necessary	8.00 FS	*6.40 FS
126	1		*FRONT PROTECTIVE CAP	Necessary	4.00 FS	*3.20 FS
127	1		*FRONT SUSPENSION SHOCK SPACER - LH	Necessary	28.00 FS	*22.32 FS
128	1		*FRONT SUSPENSION SPRING DISC LOWER - LH	Bent	36.00 FS	*28.80 FS
129	1		*FRONT GAS SHOCK ABSORBER - LH	Bent	276.00 FS	*220.40 FS
130	1		*FRONT COIL SPRING - LH	Not Necessary	238.00 FS	*- FS
131	1		*FRONT DRIVE SHAFT - LH	Bent	2,422.00 FS	*1,937.60 FS
132	1		*FRONT WIRING SET FOR SPEED SENSOR - LH	Activated	224.00 FS	*178.80 FS
133	1		*FRONT HOSE BRAKE BRACKET - LH	Not Necessary	25.00 FS	*- FS
134	1		*FRONT BRAKE HOSE BRACKET - LH	Not Necessary	25.00 FS	*- FS
135	1		*FRONT BRAKE CALIPER HOUSING - LH	Bent	246.00 FS	*340.40 FS
136	1		*FRONT BRAKE CALIPER CARRIER - LH	Bent	221.00 FS	*176.80 FS
137	1		*FRONT BRAKE PADS WITH WEAR INDICATOR - LH	Necessary	255.00 FS	*204.00 FS
138	1		*FRONT BRAKE DISC - LH	Bent	219.00 FS	*175.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
139	1		*FRONT BRAKE DISC COVER PLATE - LH	Bent	106.00 FS	*84.40 FS
140	1		*FRONT BRAKE HOSE - LH	Twisted	70.00 FS	*55.84 FS
141	2		*FRONT BRAKE HOSE CLIP - LH	Not Necessary	4.00 FS	*- FS
142	1		*FRONT BRAKE PIPE FROM HYDRAULICS TO BRAKE HOSE - LH	Twisted	50.00 FS	*39.44 FS
143	2		*FRONT BRAKE FLUID 1.0 LTR	Necessary	59.00 FS	*46.56 FS
144	1		*STEERING WHEEL AIR BAG UNIT	Activated	3,141.00 FS	*2,512.80 FS
145	1		*FRONT DASHBOARD AIR BAG UNIT	Activated	4,019.00 FS	*3,215.20 FS
146	1		*ROUND CONNECTOR HSD WITH CABLE	Activated	241.00 FS	*192.80 FS
147	1		*SIDE AIRBAG UNIT - LH	Activated	1,391.00 FS	*1,112.80 FS
148	1		*SIDE AIRBAG WIRING HARNESS - LH	Activated	190.00 FS	*151.60 FS
149	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,416.00 FS	*2,732.80 FS
150	1		*AIR BAG CONTROL UNIT	Activated	1,927.00 FS	*1,541.60 FS
151	3		*FRONT AIR BAG CRASH SENSOR	Activated	1,145.00 FS	*915.60 FS
152	1		*FRONT DASHBOARD WITH AIR DUCT	Damaged	4,838.00 FS	*3,870.40 FS
153	1		*FRONT CENTRAL CONSOLE TRIM PART	Not Necessary	113.00 FS	*- FS
154	2		*FRONT A-PILLAR TRIM - LH UPPR / RH UPPER	Necessary	374.00 FS	*298.40 FS
155	2		*FRONT GRAB HANDLE FOLDING - LH / RH	Broken	258.00 FS	*103.20 FS
156	2		*REAR GRAB HANDLE FOLDING - LH / RH	Not Necessary	258.00 FS	*- FS
157	1		*MOULDED HEADLINING	Necessary	1,751.00 FS	*1,400.80 FS
158	2		*THREE POINT AUTOMATIC SEAT - LH / RH	Activated	2,010.00 FS	*1,608.00 FS
159	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	322.00 FS	*257.60 FS
160	1		*BACKREST COVER - LH	Torn	2,232.00 FS	*1,785.60 FS
161	1		*BACKREST FOR PADDING - RH (NPA)	Not Necessary	0.00 FS	*- FS
162	1		*FRONT WINDSCREEN	Necessary	1,040.00 FS	*832.00 FS
163	1		*FRONT WINDSCREEN GEL FOIL FOR RAIN SENSOR	Necessary	128.00 FS	*102.40 FS
164	1		*CENTRAL PROTECTION	Necessary	485.00 FS	*388.00 FS
165	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
166	1		*ACRYLIC SEALANT	Necessary	360.00 FS	*360.00 FS
167	1		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
168	1		*STONE CHIP	Necessary	360.00 FS	*360.00 FS
169	1		*FRONT CAR PLATE NO.	Not Necessary	25.00 FS	*- FS
170	1		*SUNDRIES	Necessary	2,000.00 FS	*642.36 FS
171	1		*FRONT FENDER END PLATE - LH	Necessary	25.04 FS	*25.04 FS
172	1		*DRAIN HOSE FOR HEADLIGHT WASHER SYSTEM - LH	Missing	25.36 FS	*25.36 FS
173	2		*HEADLIGHT COMPESATING ELEMENT - LH	Necessary	53.60 FS	*53.60 FS
174	2		*HEADLIGHT RETAINER PLATE SPACER - LH	Necessary	53.60 FS	*53.60 FS
175	2		*HEADLIGHT SCREW ASSEMBLY SPACE - LH	Necessary	59.20 FS	*59.20 FS
176	1		*FRONT FENDER TOP COVER - LH	Missing	22.24 FS	*22.24 FS
177	1		*FRONT FENDER LEDGE COVER - LH	Missing	41.52 FS	*41.52 FS
178	1		*SOCKET - JACK	Necessary	32.40 FS	*32.40 FS
179	4		*HEXAGON HEAD BOLT	Necessary	40.32 FS	*40.32 FS
180	4		*HEXAGON NUT	Necessary	1.60 FS	*1.60 FS
181	4		*POP RIVET	Necessary	2.88 FS	*2.88 FS
182	8		*HEXAGON BOLT	Necessary	49.92 FS	*49.92 FS
183	1		*RETAINER FOR BRAKE HOSE - LH	Necessary	19.40 FS	*19.40 FS
184	1		*JOINTED SHAFT - LH	Necessary	26.88 FS	*26.88 FS
185	1		*REAR VIEW MIRROR	Distorted	786.80 FS	*786.80 FS
186	1		*FRONT DOOR TRIM - LH	Cracked	1,502.40 FS	*1,502.40 FS
187	1		*ENGINE MOUNTING - LH	Bent	301.60 FS	*301.60 FS
188	1		*ENGINE MOUNTING BRACKET - LH	Cracked	119.20 FS	*119.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
189	1		*ENGINE MOUNTING HOLDER SUPPORT	Necessary	49.76 FS	*49.76 FS
190	1		*ENGINE AND GEARBOX FIXING PARTS	Necessary	102.40 FS	*102.40 FS
191	1		*ENGINE OIL SUMP - LOWER PART	Necessary	248.40 FS	*248.40 FS
192	1		*ENGINE OIL SUMP - UPPER PART	Necessary	405.60 FS	*405.60 FS
193	1		*HEXAGON SOCKET HEADBOLT	Not Necessary	16.00 FS	*- FS
194	2		*ENGINE OIL LEVEL SENSOR SEAL RING	Necessary	17.60 FS	*17.60 FS
195	1		*SILICONE SEALANT	Necessary	46.48 FS	*46.48 FS
196	1		*SHAFT OIL SEAL	Necessary	16.40 FS	*16.40 FS
197	1		*HIGH LUBRICITY ENGINE OIL 5.0 LTR	Necessary	215.60 FS	*215.60 FS
198	1		*CROSS MEMBER FOR WHEEL HOUSING LINER	Necessary	49.28 FS	*49.28 FS
199	1		*WHEEL HOUSING LINER LENGTH EXTENSION - LH	Missing	221.60 FS	*221.60 FS
200	1		*FRONT FENDER REINFORCEMENT - LH	Distorted	101.60 FS	*101.60 FS
201	1		*FRONT FENDER LOWER PLATE - LH	Distorted	221.60 FS	*221.60 FS
202	1		*7 SPEED DUAL CLUTCH GEARBOX	Not Necessary	27,830.00 FS	*- FS
203	1		*DUAL CLUTCH TRANSMISSION FLUID 1.0 LTR	Necessary	97.60 FS	*97.60 FS
204	1		*FRONT A-PILLAR OUTER - LH	Repeated	976.00 FS	*- FS
205	1		*STEERING COLUMN CRUISE CONTROL	Activated	752.00 FS	*752.00 FS
206	1		*STEERING GEAR	Bent	4,751.20 FS	*4,751.20 FS
207	1		*FRONT TIE ROD END - LH	Bent	144.00 FS	*144.00 FS
208	1		*FRONT SPEED SENSOR	Activated	71.84 FS	*71.84 FS
209	1		*FRONT RIM - LH (AFTER MARKET RIM)	Distorted	500.00 FS	*500.00 FS
210	1		*FRONT TYRE - LH (245/40 R18)	Distorted	272.00 FS	*272.00 FS
211	1		*FRONT REINFORCEMENT BEAM	Bent	586.00 FS	*586.00 FS
212	1		*SEALING FLANGE	Necessary	214.00 FS	*214.00 FS
213	1		*STEERING UNDER DASH COVER	Necessary	184.00 FS	*184.00 FS
214	1		*LHS B PILLAR LOWER COVER	Scratched	112.00 FS	*112.00 FS
215	1		*LHS SILL PANEL INNER REINFORCEMENT	Bent	365.60 FS	*365.60 FS
216	1		*LHS A PILLAR LOWER INNER REINFORCEMENT	Bent	162.80 FS	*162.80 FS
217	1		*LHS CURTAIN AIR BAG CONNECTOR	Necessary	138.80 FS	*138.80 FS
218	1		*LHS FRONT DOOR ARM REST TRIM	Cut	388.00 FS	*388.00 FS
219	1		*LHS FRONT WHEEL SPOILER	Missing	77.36 FS	*77.36 FS
220	1		*DASHBOARD AIR VENT - CENTRE	Necessary	122.40 FS	*122.40 FS
221	1		*LHS REAR DOOR HINGE - LOWER	Bent	33.04 FS	*33.04 FS
222	1		*FLOORPAN RUBBER PLUG (4PCS)	Necessary	61.49 FS	*61.49 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 123,179.41 71,982.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO CARRY OUT FIRST MEASUREMENT ON CAR-LINER	New	800.00	800.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN	New	480.00	480.00
4	TO REMOVE AND TRANSFER, AIR CON CONDENSER, TURBO COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
5	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOORS MULTI LOCKS SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	720.00	720.00
6	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,400.00	1,400.00
7	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND CENTRAL PROTECTION	New	3,600.00	3,600.00
8	TO RENEW PASSENGER SEAT AIR BAG AND LEATHER COVER	New	800.00	800.00
9	TO SUSPEND ENGINE, REMOVE AND REINSTALL FRONT SUSPENSION FOR CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	2,800.00	2,800.00
10	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER ASSY, REAR SUSPENSION ASSY AND FUEL TANK, FOR CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES	New	2,800.00	2,800.00
11	TO PLACE VEHICLE ON CAR-O-LINER	New	1,800.00	1,800.00
12	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, LHS FRONT AND REAR DOORS. INSPECT LHS WHEEL HOUSE AND FLOOR PAN FOR DAMAGES. CUT OUT AND WELD LHS A-PILLAR, INNER REINFORCEMENTS, SILL PANEL AND INNER WEB PLATES. RENEW FRONT LOCK CARRIER. RENEW ALL DAMAGED PANELS. REINSTALL ALL PARTS REMOVED	New	12,600.00	10,500.00
13	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT AND REAR DOORS, DOOR HANDLES, LHS A-PILLAR, SILL PANEL, DOOR ENTRANCES AND INNER REINFORCEMENTS. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	6,500.00	4,750.00
14	TO RENEW LHS FRONT AND REAR RIMS AND LHS FRONT TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	576.00	576.00
16	TO REMOVE AND REINSTALL DASHBOARD INNER FRAMES, WIRE HARNESS AND ALL ATTACHMENTS	New	1,800.00	1,800.00
17	TO CUT OUT AND WELD LHS INNER WHEEL HOUSE, FLOOR PAN, FIRE WALL LOWER SECTION AND REINFORCEMENTS	New	5,500.00	1,500.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
18	TO RESEAL FIRE WALL AND FLOOR PAN SECTION, RESPRAY INNER WHEEL HOUSE, FLOOR PANS AND INNER PANELS	New	2,600.00	1,650.00
19	TO RENEW GEAR BOX ASSY AND CARRY OUT ADAPTATION	New	1,200.00	960.00
20	TO RE-NEW FRONT WINDSCREEN SOLAR FILM	New	400.00	400.00
Gross Labour Cost (S\$)			48,176.00	39,136.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >