

Continued

ASSIGNMENT

REF

CS/FCI 19005775/Dxd31ⁿ²

Special Instruction

Officer/Agent

aus

Boyer
May chun

ASSIGNMENT (Office)

FCI

Date/Time 11:14am 26/3/19

From (Person)

Estimated Cost

Bill to

OD/TT/WS/TP/RES/OD/RES/EVA/INV/MT/CS

To Inspect Vehicle No

SHC 8689A

Insured

SHA 4170R

at Workshop no

chunni Motor

Tel

of

Blk 10 AMK Ind. park 2A #03-19

Policy No

Claim No

D19002043MPST

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 24/3/2019

CA / REV / REF / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time

26/3/19

Person Contacted

lym

Vehicle

IN

OUT

Date/Time

Action/Instruction (/) Estimate

24/4/19

Email preli revised to FCI

REF


Vehicle Survey

05 Jan 2024

From: _____ Date: _____
 Estimated cost: _____
 (D) / (T) / (W) / (R) / (S) / (O) / (R) / (S) / (E) / (V) / (A) / (H) / (V) / (M)
 Technopec Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 11 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHC 8689A** at Regd: **2016 Jan**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or _____
 Make: **Hyundai I40** C/S: **1685**
 Colour: **Blue** A/C: Insured / Std / Nil / NA
 Sp Reading: **417403** T/Radio: Insured / Std / Nil / NA
 Engine No: **D4FDFU580586**
 Chassis: **KMHLB41UMGU083134**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or _____
 Brake: Insured / Jammed / Leaked / Burnt or _____
 Mod: Nil S/Rim / STD A/Rim or _____
 Tyre Size: F: **205/60 R16**
 R: **— " —**
 BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Wastlake**
 Front: _____ Rear: _____
 R/Bal: **5** mm R/Bal: **5** mm
 L/Bal: **5** mm L/Bal: **5** mm
 D.O.A: **24/03/2019** D.O.I: **26/03/2019**
 Survey held at: **Chunni AMC**
 Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or _____
N/S Front y N/S Body y N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

First report SHA 4170R

24/04/19 Jmwr 1/3 15500/- with 11 days of repair (Red 9826.88, 3999)

RECEIVED 24 APR 2019

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 Date/Time, File Return to? _____

24/4 - typist

Report Format: **CWS**
 Lump Sum / L.B.L: **15,500/-**

Add Fee: ☐ Site Insp. (\$) ☐
☐ Interview (\$) ☐
☐ Tech. fees (\$) ☐
☐ Weekend (\$) ☐

Days Of Repair: **11**
 Resurvey No. of Trip: **2**

Survey Fee:
 Interpretation

Photo: **580**
 Other: **05P**

24/4/19

15x15 = 225
 170 + 225
 50
 50 + 50
 190
735



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002043MFSH

Our ref: CS/FCI19005775/Dvd3

Date: 2/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHC 8689A

We thank you for your instruction on 26/3/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/3/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-


Workshop Estimate Amount	: S\$25,326.88
Revised Estimate Amount	: S\$18,940.48
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion, n/s rear portion and n/s body

Comments/Present Status:

Damages Consistent



Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	25-03-2019	Our Ref No. D19002043MFSH
Accident Date	24-03-2019	Claim Type. Third Party
Insured Vehicle	SHA4170R	Third Party Vehicle. SHC8689A
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 2 April 2019 2:25 PM
To: 'CWS Motor Claims'
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002043MFSH/2, SHC 8689A
Attachments: SHC 8689A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 8689A
Date of survey: 26/3/2019
Number of days : 11 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 1 April 2019 4:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002043MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 1 April 2019 3:29 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin
<maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19002043MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

QTY	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH) Vst			\$ 663.00
	Front Fender Shield (LH) NW			\$ 174.90
	Rear Bumper NW			\$ 553.00
	Rear Bumper Clip 10 pcs SWC			\$ 22.00
	Rear Fender With Housing (LH) Buc			\$ 4,736.80
	Rear Fender Inner Lining (LH) deformed			\$ 169.30
	Rear Windscreen Moulding LW			\$ 28.30
	Fuel Lid Cover destroyed			\$ 70.90
	Rear Door (LH) Buc			\$ 2,201.10
	Rear Door Rubber (LH) deformed			\$ 280.50
	Rear Door Gear/Regulator (LH) 2 mandy crank			\$ 242.80
	Rear Door Power Motor (LH) NW			\$ 158.60
	Rear Door Lock Assy Dam			\$ 240.00
	Rear Door Hinge Lower (LH) Vst			\$ 45.90
	Rear Door Check (LH) Vst			\$ 62.90
	Rear Door Trim Board (LH) 2 mandy broken			\$ 808.70
	Front Door (LH) Buc			\$ 2,256.40
	Front Door Gear / Regulator (LH) 2 mandy broken			\$ 250.60
	Front Door Inner Lock (LH) Dam			\$ 290.80
	Front Door Outer Moulding (LH) NW			\$ 47.10
	Front Door Power Motor, LH NW			\$ 172.70
	Front Door Trim Board (LH) broken			\$ 973.50
	Door Centre Pillar Outer (LH) Buc			\$ 2,527.80
	Rocker Panel Outer Garnish (LH) Deformed dislodged			\$ 341.40
	Rocker Panel Outer destroyed Buc Deform			\$ 1,310.60
	Rocker Panel Step Garnish (Front) (LH) deformed			\$ 31.70
	Rocker Panel Step Garnish (Rear) (LH) deformed			\$ 31.70
	Rear Tyre Rim (LH) NW photo taken			\$ 325.30
	Rear Wheel Hub-Cap (LH) NW photo taken			\$ 107.10
	Rear Wheelbearing ING & Hub 2 Dam			\$ 362.00
	Rear Trailing Arm (LH) Not photo taken distrital			\$ 192.00
	Rear Assist (LH) Not photo taken distrital			\$ 145.70
	Rear Shock Absorber (LH) Not photo taken distrital			\$ 276.30
	Rear Shock Absorber Mounting (LH) NW			\$ 81.30
	Rear Crossmember NW photo taken			\$ 1,021.50
	Stabilizer Bar NW			\$ 199.60
	Stabilizer Link NW			\$ 85.90
	Rear Upper Arm (LH) 2 distrital			\$ 335.75
	Rear Lower Arm (LH) 2 distrital			\$ 353.80
	Rear Knuckle Arm (LH) 2 distrital			\$ 545.60
	SUB TOTAL			\$ 22,724.85
	LESS 20%			\$ 4,544.97
	DISCOUNTED TOTAL			\$ 18,179.88

SHC 8689A

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender Advertisement Logo (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Hec</i>			\$ 80.00	Nett ✓
	Front Door Coloured Comfort Logo (LH) <i>Hec</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Tyre (LH) <i>Svc</i>		701.00	\$ 216.00	Nett X
	Front Fender Advertisement Logo(LH) <i>Hec</i>			\$ 100.00	Nett ✓
				\$ 917.00	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1200/-
	Spray Painting Charge			\$ 1,750.00	1000/-
	Wiring Charge			\$ 100.00	42/-
	Tuff Kote			\$ 150.00	40/-
	Towing Charge			\$ 50.00	42/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	42/-
	Remove/Refix Fuel Tank			\$ 150.00	42/-
	Transfer of Door	\$ 120.00	\$ 240.00	120/-	
	Remove/Refix Undercarriage (RR)		\$ 200.00	150/-	
	Rear Wheel Alignment		\$ 120.00	60/-	
	Re-set Rear ABS System	2910.00	\$ 200.00		
	Re-set Frt & Rear Power Window System	\$ 200.00	\$ 400.00		
	Diagnostic & Resetting To Erase Fault Code		\$ 480.00		180/-
	TOTAL LABOUR			\$ 6,230.00	
	ESTIMATE TOTAL		19431.68	\$ 25,326.88	
	26/03/2019 @ 1300hrs		4/515500/-		
	via Antman				
	1/5mm 11 days				
	yan				
	LKK Auto				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8689 A

Technician:

Mileage: 417403

Time Printed 26.3.19 2:00 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°39'		-3°00' 3°00'
3°52'		-0°19' 5°41'
-0°03'		-1°30' 1°30'
17°29'		
16°50'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°14'		-3°00' 3°00'
4°00'		-0°19' 5°41'
0°06'		-1°30' 1°30'
15°29'		
15°15'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°24'		-3°00' 3°00'
-0°07'		-3°00' 3°00'
2°00'		-3°00' 3°00'
0°03'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°35'		-3°30' 2°30'
3°03'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°48'		-3°30' 2°30'
0°13'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°13'		-3°00' 3°00'
3°16'		-3°00' 3°00'
1°25'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19005775/Dvd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4170R	Veh. Inspected	SHC 8689A
Policy No.		Coverage (\$)	0.00
Claim No.	D19002043MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	26/03/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU083134	Colour	BLUE
Odometer	417403	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY,N/S FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/03/2019	Inspection Date	26/03/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8689A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER (LH)	BENT	663.00	663.00
1	FRONT FENDER SHIELD (LH)	NOT NECESSARY	174.90	-
1	REAR BUMPER	NOT NECESSARY	553.00	-
10	REAR BUMPER CLIP	SERVICEABLE	22.00	-
1	REAR FENDER WITH HOUSING (LH)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	DEFORMED	169.30	169.30
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	FUEL LID COVER	DISLODGE	70.90	70.90
1	REAR DOOR (LH)	BUCKLED	2,201.10	2,201.10
1	REAR DOOR RUBBER (LH)	DEFORMED	280.50	280.50
1	REAR DOOR GEAR/REGULATOR (LH)	MOUNTING CRACKED	242.80	242.80
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	158.60	-
1	REAR DOOR LOCK ASSY	DAMAGED	240.00	240.00
1	REAR DOOR HINGE LOWER (LH)	BENT	45.90	45.90
1	REAR DOOR CHECK (LH)	BENT	62.90	62.90
1	REAR DOOR TRIM BOARD (LH)	MOUNTING BROKEN	808.70	808.70
1	FRONT DOOR (LH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (LH)	MOUNTING BROKEN	250.60	250.60
1	FRONT DOOR INNER LOCK (LH)	DAMAGED	290.80	290.80
1	FRONT DOOR OUTER MOULDING (LH)	NOT NECESSARY	47.10	-
1	FRONT DOOR POWER MOTOR, LH	NOT NECESSARY	172.70	-
1	FRONT DOOR TRIM BOARD (LH)	BROKEN	973.50	973.50
1	DOOR CENTRE PILLAR OUTER (LH)	BUCKLED	2,527.80	2,527.80
1	ROCKER PANEL OUTER GARNISH (LH)	DISLODGE	341.40	341.40
1	ROCKER PANEL OUTER	BUCKLED / DENTED	1,310.60	1,310.60
1	ROCKER PANEL STEP GARNISH (FRONT)(LH)	DEFORMED	31.70	31.70
1	ROCKER PANEL STEP GARNISH (REAR)(LH)	DEFORMED	31.70	31.70
1	REAR TYRE RIM (LH)	NOT NECESSARY	325.30	-

Report Ref No. CS/FC119005775/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL HUP-CAP (LH)	NOT NECESSARY	107.10	-
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-4,544.97	-3,955.17
			18,179.88	15,820.68
	<u>SPECIAL NETT ITEMS</u>			
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
			917.00	701.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,000.00	1,200.00
	SPRAY PAINTING CHARGE.		1,750.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00

Report Ref No. CS/FCI19005775/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
			6,230.00	2,910.00
GRAND TOTAL			25,326.88	19,431.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,500.00

Report Ref No. CS/FCI19005775/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.