



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 909D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HEADLAMP COWLING	NOT NECESSARY	832.00	-
1	HEADLAMP TOP COVER	USABLE	312.00	-
1	COWLING STAY	NOT NECESSARY	312.00	-
1	SIDE LAMP RH	CUT	132.00	132.00
2	HANDLE BAR @\$147.00	O/S BENT	294.00	147.00
1	SET HANDLE BALANCER	CUT	76.00	76.00
1	SET HANDLE GRIP	USABLE	72.00	-
1	BRAKE LEVER	BENT / CUT	72.00	72.00
1	CLUTCH LEVER	USABLE	55.00	-
2	MIRROR @\$123.00	NOT NECESSARY	246.00	-
1	SET HEAD LAMP ASSY	NOT NECESSARY	840.00	-
1	FRONT FENDER	NOT NECESSARY	265.00	-
2	FRONT FORK ASSY @\$860.00	NOT NECESSARY	1,720.00	-
1	STEERING STEM	NOT NECESSARY	520.00	-
1	FRONT RIM	NOT NECESSARY	680.00	-
2	FRONT BRAKE DISC L @\$425.00	NOT NECESSARY	850.00	-
1	FUEL TANK	NOT NECESSARY	975.00	-
1	SIDE FAIRING RH	NOT NECESSARY	826.00	-
1	SIDE FAIRING "X: MARK	NOT NECESSARY	76.00	-
1	MID FAIRING CENTRE LOWER	NOT NECESSARY	315.00	-
1	FRONT FOOTREST RH	BENT / CUT	73.00	73.00
1	FRONT FOOTREST BRACKET RH	BENT	135.00	135.00
1	BRAKE PEDAL	BENT	75.00	75.00
1	REAR FOOTREST RH	BENT / CUT	65.00	65.00
1	REAR FOOTREST BRACKET RH	BENT	192.00	192.00
1	REAR SIGNAL LAMP RH	CUT	73.00	73.00
1	REAR PILLION GRIP RH	NOT NECESSARY	125.00	-
1	TAIL BOX COVER ASSY	NOT NECESSARY	655.00	-
1	EXHAUST ASSY (AFTER MARKET)	NOT NECESSARY	1,800.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,266.30	-104.00
			11,396.70	936.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	NOT REQUIRED	12.00	-
1	STEERING CONE & BEARING (SN)	NOT NECESSARY	172.00	-
1	SET EXHAUST GASKET (SN)	NOT NECESSARY	52.00	-
			236.00	-
	<b><u>LABOUR</u></b>			
	TOWING FEE.	NOT NECESSARY	60.00	-
	REAR FRAME REPAIR.	NOT NECESSARY	250.00	-
	LABOUR CHARGE.		500.00	150.00
			810.00	150.00
	<b>GRAND TOTAL</b>		<b>12,442.70</b>	<b>1,086.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>850.00</b>
---	--	--	--	---------------

Report Ref No. CS3/SMO18014013/Dvd3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.