

INS. CASE OWNER:

CC 3, MG 1900

5795, JKA39

LKK:

IDAC:

Surveyor:

OHJ

DOI:

ASSIGNMENT

11/4/19

Date / Time:

11/4/19

Registered in Merimen:

11/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 1283R

Name of Insured:

ONG CHIN HONG

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :SS

D.O.A: 30/3/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SAD 6356T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Empy, un



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

9/1/19

11/4/19

10/14/2019

12/6/19

12/6/19

13/11/19

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

11/3/2020

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

SS 8,450

(11 - days)

Reduction:

78 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Lee

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

71

If NO or B 28, Ass. Lia:

OOI lost control

Repair Cost:

SS 8,450

Loss of Rental (LOR):

SS 1,605

(12 days)

X

\$133.95

Loss of Use (LOU):

SS

(5 - x - days)

Loss of Income (LOI):

SS

(5 - x - days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

SS 7.00

Medical:

SS -

Disbursement:

SS -

Legal Cost

SS -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

Total:

SS 10,062

Global Sum SS:

10,000

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 10,000

Name 1:

SMRT TAXIS

PTL10

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
21 Woodlands Industrial Park 11, Singapore 737709
Tax Number: 20443344
Company Registration Number: 4466363
Accident Reporting Number: 4466363
Date Submitted: 18/03/2019
Dear Sir: Feedback

Section A - Accident Details

Registration Number	SHD356T
Case Reference Number	TAX037192148
Registration Date	23/10/2018
Company Type	SMRT Taxi Pte Ltd
Make	TOYOTA
Model	PROJ2
Name of Driver	CHIN CHION LIANG
Type of Accident	Head to Rear
Accident Date and Time	30/3/2019 2:50 AM
Accident Reported Date and Time	30/3/2019 8:37 AM
Is Surveyor Required?	Yes
Surveyor	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/3/2019 4:34 AM
Replacement Vehicle Issued?	No
Job Card Number	24100834
Special Instruction to ARC, if any	TOWED: 390/AGG - LKK
Prepared Date and Time	1/4/2019 9:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



1/2/19

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,170.00	\$1,230.00
Total Spray Cost	\$4,812.00	\$1,230.00
Total Spare Part Cost	\$22,273.58	\$5,247.43
Total Other Cost	\$3,328.00	\$720.00
TOTAL COST	\$32,583.58	\$8,447.43
Lump Sum Total	\$32,600.00	\$8,460.00 (L/S)
Number of Repair Days	12.0	11.0
Prepared / Adjusted By	Tuck Foon Koh	Heee Jie (LKK) / AG
ARC / Surveyor Sign Off Date	01/04/2019 2:55 PM	01/04/2019 2:28 PM
Signature		
Remarks	Supplementary = 3 days	L/S REPAIR, PHOTO AFTER PAINT



SMRT Accident Vehicle Repair Estimates

SMRT Accessories Services Pte Ltd
60 Woodlands Industrial Park Ct, Singapore 737715
Fax Number: 65955552
Customer Telephone Number: 65955555
Insurance Company Number: 65955555

Date Generated: 14/09/2018
Page: 15 of 15

Section C - Quotation and Accident Invoice Details			
Quotation Number	QV-1909-0285	Invoice Number	
Quotation Date	18.09.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR TAIL LAMP PANEL	\$180.00	\$80.00
TO REPAIR REAR LH WHEEL HOUSE	\$300.00	\$180.00
TO REPAIR REAR PORTION	\$1,890.00	\$1,000.00
Total Labour	\$2,170.00	\$1,230.00
Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR MEMBER LH	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$100.00
TO RESPRAY TAIL LAMP PANEL LH	\$180.00	\$80.00
TO RESPRAY REAR LH FLOOR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER RH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER LH	\$180.00	\$0.00
TO RESPRAY REAR LH WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$240.00	\$50.00
TO RESPRAY FUEL LID COVER	\$180.00	\$20.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,812.00	\$1,280.00
Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$128.00	\$80.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00



SMART Accident Vehicle Repair Estimates

SMART Accident Services Pty Ltd
27 Woodlands Industrial Park St, Singapore 707705
Tel: 65-63550000
Company Registration Number: 200600017
Company Operating Number: 00000017

Date Generated: 14/05/2019
User ID: P0000001

TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$50.00
TO ALIGN CHASSIS	\$150.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO REMOVE LABOR & MATERIAL FOR SOLAR FILM (NET)	\$250.00	\$250.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$50.00
TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$30.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$40.00
TO REMOVE AND REFIT WIRE HARNESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$3,326.00	\$720.00

Part 4 - Spare Parts / Material Usage

Part Number	Partion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		33557	ANTENNA, ELECTRICAL	0.00	\$157.40	0.00	\$0.00	Replace	Check
		33670	LOWER REAR SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$50.00	0.00	\$100.00	Replace	Replace
		76086	BUMPER LIP COVER	0.00	\$72.25	0.00	\$0.00	Replace	Check
		47020	RR/LH						
		76087	BUMPER LIP COVER	0.00	\$118.10	0.00	\$0.00	Replace	Check
		47020	RR/RH						
		76891	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check
		47020							
		32682	BUMPER SEAL, RR LH	1.00	\$68.90	25.00	\$51.68	Replace	Replace
		47021							
		32576	BUMPER SIDE RETAINER	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		47020	RR/LH						
		32575	BUMPER SIDE RETAINER	0.00	\$94.80	0.00	\$0.00	Replace	Check
		47020	RR/RH						
		34308	UNDER COVER SUBASSY	0.00	\$514.50	0.00	\$0.00	Replace	Check
		47011	RR FLOOR						
		34327	EXHAUST HEAT SHIELD,	0.00	\$127.40	0.00	\$0.00	Replace	Check
		47020	REAR						
		17430	EXHAUST TAIL PIPE	0.00	\$658.20	0.00	\$0.00	Replace	Check
		37380							
		17386	SUPPORT, EXHAUST	0.00	\$33.60	0.00	\$0.00	Replace	Check
		32030	REAR						
		37009	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace
		47241							
		75574	TAIL GATE DOOR GLASS	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		47020	MOULDING, LH						
		75575	TAIL GATE DOOR GLASS	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		47080	MOULDING, RH						
		75576	MOULDING BACK	1.00	\$29.40	25.00	\$22.05	Replace	Replace
		47038	WINDOW LOWER NO.1						
		38117	DAM. BACK DOOR GLASS	1.00	\$27.30	25.00	\$20.48	Replace	Replace
		39149	ADHESIVE, NO.1						
		84821	TAILGATE LOWER	1.00	\$721.30	25.00	\$540.98	Replace	Replace
		47009	WINDOW GLASS						



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
67 Woodlands Industrial Park Dr, Singapore 757145
Tel: 6760 0000
Fax: 6760 0001
Email: enquiry@smrt.sg
Website: www.smrt.sg

Estimate Number: 1000000000
Estimate Date: 10/01/2010

	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	nec
52156-47905	BUMPER REAR	1.00	\$458.00	25.00	\$343.95	Replace	Replace	BR
52161-19010	BUMPER CLIP	10.00	\$1.61	25.00	\$12.08	Replace	Replace	nec
52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X
52016-47030	ARM SUB-ASSY, RR	0.00	\$139.50	0.00	\$0.00	Replace	Check	X
52016-47030	BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
52016-47030	ARM SUB-ASSY, RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
52016-47030	BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
88105-47122	TAILGATE DOOR GLASS	0.00	\$1,090.00	0.00	\$0.00	Replace	Not Given	X
88810-47010	TAILGATE DOOR HINGE L/RH	0.00	\$06.30	0.00	\$0.00	Replace	Not Given	X
88200-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	X
88985-0W532	TAILGATE DOOR STAY LH	0.00	\$241.00	0.00	\$0.00	Replace	Check	X
88985-0W542	TAILGATE DOOR STAY RH	0.00	\$241.00	0.00	\$0.00	Replace	Check	X
57681-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$253.40	0.00	\$0.00	Replace	Check	X
88415-47020	TAILGATE LOCK COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X
18861-47070-80	TAILGATE OUTSIDE CARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
89431-47010	STRUT, BACK DOOR	0.00	\$45.90	0.00	\$0.00	Replace	Check	X
87781-47040CB	TAILGATE TRIM LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	X
87780-47071CB	TAILGATE BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Check	X
82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	X
86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,438.00	0.00	\$0.00	Replace	Not Given	X
84840-28040	SWITCH ASSY, BACK DOOR OPENER	0.00	\$148.10	0.00	\$0.00	Replace	Check	X
76310-47020	EMBLEM REAR	1.00	\$60.10	25.00	\$45.23	Replace	Replace	nec
81271-52011	LICENSE PLATE LAMP	0.00	\$55.70	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
76374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	nec
75442-47030	NAME PLATE (P/US)	1.00	\$60.80	25.00	\$45.80	Replace	Replace	nec
75442-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	nec
76085-47810	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
91005-87211	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Check	X
	SMRT LOGO	1.00	\$7.60	0.00	\$7.60	Replace	Replace	nec
	STICKER DECAL ESSE ESSE	1.00	\$21.80	0.00	\$21.80	Replace	Replace	nec
58337-47260	END PANEL	0.00	\$802.10	0.00	\$0.00	Replace	Check	X
64719-4703180	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
64716-4703180	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X
68336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X
4506314	SEALANT SNAPLEJ	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
58311-47071	SPARE TYRE PANEL	0.00	\$687.70	0.00	\$0.00	Replace	Check	X
57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
58303-47301	FLOOR PANEL R/LH	0.00	\$122.00	0.00	\$0.00	Replace	Check	X
64993-87020	BOX DECK FLOOR, RR	0.00	\$546.70	0.00	\$0.00	Replace	Not Given	X



SMART Accident Vehicle Repair Estimates

SMART Automotive Services Pty Ltd
20 Woodlands Industrial Park Dr, Bayswater 107102
Toll Number: 1800 000 000
Company Taxation Number: 66600023
Insurance Licensing Number: 26660012

Form Numbered: 10000010
Last 5: 10000010

58415-47020B	BOX, RR FLOOR, BOARD	0.00	\$879.50	0.00	\$0.00	Replace	Not Given	X
58415-47000	BOARD, RR FLOOR	0.00	\$332.30	0.00	\$0.00	Replace	Not Given	X
58415-47020B	BOX, DECK FLOOR	0.00	\$230.10	0.00	\$0.00	Replace	Not Given	X
58467-47030	COVER LH	0.00	\$195.82	0.00	\$0.00	Replace	Not Given	X
58415-47020B	BOX, DECK FLOOR, LH	0.00	\$862.12	0.00	\$0.00	Replace	Not Given	X
58415-47020B	COVER ASSY, TONNEAU	0.00	\$250.80	0.00	\$0.00	Replace	Check	X
58415-47020B	CUSHION, SPARE WHEEL	0.00	\$143.70	0.00	\$0.00	Replace	Check	X
58415-47020B	PROTECTOR, SPARE	0.00	\$15.70	0.00	\$0.00	Replace	Check	X
58415-47020B	CARRIER, SPARE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
58415-47020B	TYRE	0.00	\$1430.20	0.00	\$0.00	Replace	Not Given	X
58415-47020B	WHEEL DISC	0.00	\$35.50	0.00	\$0.00	Replace	Check	X
58415-47020B	BREAKDOWN SIGN	0.00	\$1675.00	0.00	\$0.00	Replace	Check	X
58415-47020B	PANEL ASSY, DECK LH	0.00	\$1305.40	0.00	\$0.00	Replace	Not Given	X
58415-47020B	WIRE, FLOOR	0.00	\$558.40	0.00	\$0.00	Replace	Check	X
58415-47020B	WIRE, FLOOR, NO 2	0.00	\$326.70	0.00	\$0.00	Replace	Check	X
58415-47020B	PANEL SUB-ASSY, QTR WHEEL HOUSE	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
58415-47020B	PANEL, QUARTER WHEEL HOUSE, OUTER LH	0.00	\$348.40	10.00	\$493.58	Replace	Replace	X
58415-47020B	TAIL LAMP BRACKET, LH	0.00	\$110.60	0.00	\$0.00	Replace	Check	X
58415-47020B	TAIL LAMP, LH	1.00	\$788.80	25.00	\$375.10	Replace	Replace	X
58415-47020B	TROUGH, BACK DOOR LH	0.00	\$7.50	0.00	\$7.50	Replace	Replace	X
58415-47020B	FENDER RRLH	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
58415-47020B	SMART LOGO	1.00	\$141.30	0.00	\$0.00	Replace	Check	X
58415-47020B	STICKER DECAL 8555 AAAA	1.00	\$65.90	0.00	\$0.00	Replace	Check	X
58415-47020B	FENDER LINER RRLH	0.00	\$152.00	100.00	\$0.00	Replace	Repair	X
58415-47020B	LID ASSY, FUEL	0.00	\$63.90	0.00	\$0.00	Replace	Check	X
58415-47020B	CABLE SUB-ASSY, FUEL LID	0.00	\$5.90	0.00	\$0.00	Replace	Check	X
58415-47020B	RETAINER, FUEL LID	0.00	\$08.10	0.00	\$0.00	Replace	Not Given	X
58415-47020B	CABLE	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
58415-47020B	CAP ASSY, FUEL TANK	0.00	\$36.10	0.00	\$0.00	Replace	Check	X
58415-47020B	PIPE SUB-ASSY, FUEL NECK	0.00	\$743.10	0.00	\$0.00	Replace	Check	X
58415-47020B	TUBE, FUEL TANK	0.00	\$168.10	25.00	\$125.58	Replace	Replace	X
58415-47020B	TANK SUB-ASSY, FUEL	0.00	\$37.00	0.00	\$0.00	Replace	Replace	X
58415-47020B	QUARTER GLASS RRLH	1.00	\$126.74	0.00	\$0.00	Replace	Replace	X
58415-47020B	SEALANT W/SCREEN	1.00	\$126.74	0.00	\$0.00	Replace	Replace	X
58415-47020B	TYRE	1.00	\$126.74	0.00	\$0.00	Replace	Replace	X
58415-47020B	WHEEL DISC	1.00	\$30.70	0.00	\$0.00	Replace	Check	X
58415-47020B	TAIL LAMP BRACKET, RH	0.00	\$567.50	0.00	\$0.00	Replace	Not Given	X
58415-47020B	TAIL LAMP, RH	0.00	\$116.90	0.00	\$0.00	Replace	Check	X
58415-47020B	TROUGH, BACK DOOR	0.00	\$756.90	0.00	\$0.00	Replace	Not Given	X
58415-47020B	FENDER RRLH	0.00	\$7.50	0.00	\$0.00	Replace	Not Given	X
58415-47020B	SMART LOGO	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
58415-47020B	STICKER DECAL 8555 AAAA	0.00	\$554.50	100.00	\$0.00	Replace	Repair	X
58415-47020B	DOOR RRLH	1.00						



SMRT Accident Vehicle Repair Estimates

SMRT Insurance Services Pte Ltd
41 Northshore Industrial Park S.S. Singapore 137071
Fax Number: 6880000
Company Telephone Number: 6880001
Accident Reporting Number: 9880012

Date Submitted: 14/05/04
User ID: P000001

	89080-47080	DOOR LOCK RR/LH	0.00	\$709.30	0.00	\$0.00	Replace	Check	X
	65410-33018	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Check	Y
	88780-20122	DOOR HINGE UPPER RR/LH	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X
	88780-37021	DOOR HINGE LOWER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	Y
	88630-47031	CHECKASSY. RR DOOR	0.00	\$190.30	0.00	\$0.00	Replace	Check	X
Total				\$31,491.09		\$3,874.32			
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		58311-47071	SPARE TYRE PANEL	1.00	\$687.70	25.00	\$515.78	Replace	Replace
		58303-47301	FLOOR PANEL RR/LH	1.00	\$102.50	25.00	\$76.88	Replace	Replace
		78087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
		38306-47011	UNDER COVER BUMASSY RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace
		84718-4703180	END PANEL COVER, DECK, TRIM HOLE	1.00	\$48.10	25.00	\$36.08	Replace	Replace
		84718-4703180	END PANEL COVER, DECK, TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace
		57854-47020	MEMBER SUB-ASSY. RR LH	1.00	\$174.10	25.00	\$130.58	Replace	Replace
		58307-47080	END PANEL	1.00	\$802.10	25.00	\$601.58	Replace	Replace
		78891-47020	BUMPER LIP REAR	1.00	\$228.50	25.00	\$171.38	Replace	Replace
		78088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace
		52018-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$136.80	25.00	\$102.60	Replace	Replace
		52018-47030	ARM SUB-ASSY. RR BUMPER RH	1.00	\$139.80	25.00	\$104.70	Replace	Replace
		52023-12340	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52876-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		87881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace
Total					3,878.90		2,884.97		

6559.24

20%

5242.43

+ 1230.00

+ 1970.00

8442.43

1/5 \$84.01-

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Case Details

Case Reference Number : TX003192148
 Type of Repair : Accident Repair
 Vehicle Registration Number : SH000087

Company Type : SMRT Taxi Pte Ltd
 Estimation ID : EST-0298-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 29/03/2018 06:00 PM
 Vehicle Age(In Months) : 41

Documents / Photographs

[View Documents / Photographs](#) Zero Documents

Estimation Details

Items Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
Item Type	Coating Type	Partion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Unit/No	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Wash			ANTENNA ELECTRICAL LOWER REAR	1	187.80	187.80	10.00	141.84	Replace	0	0	Check	X NN
One Time Key In	Wash			SENSOR REVERSE	1	186.00	186.00	5.00	186.00	Replace	1	186.00	Replace	/ BR
One Time Key In	Wash			HEEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ MR
One Time Key In	Wash			BUMPER LIP COVER FRONT	1	72.00	72.00	0.00	64.71	Replace	0	0	Check	X NN
One Time Key In	Wash			BUMPER LIP COVER REAR	1	118.50	118.50	0.00	68.07	Replace	0	0	Check	X NN
One Time Key In	Wash			BUMPER LIP REAR	1	228.00	228.00	0.00	171.84	Replace	0	0	Check	X NN
One Time Key In	Wash			BUMPER SEAL, RS LH	1	55.00	55.00	0.00	55.00	Replace	1	55.00	Replace	/ CR4
One Time Key In	Wash			BUMPER SIDE RETAINER RSLH	1	64.00	64.00	0.00	71.70	Replace	1	71.70	Replace	/ BR
One Time Key In	Wash			BUMPER SIDE RETAINER RSRH	1	64.00	64.00	0.00	71.70	Replace	0	0	Check	X NN
One Time Key In	Wash			WIPER COVER SUSPENT, RS FLOOR	1	514.00	514.00	0.00	368.00	Replace	0	0	Check	X NN
One Time Key In	Wash			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	0.00	65.04	Replace	0	0	Check	X NN

Total Spare Part Cost: 20,125.84

Lump Sum Discount (%) 25.00

Final Spare Part Cost: 15,104.40

Surveyor Total: 3,874.24

Lump Sum Dis (%) 25

Final Sur Total: 2,905.68

4/1/2019

https://vacswest.amt.com.sg/Estimation.aspx

SPARE Recommendation										Surveyor Approval		
QOM Type	Costing Type	Part Name	Qty	Unit Price	Unit Price	Qty (%)	Final Price	Replace	Surveyor Quantity	Surveyor Final Price	Replace/Repair	Remarks
One Time Key In	Man	EXHAUST TAIL PIPE	1	555.21	555.21	25.00	492.14	Replace	2	2	Check	X NAI
One Time Key In	Man	SUPPORT, EXHAUST REAR	2	22.80	27.20	25.00	52.80	Replace	2	2	Check	X NAI
One Time Key In	Man	TAILGATE KEY	1	1,007.90	1,007.90	15.00	755.93	Replace	1	755.93	Replace	/ DO
One Time Key In	Man	TAILGATE DOOR GLASS MOLDING, LH	1	22.05	22.05	15.00	22.05	Replace	1	22.05	Replace	/ MC
One Time Key In	Man	TAILGATE DOOR GLASS MOLDING, RH	1	22.05	22.05	15.00	22.05	Replace	1	22.05	Replace	/ MC
One Time Key In	Man	MOLDING BACK WINDOW, LOWER NO.1	1	22.05	22.05	15.00	22.05	Replace	1	22.05	Replace	/ MC
One Time Key In	Man	BACK DOOR GLASS ADHESIVE, NO.1	1	27.20	27.20	15.00	20.48	Replace	1	20.48	Replace	/ MC
One Time Key In	Man	TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.98	Replace	1	540.98	Replace	/ GR
One Time Key In	Man	SEALANT W/SCREEN	2	27.20	111.20	1.00	111.20	Replace	2	111.20	Replace	/ MC
One Time Key In	Man	BUMPER REAR	1	432.90	432.90	15.00	343.95	Replace	1	343.95	Replace	/ BR
One Time Key In	Man	BUMPER CLIPS	10	1.20	15.18	15.00	12.08	Replace	10	12.08	Replace	/ MC
One Time Key In	Man	BUMPER REINFORCEMENT REAR	1	205.75	205.75	15.00	154.27	Replace	2	2	Check	X NAI
One Time Key In	Man	ARM SUB-ASSEMBLY, RE BUMPER LH	1	126.60	126.60	15.00	104.75	Replace	2	2	Check	X NAI
One Time Key In	Man	ARM SUB-ASSEMBLY, RE BUMPER RH	1	126.60	126.60	15.00	104.75	Replace	2	2	Check	X NAI
One Time Key In	Man	TAILGATE DOOR GLASS	1	1,000.00	1,000.00	15.00	819.74	Replace	2	2	Not Give	X NAI
One Time Key In	Man	TAILGATE DOOR HINGE LATCH	2	58.30	116.60	15.00	87.35	Replace	2	2	Not Give	X NAI

Total Spare Part Cost 22,187.04

Surveyor Total 2,874.26

Lump Sum Discount (%) 25.00

Lump Sum SW (%) 25

Final Spare Part Cost 22,126.82

Final SW Total 2,899.41

https://vacswest.amt.com.sg/Estimation.aspx

2/19

4/1/2019

https://vacweb.smt.com.sg/Estimation.aspx

SMT Recommendation													Surveyor Approval		
QDR Type	Quoting Type	Partion	Material Number	Part Name	Qty	Unit Price Per Unit	Unit Price	Unit Price	Final Price	Request Replace	Surveyor Quantity	Surveyor Final Price	Request/Replace	Remarks	
One Time Key In	Man			TAILGATE DOOR LOCK	1	444.15	444.15	25.00	322.08	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE DOOR STRAP LN	1	241.80	241.80	25.00	181.12	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE DOOR STRAP BR	1	181.30	181.30	25.00	141.12	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE DOOR WEATHER STRIP	1	255.80	255.80	25.00	205.80	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE LOCK COVER	5	15.75	15.75	25.00	11.77	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			TAILGATE OUTSIDE SAMBHA	1	344.80	344.80	25.00	274.87	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			STRIKER, BACK DOOR	1	45.00	45.00	25.00	35.87	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	130.22	Replace	0	0	Check	X N/A	
One Time Key In	Man			TAILGATE, GARD ASBY	1	245.80	245.80	25.00	190.18	Replace	0	0	Check	X N/A	
One Time Key In	Man			WIRE, BACK DOOR, NO.1	1	322.40	322.40	25.00	224.15	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			CAMERA ASBY, TELEVISION, BR	1	1,836.00	1,836.00	10.00	1,280.94	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			SWITCH ASBY, BACK DOOR OPENER	1	146.10	146.10	10.00	121.45	Replace	0	0	Check	X N/A	
One Time Key In	Man			WHEEL REAR	1	60.30	60.30	25.00	42.22	Replace	1	45-33	42/3	Replace	X N/A
One Time Key In	Man			LICENSE PLATE LOCK	2	20.75	11.40	10.00	64.28	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	X N/A	
One Time Key In	Man			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	X N/A	

Total Spare Part Cost 25,157.34

Lump Sum Discount (%) 20.00

Final Spare Part Cost 20,125.87

Surveyor Total 2,874.26

Lump Sum Dis (%) 20

Final Sur Total 2,299.41

https://vacweb.smt.com.sg/Estimation.aspx

3/10

PARTY Recommendation										Surveyor Approval				
QOM Type	Coating Type	Purpose	Material Number	Part Name	Qty	Unit Price Per (MTR)	Unit Price (MTR)	Dis (%)	Total Price (S)	Report Replace	Surveyor Quantity	Surveyor Unit Price (S)	Report/Replace	Remarks
One Time Rep	Matn			NAME PLATE (175000)	1	11.00	11.00	35.00	11.00	Replace	1	38.43 38.73	Replace	/ MC
One Time Rep	Matn			NAME PLATE (175000)	1	45.00	45.00	35.00	45.00	Replace	1	45.00 45.60	Replace	/ MC
One Time Rep	Matn			NAME PLATE (175000)	1	51.00	51.00	35.00	51.00	Replace	1	38.43 38.73	Replace	/ MC
One Time Rep	Matn			SHOULDER REAR	1	602.00	602.00	35.00	710.20	Replace	0	0	Not Done	X N/A
One Time Rep	Matn			END BRAKE LAMP	1	207.00	207.00	35.00	207.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			EMPTY LOGO	1	7.00	7.00	35.00	7.00	Replace	1	7.00 7.50	Replace	/ MC
One Time Rep	Matn			STICKER DECAL 8000 8000	1	21.00	21.00	35.00	21.00	Replace	1	21.00 21.60	Replace	/ MC
One Time Rep	Matn			END PANEL	1	602.00	602.00	35.00	602.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			END PANEL COVER, DOOR TRIM HOLE	1	40.00	40.00	35.00	40.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			END PANEL COVER, DOOR TRIM, RH	1	121.00	121.00	35.00	90.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			REINFORCEMENT, RH	2	30.00	60.00	35.00	61.00	Replace	0	0	Check	X N/A
One Time Rep	Matn		400014	SEALANT SKAFLEX	1	27.00	27.00	35.00	27.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			SPARE TYRE PANEL	1	607.00	607.00	35.00	607.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			MEMBER SUB-ASSY, RH LH	1	174.00	174.00	35.00	130.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			MEMBER SUB-ASSY, RH RH	1	174.00	174.00	35.00	130.00	Replace	0	0	Check	X N/A
One Time Rep	Matn			FLOOR PANEL, RSLR	1	102.00	102.00	35.00	79.00	Replace	0	0	Check	X N/A

Total Spare Part Cost 25,157.04

Surveyor Total 3,879.28

Lump Sum Discount (%) 35.00

Lump Sum Dis (%) 35

Final Spare Part Cost 25,128.83

Final Sur Total 3,289.81

SMT Recommendation													Surveyor Approval		Remarks
QCR Type	Coating Type	Partion	Material Number	Part Name	Qty	Unit Price Per (Unit)	Unit Price (USD)	Qty (%)	Final Price (USD)	Request Replace	Surveyor Quantity	Surveyor Final Price (USD)	Request/Replace		
One Time Key In	Mask			BOX, DECK FLOOR, RR	1	448.70	448.70	25.00	448.70	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			BOX, RR FLOOR, SGARD	1	475.40	475.40	25.00	475.70	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			SGARD, RR FLOOR	1	300.20	300.20	25.00	294.20	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			BOX, DECK FLOOR, COVER LH	1	200.14	200.14	25.00	175.37	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			BOX, DECK FLOOR, LH	1	146.80	146.80	25.00	147.80	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			COVER ASSEY, TOWNEAU	1	805.10	805.10	25.00	491.34	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			CUSHION, SPARE WHEEL	1	200.00	200.00	25.00	175.16	Replace	0	0	Check	X N/A	
One Time Key In	Mask			PROTECTOR, SPARE	1	142.70	142.70	25.00	100.77	Replace	0	0	Check	X N/A	
One Time Key In	Mask			CARRIER, SPARE	1	16.70	16.70	25.00	14.77	Replace	0	0	Check	X N/A	
One Time Key In	Mask		400707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			WHEEL, DISC	1	1,490.00	1,490.00	25.00	1,177.80	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			BREAKDOWN BOX	1	20.00	20.00	0.00	20.00	Replace	0	0	Check	X N/A	
One Time Key In	Mask			PANEL ASSEY, DECK LH	1	307.00	307.00	0.00	307.00	Replace	0	0	Check	X N/A	
One Time Key In	Mask			WIRE, FLOOR	1	1,075.00	1,075.00	10.00	1,507.00	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			WIRE, FLOOR, NO 2	1	1,260.40	1,260.40	10.00	1,174.00	Replace	0	0	Not Done	X N/A	
One Time Key In	Mask			PANEL SUB-ASSEY, DTR WHEEL HOUSE	1	388.40	388.40	25.00	441.30	Replace	0	0	Check	X N/A	

Total Spare Part Cost 26,197.00

Surveyor Total 5,674.26

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,135.40

Final Sur Total 5,099.47

4/15/2018

https://vacswb.smt.com.sg/Estimation.aspx

SMT Recommendation										Surveyor Approval			
QSR Type	Coating Type	Partion	Material Number	Part Name	Qty	QSR Price Per Unit	Unit Price	Est Price	Final Price	Report Replace	Surveyor Quantity	Surveyor Final Price	Remarks
One Time Only	Mask			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	324.70	324.70	33.30	340.02	Replace	0	0	Check - X NAI
One Time Only	Mask			TAIL LAMP BRACKET, LH	1	30.70	30.70	35.00	33.00	Replace	0	0	Check - X NAI
One Time Only	Mask			TAIL LAMP LH	1	648.00	648.00	11.00	460.00	Replace	1	460.00	403.50 Replace - B / BR
One Time Only	Mask			THROCK, BACK DOOR LH	1	110.00	110.00	30.00	80.00	Replace	0	0	Check - X NAI
One Time Only	Mask			FENDER BRUSH	1	168.00	168.00	25.00	275.10	Replace	1	275.10	575.10 Replace - / DD
One Time Only	Mask			SWRT LOGO	1	7.00	7.00	0.00	7.00	Replace	0	7.00	1.00 Replace - / MC
One Time Only	Mask			STICKER DECAL 8000 8000	1	21.00	21.00	0.00	21.00	Replace	0	21.00	21.00 Replace - / MC
One Time Only	Mask			FENDER LINER BRUSH	1	141.00	141.00	30.00	100.00	Replace	0	0	Check - X NAI
One Time Only	Mask			LID ASSY, FUEL	1	100.00	100.00	35.00	16.00	Replace	1	0	Report - X R
One Time Only	Mask			CABLE SUB-ASSY, FUEL LH	1	65.00	65.00	30.00	41.00	Replace	0	0	Check - X NAI
One Time Only	Mask			RETAINER, FUEL LID COILS	1	0.00	0.00	30.00	4.00	Replace	0	0	Check - X NAI
One Time Only	Mask			CAP ASSY, FUEL TANK	1	66.10	66.10	30.00	30.00	Replace	0	0	Not Done - X NAI
One Time Only	Mask			PIPE SUB-ASSY, FUEL NOCK	1	200.00	200.00	25.00	175.10	Replace	0	0	Check - X NAI
One Time Only	Mask			TUBE, FUEL TANK	1	26.10	26.10	25.00	27.00	Replace	0	0	Check - X NAI
One Time Only	Mask			TANK SUB-ASSY, FUEL	1	140.10	140.10	30.00	100.00	Replace	0	0	Check - X NAI
One Time Only	Mask			QUARTER GLASS PANEL	1	100.10	100.10	30.00	100.00	Replace	1	100.00	100.00 Replace - / MC

Total Spare Part Cost 20,107.04

Surveyor Total 1,879.20

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 20,107.04

Final Sur Total 1,879.20

https://vacswb.smt.com.sg/Estimation.aspx

6/10

4/1/2018

https://vaceweb.smt.com.sg/Estimation.aspx

SMT Recommendation										Surveyor Approval				
QTY	Coating Type	Part No.	Material Number	Part Name	Qty	List Price	List Price(\$)	Qty(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Mask			EXHAUST SCREEN	1	21.00	21.00	0.00	21.00	Replace	1	21.00	Replace	✓ OK
One Time Key In	Mask		880707	TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	✓ TN
One Time Key In	Mask			WHEEL SHC	1	1,490.20	1,490.20	0.00	1,117.65	Replace	1	0	Repair	✗ R
One Time Key In	Mask			TAIL LAMP BRACKET, RH	1	30.70	30.70	0.00	30.00	Replace	0	0	Check	✗ NA
One Time Key In	Mask			TAIL LAMP RH	1	337.80	337.80	0.00	332.00	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			TRUCKS BACK DOOR	1	110.90	110.90	0.00	99.14	Replace	0	0	Check	✗ NA
One Time Key In	Mask			FENDER RUSH	1	709.80	709.80	0.00	576.10	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			SWRT LOCK	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			STICKER DECAL 8550 8550	1	21.80	21.80	0.00	21.64	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			DOOR RSLH	1	504.00	504.00	0.00	716.88	Replace	1	0	Repair	✗ R
One Time Key In	Mask			DOOR LOCK RSLH	1	196.00	196.00	0.00	191.97	Replace	0	0	Check	✗ NA
One Time Key In	Mask			DOOR LOCK STICKER	1	40.50	40.50	0.00	36.00	Replace	0	0	Check	✗ NA
One Time Key In	Mask			DOOR HINDE UPPER RSLH	1	81.70	81.70	0.00	81.28	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			DOOR HINDE LOWER RSLH	1	70.00	70.00	0.00	64.10	Replace	0	0	Not Give	✗ NA
One Time Key In	Mask			CHECK ASSY, RR DOOR	1	100.00	100.00	0.00	112.70	Replace	0	0	Check	✗ NA

Total Spare Part Cost 25,107.04

Surveyor Total 2,074.28

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 25,107.04

Final Sur Total 2,074.28

WOMEN'S COS (2018)

S.No.

Coating Type

Job Scope

SMT Recommendation(S)

Surveyor Adjustment(S)

Remarks

https://vaceweb.smt.com.sg/Estimation.aspx

7/10



<https://vacoweb.smt.com.sg/Estimation.aspx>

S.No.	Coating Type	Job Scope	SMT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Repaint	TO REPAIR REAR PORTION	1,000.00	1,000	✓ 1,000
Total			1,000.00	1,000.00	

Body Coat Detail

S.No.	Coating Type	Job Scope	SMT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Repaint	TO REPAINT REAR SLAMPER	275.00	200	✓ 200
2	Repaint	TO REPAINT TAILGATE OUTSIDE BARNISH	180.00	0	
3	Repaint	TO REPAINT TAIL GATE	275.00	200	✓ 200
4	Repaint	TO REPAINT REAR SPOILER	180.00	0	
5	Repaint	TO REPAINT REAR PANEL	180.00	0	
6	Repaint	TO REPAINT REAR QUARTER TIRE PANEL	180.00	0	
7	Repaint	TO REPAINT REAR MEMBER RH	180.00	0	
8	Repaint	TO REPAINT REAR MEMBER LH	180.00	0	
9	Repaint	TO REPAINT REAR LH WHEEL HOUSE	180.00	0	
10	Repaint	TO REPAINT REAR FLOOR SIDE PANEL LH	180.00	0	
11	Repaint	TO REPAINT RH	240.00	50	✓ 50
12	Repaint	TO REPAINT FUEL LID COVER	180.00	20	✓ 20
13	Repaint	TO REPAINT THROUGH BACK DOOR LH	180.00	0	
14	Repaint	TO REPAINT REAR FRONTS LH	275.00	200	✓ 200
15	Repaint	TO REPAINT REAR FENDER RH	275.00	0	
16	Repaint	TO REPAINT THROUGH BACK DOOR RH	180.00	0	
Total			3,750.00	375.00	✓ 610

Other Coat Detail

S.No.	Coating Type	Job Scope	SMT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Paint	TO PAINT CHASSIS	120.00	90	✓ 90
2	Paint	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ 20
Total			2,000.00	120.00	

<https://vacoweb.smt.com.sg/Estimation.aspx>

4/10/2019

https://vacsweb.smart.com.sg/Estimation.aspx

SL No.	Estimate Type	Job Scope	BSMT Recommendation(S)	Surgeon Adjustment(S)	Remarks
1	Man	TO APPLY FOOT PROOFING ON WHEELS & AXES	200.00	30 Mc ✓	
2	Man	TO DO WHEEL ALIGNMENT / TYRE BALANCING	100.00	0	
3	Man	TO REMOVE & REFIT SEAT	100.00	50 Mc ✓	
4	Man	TO ALIGN CHASSIS	200.00	0	
5	Man	TO REMOVE & REFIT FUEL TANK	100.00	0	
6	Man	TO REMOVE & REFIT EXHAUST	100.00	0	
7	Man	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM ACT.	250.00	250 Mc ✓	
8	Man	TO TRANSFER REAR FALSBATE MECHANISM	100.00	50 Mc ✓	
9	Man	TO TEST AND RETRY REVERSE SENSOR SYSTEM	100.00	20 Mc ✓	
10	Man	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRAY TO FACILITATE REPAIR	100.00	50 Mc ✓	
11	Man	TO INSPECT WIR LIGHTING MECHANISM & WATER TEST AIR LIGHTING FOR LEAKAGE	100.00	30 Mc ✓	
12	Man	TO REMOVE AND REFIT TRIM BOLT (ORNAMENT PURPOSE)	200.00	20 Mc ✓	
13	Man	TO CHECK & RESET SYSTEM FUNCTION	200.00	0	
14	Man	TO REMOVE AND REFIT REAR WINDSCREEN	200.00	60 Mc ✓	
15	Man	TO REMOVE & REFIT REAR QUARTER GLASS LH	100.00	40 Mc ✓	
16	Man	TO REMOVE AND REFIT WIRE HARNESS	200.00	0	
17	Man	TO REPLACE SLUSHY HATTE	100.00	0	
18	Man	TO WASH AND VACUUM	50.00	0	
Total			3,328.00	430.00	✓

Summary

	Estimate Assessment(S)	Surgeon Assessment(S)
Total Spare Part Cost	20,125.00	1,000.00
Total Labour Cost	1,000.00	1,000.00
Total Survey Parking	2,000.00	600.00
Other	2,000.00	500.00
Grand Total	25,125.00	3,100.00

https://vacsweb.smart.com.sg/Estimation.aspx

9/10

Downloaded from ascelibrary.org by University of California, San Diego on 07/06/16. Copyright ASCE, For All Rights Reserved, No part of this document may be reproduced without written permission from ASCE.

LKX Agent's Consent: I/We hereby notify the Registrar of the following:

- To receive all monies being sent;
- To place all monies in a trust for recovery;
- To provide all necessary information;
- To provide all "Without Prejudice" basis;
- To keep all monies in a safe place;
- To provide all necessary information to the Registrar and to the Insurance Company.

Authorized by Registrar:

Signature: _____

Date: _____

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TRX/03/19/2146	Date of Collection	2/4/19
Vehicle No	SHD 6356 T	Date of Request	5/4/15
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	3 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	9446, 99, 9000	Bumper Lip cover RR LH		\$ 72.20 ✓
2	9001, 02, 103	Bumper Lip cover RR RH		\$ 118.10 ✓
3	9004, 05, 06	Bumper Lip Rear		\$ 228.90 ✓
4	9007, 08, 09, 10	Bumper Side Retainer RR LH		\$ 94.80 ✓
5	9012, 13, 14	Under cover Sub Assy RR floor		\$ 514.50 ✓
6	9015, 16, 17, 25, 26	Bumper Reinforcement Rear		\$ 205.70 ✓
7	9021, 22, 27, 28	Arm Sub Assy RR Bumper LH	\$ 194.70	\$ 139.60 ✓
8	9023, 24, 29, 30	Arm Sub Assy RR Bumper RH		\$ 139.60 ✓

CUT \$54.15
 CRA \$88.58
 CUT \$71.68
 CRA \$71.10
 BUL \$705.98
 OD \$154.70
 BT \$130.58
 BT \$194.70

<<<Please submit photographs for damaged parts>>>

I (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle

Chia

Signature of person making this declaration

(To be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMART Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMART Staff

①

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	702/03/19/2146	Date of Collection	2/4/19
Vehicle No	SHD 6356 T	Date of Request	5/4/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	905,74,20	Tail Gate Door Weatherstrip		#353.40	✓
2	9063,104,105	End Panel Cover Deck Trim Left		#46.10	✓
3	9059,40,41,42	End Panel Cover Deck trim RR		#121.10	✓
4	9039,60,61	Member Sub Assy RR LH		#174.10	✓
5	9046,47,48	Rear LH Floor Panel		#185.90	✓
6	9021,32,33,34,35	End Panel		#602.10	✓
7	9062,63,64,65,66,67	Spare Tyre Panel		#667.70	✓
8	9036,37,38	To Repair Tail Lamp Panel		#120.00	✓

265.05

CUT \$165.00

CRA \$34.58

SLR \$90.13

BUC \$100.58

BUC \$76.50

BUC \$451.58

BUC \$500.78

#80

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle

Chia

Signature of person making this declaration

(To be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

2

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	748/03/19/2146	Date of Collection	2/4/19
Vehicle No	SHD 6356T	Date of Request	5/4/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	9855, 56, 57	To Repair Rear LH wheel House	1	150.00	\$150
2		To Repair Rear Panel	1	100.00	\$100
3		To Repair Spare Tyre Panel	1	100.00	\$100
4		To Repair Rear Member LH	1	100.00	\$100
5		To Repair Rear LH wheel House	1	100.00	\$100
6		To Repair Rear LH Floor Panel	1	100.00	\$100
7		To Repair Rear LH Tail Lamp Panel	1	80.00	\$80
8					

<<<Please submit photographs for damaged parts>>>

8/4/19

I (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorized witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

②

4/1/2019

https://vacsweb.smrt.com.sg/Estimation.aspx



Case Details

Case Reference Number : TAX03/19/2146
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6356T

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-6298-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 29/03/2019 06:50 PM
Vehicle Age(In Months) : 41

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	*
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	*
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	*
One Time Key In	Main			BUMPER LIP COVER R/LH	1	72.20	72.20	28.00	54.16	Replace	0	0	Check	*
One Time Key In	Main			BUMPER LIP COVER R/RH	1	118.10	118.10	28.00	86.37	Replace	0	0	Check	*
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Check	*
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	*
One Time Key In	Main			BUMPER SIDE RETAINER R/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	*
One Time Key In	Main			BUMPER SIDE RETAINER R/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	*
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	*
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check	*
Total Spare Part Cost									25,157.04	Surveyor Total				3,874.26
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				20
Final Spare Part Cost									20,125.63	Final Sur Total				3,099.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Check	*
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	*
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	*
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	*
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	*
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	*
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	*
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	*
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	*
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	0	0	Not Give	*
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	*
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.28				
Lump Sum Discount (%)									20.00	Lump Sum Disa (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	*
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	304.90	304.90	25.00	228.67	Replace	0	0	Not Give	*
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	*
One Time Key In	Main			TAILGATE BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	*
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	*
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Not Give	*
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0	Check	*
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	*
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	0	0	Not Give	*
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	*
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	*
Total Spare Part Cost									25,157.04	Surveyor Total		3,674.26		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									20,125.63	Final Sur Total		3,099.41		

SMRT Recommendation											Surveyor Approval			
EDM Type	Ceiling Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	*
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.60	60.60	25.00	45.60	Replace	1	45.60	Replace	*
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	*
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	*
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Check	*
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	*
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	*
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	*
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	*
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	*
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	*
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	*
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	*
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	*
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	*
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	*
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.26				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BOX, DECK FLOOR, RR	1	849.70	849.70	25.00	487.28	Replace	0	0	Not Give	*
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	*
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give	*
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Not Give	*
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Not Give	*
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	*
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	*
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check	*
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check	*
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	*
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	*
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check	*
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	0.00	307.00	Replace	0	0	Check	*
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	*
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give	*
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	*
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.28				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	*
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	*
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.56	Replace	*
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	*
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	*
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	*
One Time Key In	Main			STICKER DECAL 8555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	*
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	*
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	1	0	Repair	*
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	*
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	*
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	25.00	51.07	Replace	0	0	Not Give	*
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	*
One Time Key In	Main			TUBE, FUEL TANK	1	26.10	26.10	25.00	27.08	Replace	0	0	Check	*
One Time Key In	Main			TANK SUB-ASSY, FUEL	1	745.10	745.10	25.00	558.83	Replace	0	0	Check	*
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	*
Total Spare Part Cost									25,157.04	Surveyor Total		3,874.26		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									20,128.83	Final Sur Total		3,099.41		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unr(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	*
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	*
One Time Key In	Main			WHEEL DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	1	0	Repair	*
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	*
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	*
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	*
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	*
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	*
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	*
One Time Key In	Main			DOOR RRLH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	*
One Time Key In	Main			DOOR LOCK RRLH	1	709.30	709.30	25.00	531.97	Replace	0	0	Check	*
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Check	*
One Time Key In	Main			DOOR HINGE UPPER RRLH	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	*
One Time Key In	Main			DOOR HINGE LOWER RRLH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	*
One Time Key In	Main			CHECK ASSY, RH DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check	*
Total Spare Part Cost									25,157.04	Surveyor Total		3,874.28		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									20,125.63	Final Sur Total		3,098.41		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	1,000	
Total:			1,690.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY REAR SPOILER	180.00	0	
5	Main	TO RESPRAY REAR PANEL	180.00	0	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
7	Main	TO RESPRAY REAR MEMBER RH	180.00	0	
8	Main	TO RESPRAY REAR MEMBER LH	180.00	0	
9	Main	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
11	Main	TO RESPRAY RIM	240.00	50	
12	Main	TO RESPRAY FUEL LID COVER	180.00	20	
13	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
14	Main	TO RESPRAY REAR FENDER LH	378.00	200	
15	Main	TO RESPRAY REAR FENDER RH	378.00	0	
16	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
Total:			3,732.00	670.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	125.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
Total:			3,326.00	630.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE / REFIT SEAT	120.00	50	
6	Main	TO ALIGN CHASSIS	350.00	0	
7	Main	TO REMOVE & REFIT FUEL TANK	120.00	0	
8	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250	
10	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	
11	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
12	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	50	
13	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	
14	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30	
15	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
16	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	60	
17	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	40	
18	Main	TO REMOVE AND REFIT WIRE HARNESS	250.00	0	
19	Main	TO REPLACE SUNDRY PARTS	100.00	0	
20	Main	TO WASH AND VACUUM	60.00	0	
Total:			3,326.00	630.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	20,125.63	3,098.41
Total Labour Cost	1,690.00	1,000.00
Total Spray Painting	3,732.00	670.00
Other	3,326.00	630.00
Overall Total	28,873.63	5,398.41

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Repair Option		
Lump Sum Total	28,650.00	5,400.00
Surveyor Approved Amount		5,400.00
No of Repair Days*	12	9
Remarks		L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee Jie
Signature		
Survey Date	01/04/2019	

LKK Auto Care Centre hence notify the Repaired Party following:

- To resurvey for the body painting
- To discontinue any further resurvey
- Parts or materials provided confirmation
- Third party claim to be on "Without Prejudice" basis
- No illegal work to be allowed
- Supplier to be notified and resurveyed and is subject to the LKK Auto Care Insurance Company

Acknowledged by Reparer

Signature:

Date:

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Apr 2019 15:06	Cim Dtl Modified	Claimant's Name: -> SMRT TAXIS PTE LTD. Claimant's ID: -> 198905369K.	[A] HOW MEI KWAN
2	02 Apr 2019 15:06	Cim Veh Model Changed	(204897) TOYOTA PRIUS TAXI 1.8 (A).	[A] HOW MEI KWAN
3	02 Apr 2019 15:06	Cim Created	Reg No: SHD6356T, Acct Date: 2019/03/30, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Lt d. (SG), TP Insurer: MS First Capital Insurance Ltd (HQ), Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[A] HOW MEI KWAN
4	02 Apr 2019 15:06	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	02 Apr 2019 15:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/11	[A] HOW MEI KWAN
6	02 Apr 2019 15:06	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	02 Apr 2019 15:06	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Ex press)	[I] Merimen Administrator
8	02 Apr 2019 15:08	Label Added	(23):Express.	[A] HOW MEI KWAN
9	02 Apr 2019 15:08	Adj Adjuster Assigned	[None] -> ONG HWEE JIE	[A] HOW MEI KWAN
10	22 Jan 2020 16:08	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	22 Jan 2020 16:08	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN
12	22 Jan 2020 16:08	Cim Dtl Modified	JPJ Reg. Date: -> 2015/10/23.	[A] JOANNE LEE KHANG MIN
13	22 Jan 2020 16:08	Cim Details Notified		[A] JOANNE LEE KHANG MIN
14	31 Jan 2020 18:01	Adj Mandate Request	Cur.Req:10062.00:Liability down against OI - OI lost control and collided into TP. BOLA 21, ** 11 days r ecommendation for repair + 1 Sunday = 12 days	[A] Khanchna Pothuraj

Date From

Date To

Audit Type

None

Go

ACTIVITY

[10/04/2019 17:37] VIC ALPEH:
10/4/2019 @5.15PM - Spoken to OI (Mr. Ong Chin Howe - 84984988).He confirmed the mva.
OI rear ended TP.Informed OI on TP claim,agreed to settle and aware NCD will be affected.
Sent letter to OI

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc.Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2416288	22 Jan 2020 16:08:46	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHD6356T	SLU1283R	11.77

View Received Message

This mail is associated with :

***SHD6356T (8871498074SG)**
[SLU1283R]
TP
SMRT TAXIS PTE LTD
Mar 30 2019 2:00AM
[ONG CHIN HOWE]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/02/2020 09:17 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10000.00) - SHD6356T - Claim Handler: Chan, Kian-Meng

Approved:10000.00.

DOCUMENTS SUMMARY
There are no documents.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 5 March 2020 1:59 PM
To: 'Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)'
Cc: Admin A
Subject: RE: LOD Re: Accident on 30/3/2019 involving SHD 6356T & SLU 1283R (AIG's insured)
Our Ref: TAX/03/19/2146/lg

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement for global sum of **\$10,000.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Tuesday, 24 September 2019 6:13 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: LOD Re: Accident on 30/3/2019 involving SHD 6356T & SLU 1283R (AIG's insured) Our Ref: TAX/03/19/2146/lg

Dear All,

We quantify our own losses as follows:-

Cost of Repair	\$8,450.00
Loss of Rental	\$1,872.50 (14 days x \$133.75)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 11 March 2020 1:21 PM
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A
Subject: RE: Acceptance of offer Re: Accident on 30/3/2019 involving SHD 6356T & SLU 1283R (AIG's insured) Our Ref: TAX/03/19/2146/lg
Attachments: AIG DV.pdf; ATA.pdf

WITHOUT PREJUDICE

Dear Sir/Madam,

Thank you for the acceptance.

We attach herewith a copy of the DV & ATA for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>

Sent: Friday, 6 March 2020 2:28 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Acceptance of offer Re: Accident on 30/3/2019 involving SHD 6356T & SLU 1283R (AIG's insured)
Our Ref: TAX/03/19/2146/lg

Dear Khanchna,

We accept your global offer of \$10,000.00 for our own losses. Please let us have your DV and ATA. Thanks.

Regards

...CLAIM SUBFOLDER...(Pending for Survey Report)
Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2019 Edit Reg		01 Apr 2019 00:00 Edit Adj Rpt	S\$8,450.00 Edit Estimates	S\$8,450.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ONG CHIN HOWE, ID: 576391311		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHD6356T	Date of Loss:	30/03/2019 02:00 - :59 [41 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8871498074SG	Policy/Cover Note No.:	1700074535 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU1283R	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 11/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (20/02/2020): Alert - Adj Mandate Approved (S\$10000.00) - SHD6356T - Claim Handler: Chan, Kian...
- AIG_SG (03/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD6356T (88714980745G)
[SLU1283R]
TP
SMRT TAXIS PTE LTD
Mar 30 2019 2:00AM
[ONG CHIN HOWE]
SMRT Automotive Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	{Draft}	Third Party Express Settlement – Payment Breakdown	1 Edit	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/19 09:11	General View	1 Load JPG	☒
2	03/04/19 09:11	General View	1 Load JPG	☒
3	03/04/19 09:11	General View	1 Load JPG	☒
4	03/04/19 09:11	General View	1 Load JPG	☒
5	03/04/19 09:11	General View	1 Load JPG	☒
6	03/04/19 09:11	General View	1 Load JPG	☒
7	03/04/19 09:11	General View	1 Load JPG	☒
8	03/04/19 09:11	General View	1 Load JPG	☒
9	03/04/19 09:11	General View	1 Load JPG	☒
10	03/04/19 09:11	General View	1 Load JPG	☒
11	03/04/19 09:11	General View	1 Load JPG	☒
12	03/04/19 09:11	General View	1 Load JPG	☒
13	03/04/19 09:11	General View	1 Load JPG	☒
14	03/04/19 09:11	General View	1 Load JPG	☒
15	03/04/19 09:11	General View	1 Load JPG	☒
16	03/04/19 09:11	General View	1 Load JPG	☒
17	03/04/19 09:11	General View	1 Load JPG	☒
18	03/04/19 09:11	General View	1 Load JPG	☒
19	03/04/19 09:11	General View	1 Load JPG	☒
20	03/04/19 09:11	General View	1 Load JPG	☒
21	03/04/19 09:11	General View	1 Load JPG	☒
22	03/04/19 09:11	General View	1 Load JPG	☒
23	03/04/19 09:11	General View	1 Load JPG	☒
24	03/04/19 09:11	General View	1 Load JPG	☒
25	03/04/19 09:11	General View	1 Load JPG	☒
26	03/04/19 09:11	General View	1 Load JPG	☒
27	03/04/19 09:11	General View	1 Load JPG	☒
28	03/04/19 09:11	General View	1 Load JPG	☒
29	03/04/19 09:11	General View	1 Load JPG	☒
30	03/04/19 09:11	General View	1 Load JPG	☒
31	03/04/19 09:11	General View	1 Load JPG	☒
32	03/04/19 09:11	General View	1 Load JPG	☒
33	03/04/19 09:11	General View	1 Load JPG	☒
34	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
35	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
36	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
37	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
38	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
39	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	☒
40	19/09/19 19:04	Photographs of Damaged Parts	1 Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
			☒	☒
41	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
42	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
43	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
44	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
45	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
46	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
47	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
48	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
49	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
50	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
51	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
52	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
53	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
54	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
55	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
56	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
57	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
58	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
59	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
60	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
61	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
62	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
63	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
64	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
65	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
66	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
67	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
68	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
69	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
70	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
71	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
72	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
73	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
74	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
75	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
76	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
77	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
78	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
79	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
80	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
81	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
82	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
83	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
84	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
85	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
86	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
87	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
88	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
89	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
90	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
91	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
92	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
93	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
94	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒
95	19/09/19 19:04	Photographs of Damaged Parts	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/19 20:38	TP ESTIMATE - MARKED		Load PDF
2	05/04/19 20:38	TP GIA REPORT		Load PDF
3	10/04/19 17:34	LETTER TO OI		Load PDF
4	31/01/20 17:36	Repair Bill, Rental supporting docs, LTA Search		Load PDF
5	17/03/20 09:45	WORKSHOP INVOICE		Load PDF
6	17/03/20 09:45	AUTHORISATION TO ACT FORM		Load PDF
7	17/03/20 09:45	Release Voucher		Load PDF
8	17/03/20 09:45	RENTAL MILEAGE		Load PDF
9	17/03/20 09:45	RENTAL RECEIPT		Load PDF
10	17/03/20 09:45	LTA SEARCH		Load PDF
11	17/03/20 09:45	LOD		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/04/19 14:30	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SLU1283R (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHD6356T (TP veh)		
Date of Accident:	30/03/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	45,427.48
Final Repair Cost	:	\$	10,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	12 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	10,000.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>100</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 10,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19005795/JKA3Q2
Date: 17/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700074535
Claimant SHD6356T Insured Vehicle No : SLU1283R
Vehicle No : SHD6356T
Date of Loss: 30/03/2019 Nature of Claim: TP Claim No: 8871498074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6356T Engine No: 2ZR6544837
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Chassis No: JTDKN36U605766520
Reg. Date: 23/10/2015 (Man. Year: 2015) Odometer: 362747 km
Colour: Maroon
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,369.48	6,809.29	28,560.19	80.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,058.00	2,950.00	7,108.00	70.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,427.48	9,759.29	35,668.19	78.52
Approved Total (Overridden) (S\$)		8,450.00		
Nett Amount (S\$)	45,427.48	8,450.00	36,977.48	81.40
+ Car Rental (12.0 x S\$133.75/day) (S\$)		1,605.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		10,062.00		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 01/04/2019
Date Inspected: 01/04/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 11.0 days

Adjuster: ONG HWEE JIE

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER SEAL ,RR LH (DISC 25%)	Cracked	88.90 F	*66.68 F
2	1	*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
3	1	*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
4	1	*TAIL GATE DOOR GLASS MOULDING ,LH (DISC 25%)	Necessary	29.40 F	*22.05 F
5	1	*TAIL GATE DOOR GLASS MOULDING ,RH (DISC 25%)	Necessary	29.40 F	*22.05 F
6	1	*MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
7	1	*DAM ,BACK DOOR GLASS ADHESIVE NO.1 (DISC 25%)	Necessary	27.30 F	*20.48 F
8	1	*TAILGATE LOWER WINDOW GLASS (DISC 25%)	Broken	721.30 F	*540.98 F
9	1	*BUMPER REAR (DISC 25%)	Broken	458.60 F	*343.95 F
10	1	*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
11	1	*EMBLEM REAR (DISC 25%)	Necessary	60.30 F	*45.23 F
12	1	*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
13	1	*NAME PLATE (PRIUS) (DISC 25%)	Necessary	60.80 F	*45.60 F
14	1	*NAME PLATE (TOYOTA) (DISC 25%)	Necessary	51.90 F	*38.93 F
15	1	*FENDER RR/LH (DISC 25%)	Dented	766.80 F	*575.10 F
16	1	*QUARTER GLASS RR/LH (DISC 25%)	Necessary	168.10 F	*126.08 F
17	1	*SPARE TYRE PANEL (DISC 25%)	Buckled	667.70 F	*500.78 F
18	1	*FLOOR PANEL RR/LH (DISC 25%)	Buckled	102.00 F	*76.50 F
19	1	*BUMPER LIP COVER RR/RH (DISC 25%)	Cracked	118.10 F	*88.58 F
20	1	*UNDER COVER SUBASSY RR FLOOR (DISC 25%)	Buckled	514.50 F	*385.88 F
21	1	*END PANEL COVER ,DECK TRIM HOLE (DISC 25%)	Cracked	46.10 F	*34.58 F
22	1	*END PANEL COVER ,DECK TRIM ,RR (DISC 25%)	Scratched	121.10 F	*90.83 F
23	1	*MEMBER SUB-ASSY ,RR LH (DISC 25%)	Buckled	174.10 F	*130.58 F
24	1	*END PANEL (DISC 25%)	Buckled	602.10 F	*451.58 F
25	1	*BUMPER LIP REAR (DISC 25%)	Cut	228.90 F	*171.68 F
26	1	*BUMPER LIP COVER RR/LH (DISC 25%)	Cut	72.20 F	*54.15 F
27	1	*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
28	1	*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
29	1	*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
30	1	*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
31	1	*TAILGATE DOOR WEATHER STRIP (DISC 25%)	Cut	353.40 F	*265.05 F
32	1	*TAIL LAMP LH (DISC 10%)	Broken	548.40 F	*493.56 F
33	1	*SOLAR FILM (SN)	Necessary	250.00 F	*250.00 F
34	1	*SENSOR REVERSE (SN)	Broken	180.00 F	*180.00 F
35	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
36	3	*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
37	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
38	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
39	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
40	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
41	1	*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
42	1	*TYRE (SN)	Torn	126.74 F	*126.74 F
43	1	*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
44	1	*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
45	1	*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
46	1	*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
47	1	*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
48	1	*UNDER COVER SUBASSY RR FLOOR	Not Necessary	514.50 F	*- F
49	1	*EXHAUST HEAT SHIELD REAR	Not Necessary	107.40 F	*- F
50	1	*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*- F
51	1	*SUPPORT ,EXHAUST REAR	Not Necessary	33.60 F	*- F
52	1	*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
53	1	*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*-F
54	1	*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*-F
55	1	*TAILGATE DOOR GLASS	Not Necessary	1,090.90 F	*-F
56	2	*TAILGATE DOOR HINGE LH/RH	Not Necessary	58.30 F	*-F
57	1	*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*-F
58	1	*TAILGATE DOOR STAY LH	Not Necessary	241.50 F	*-F
59	1	*TAILGATE DOOR STAY RH	Not Necessary	241.50 F	*-F
60	1	*TAILGATE DOOR WEATHER STRIP	Not Necessary	353.40 F	*-F
61	1	*TAILGATE LOCK COVER	Not Necessary	15.70 F	*-F
62	1	*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*-F
63	1	*STRIKER ,BACK DOOR	Not Necessary	48.90 F	*-F
64	1	*TAILGATE TRIM ,LOWER	Not Necessary	180.70 F	*-F
65	1	*TAILGATE BOARD ASSY	Not Necessary	246.90 F	*-F
66	1	*WIRE BACK DOOR NO.1	Not Necessary	582.40 F	*-F
67	1	*CAMERA ASSY ,TELEVISION RR	Not Necessary	1,436.60 F	*-F
68	1	*SWITCH ASSY ,BACK DOOR OPENER	Not Necessary	146.10 F	*-F
69	1	*LICENSE PLATE LAMP	Not Necessary	35.70 F	*-F
70	1	*NUMBER PLATE	Not Necessary	15.00 F	*-F
71	1	*NUMBER PLATE FRAME	Not Necessary	12.00 F	*-F
72	1	*SPOILER REAR	Not Necessary	953.70 F	*-F
73	1	*3RD BRAKE LAMP	Not Necessary	231.30 F	*-F
74	1	*END PANEL	Not Necessary	602.10 F	*-F
75	1	*END PANEL COVER ,DECK TRIM HOLE	Not Necessary	46.10 F	*-F
76	1	*END PANEL COVER ,DECK TRIM ,RR	Not Necessary	121.10 F	*-F
77	1	*REINFORCEMENT ,RR	Not Necessary	34.60 F	*-F
78	1	*SEALANT SIKAFLEX	Not Necessary	37.00 F	*-F
79	1	*SPARE TYRE PANEL	Not Necessary	667.70 F	*-F
80	1	*MEMBER SUB-ASSY ,RR LH	Not Necessary	174.10 F	*-F
81	1	*MEMBER SUB-ASSY ,RR RH	Not Necessary	174.10 F	*-F
82	1	*FLOOR PANEL RR/LH	Not Necessary	102.00 F	*-F
83	1	*BOX,DECK FLOOR RR	Not Necessary	649.70 F	*-F
84	1	*BOX RR FLOOR BOARD	Not Necessary	579.60 F	*-F
85	1	*BOARD ,RR FLOOR	Not Necessary	392.30 F	*-F
86	1	*BOX ,DECK FLOOR COVER LH	Not Necessary	230.10 F	*-F
87	1	*BOX DECK FLOOR LH	Not Necessary	196.80 F	*-F
88	1	*COVER ASSY ,TONNEAU	Not Necessary	602.10 F	*-F
89	1	*CUSHION SPARE WHEEL	Not Necessary	230.80 F	*-F
90	1	*PROTECTOR ,SPARE	Not Necessary	143.70 F	*-F
91	1	*CARRIER SPARE	Not Necessary	19.70 F	*-F
92	1	*TYRE	Not Necessary	126.74 F	*-F
93	1	*WHEEL DISC	Not Necessary	1,490.20 F	*-F
94	1	*BREAKDOWN SIGN	Not Necessary	35.00 F	*-F
95	1	*PANEL ASSY ,DECK LH	Not Necessary	307.00 F	*-F
96	1	*WIRE FLOOR	Not Necessary	1,675.00 F	*-F
97	1	*WIRE FLOOR NO.2	Not Necessary	1,305.40 F	*-F
98	1	*PANEL SUB-ASSY ,QTR WHEEL HOUSE	Not Necessary	588.40 F	*-F
99	1	*PANEL QUARTER WHEEL HOUSE OUTER LH	Not Necessary	326.70 F	*-F
100	1	*TAIL LAMP BRACKET LH	Not Necessary	30.70 F	*-F
101	1	*TROUGH BACK DOOR LH	Not Necessary	110.90 F	*-F
102	1	*FENDER LINER RR/LH	Not Necessary	141.30 F	*-F
103	1	*CABLE SUB-ASSY ,FUEL LID	Not Necessary	63.90 F	*-F
104	1	*RETAINER ,FUEL LID CABLE	Not Necessary	5.90 F	*-F
105	1	*CAP ASSY ,FUEL TANK	Not Necessary	68.10 F	*-F
106	1	*PIPE SUB-ASSY ,FUEL NECK	Not Necessary	230.80 F	*-F
107	1	*TUBE ,FUEL TANK	Not Necessary	36.10 F	*-F
108	1	*TANK SUB -ASSY ,FUEL	Not Necessary	745.10 F	*-F
109	1	*TAIL LAMP BRACKET ,RH	Not Necessary	30.70 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
110	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F
111	1		*TROUGH BACK DOOR	Not Necessary	110.90 F	*- F
112	1		*FENDER RR/RH	Not Necessary	766.80 F	*- F
113	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
114	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
115	1		*DOOR LOCK RR /LH	Not Necessary	709.30 F	*- F
116	1		*DOOR LOCK STRIKER	Not Necessary	40.50 F	*- F
117	1		*DOOR HINGE UPPER RR/LH	Not Necessary	81.70 F	*- F
118	1		*DOOR HINGE LOWER RR/LH	Not Necessary	72.20 F	*- F
119	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*- F
120	1		*LID ASSY ,FUEL	Repair	102.00 F	*- F
121	1		*WHEEL DISC	Repair	1,490.20 F	*- F
122	1		*DOOR RR/LH	Repair	954.50 F	*- F

F=Franchise part.

Total Parts (S\$) 35,369.48 6,809.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	2,170.00	1,230.00
2	SPRAY PAINT	New	4,812.00	1,250.00
3	TOWING CHARGE	New	126.00	90.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	30.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
7	TO REMOVE/REFIT SEAT	New	120.00	50.00
8	TO ALIGN CHASSIS	New	350.00	0.00
9	TO REMOVE & REFIT FUEL TANK	New	120.00	0.00
10	TO REMOVE & REFIT EXHAUST	New	120.00	0.00
11	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
12	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
13	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	50.00
14	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	30.00
15	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	30.00
16	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	0.00
17	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	60.00
18	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	40.00
19	TO REMOVE AND REFIT WIRE HARNESS	New	250.00	0.00
20	TO REPLACE SUNDRY PARTS	New	100.00	0.00
21	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			10,058.00	2,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >