## COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE\*

VEHICLE NO: SH 8118A

MAKE

DATE 30/3/2019 10:55

CHINA LKR/Kalvin

EL	: HYUNDAI i40  Parts Description/ Labour	Type	I	Unit Price	F	Amount	
Qty		Турс		ome race	\$	553.00	/CRK
	Rear Bumper Rear Bumper Reinforcement				\$	428.40	?
	Rear Bumper Reinforcement Bracket (LH/RH)		\$	80.30	\$	160.60	?
			Ι Ψ	00.50	\$	22.00	NE
	Rear Bumper Clip 10 pcs		\$	35.60	\$	71.20	3
	Rear Bumper Bracket Rear Bumper Sponge		Ψ	33.00	\$	103.50	?
					\$	228.00	1sce
	Rear Bumper Under Cover				φ	220.00	
	SUB TOTAL				\$	1,566.70	
	LESS 20%				\$	313.34	
	DISCOUNTED TOTAL				\$	1,253.36	1
	DISCOUNTED TOTAL				9	1,233.30	
	n n n ll M-i				\$	50.00	Nett /
	Rear Bumper Rubber Mat				\$		Nett X
	Rear Bumper Reverse Sensor				Ф	133.70	INCH A
					\$	185.70	
					Φ	105.70	
	Labour Charge						
	Panel Beating				\$	350.00	200
	Spray Painting Charge				\$	250.00	200
	Wiring Charge				\$	30.00	KNI
	Remove/Refix Reverse Sensor				\$	80.00	20 19
	Remove/Remx Reverse Sensor						
	TOTAL LABOUR				\$	710.00	
	ESTIMATE TOTAL				\$	2,149.06	
	NAZ LKK	LiG	Auto Co	onsultants hence n	otify		
	114/19 1635	the	Repairer	of the following:	1		
		• 10	resurvey b	efore/after spray paint maged part(s) during n	ng		
	P1P	• Pa	rts prices a	ire subject to confirmat	ion	'	
	2 0 94			rvey is on a "Without P	rejudi	ce" basis	
	2 Days CHECK ITEMS PHOTOS BH PAINT PHOTOS			dification(s) is allowed ry item(s) must be resu	rveve	dand	
	CHECK ITEMS (11/0)	iss	ubject to f	ry item(s) must be resu inal approval from Insu	rance	Company	
	OIL DOINT OHOTOL	Actor	owledged	by Repairer			
	Da tallet trocks		ature:				
		Date	:		_		
	This is an initial estimate based on a visual inspection of the	e ahove y	ehicle	The final repair	uan	tum will	