



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 4337L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	BROKEN	1,480.00	1,480.00
1	REAR BUMPER BEAM (CONSISTENT)	DENTED	655.00	655.00
1	TAIL LAMP (RH)(CONSISTENT)	BROKEN	518.00	518.00
1	END PANEL (CONSISTENT)	DENTED	1,250.00	1,250.00
1	SET BUMPER CHROME (CONSISTENT)	BROKEN	320.00	260.00
1	REVERSE SENSOR RH (CONSISTENT)	BROKEN	820.00	250.00
1	TOW HOOK COVER (CONSISTENT)	CRUSHED	50.00	50.00
1	RH BUMPER BRACKET (ADDITIONAL) (CONSISTENT)	BROKEN	75.00	75.00
1	CENTER BUMPER BRACKET (ADDITIONAL) (CONSISTENT)	BROKEN	145.00	145.00
1	LH BUMPER BRACKET (ADDITIONAL) (CONSISTENT)	BROKEN	75.00	75.00
2	RETAINER LH & RH (ADDITIONAL) (CONSISTENT)	BROKEN	90.00	90.00
	LESS 10% DISCOUNT		-547.80	-484.80
			4,930.20	4,363.20
	<u>LABOUR</u>			
	TO REMOVE & REPLACE REAR BUMPER,BUMPER BEAM,TAILLAMP AND TO PANEL BEAT CUT & WELD ENDPANEL.		1,400.00	600.00
	TO PUTTY & SPRAY PAINT REAR BUMPER,END PANEL,FENDER AND OTHER AFFECTED AREA.		800.00	600.00
	TO CHECK & RECTIFY WIRING & REPLACE SENSOR.		220.00	50.00
	TUFF KOTE.		250.00	40.00
			2,670.00	1,290.00
	GRAND TOTAL		7,600.20	5,653.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00

Report Ref No. CC4/ASM19005803/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.