

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA7331Z

DATE: 29. Mar. 2019

MAKE : HYUNDAI

MODEL : SONATA

DOA: 28. Mar. 2019

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Boot Lid <i>X repair</i>			\$1,349.50
1	Boot Lid Rubber <i>X</i>			\$110.90
1	Boot Lid Lock Upper <i>X</i>			\$132.10
1	Boot Lid Sonata Plate <i>/</i>			\$43.60
1	Boot Lid Hyundai Plate <i>/</i>			\$24.20
1	Boot Lid 'H' Emblem <i>/</i>			\$26.10
1	Boot Lid CRDI Plate <i>/</i>			\$22.70
1	Tail Lamp (Boot) - LH <i>X</i>			\$230.20
1	Tail Lamp (Boot) - LH <i>X</i>			\$230.20
1	Rear Bumper <i>/</i>			\$578.40
1	Rear Bumper Reinforcement <i>/</i>			\$483.30
1	Rear Bumper Sponge <i>?</i>			\$137.40
1	Rear Bumper Undercover <i>X</i>			\$185.80
10	Rear Bumper Clips <i>/</i>		\$2.20	\$22.00
1	Rear Panel <i>X repair</i>			\$391.80
1	Rear Panel Garnish <i>X</i>			\$95.80
1	Exhaust Muffler <i>X</i>			\$723.00
SUB TOTAL				\$4,787.00
LESS 20%				\$957.40
DISCOUNTED TOTAL				\$3,829.60
1	Boot Lid Comfort Logo & Tel No Sticker <i>/</i>			\$30.00
1	Rear Bumper Rubber Mat <i>/</i>			\$50.00
1	Reverse Sensor <i>X</i>			\$135.70
				Nett
				Nett
				Nett
				\$215.70
Labour Charge				
1	Panel Beating			\$750.00 400
1	Spray Painting Charge			\$750.00 600
1	Tuff Kote			\$50.00 X
1	Wiring Charge			\$50.00 X
1	Remove/Refix Reverse Sensor			\$120.00 50
1	Remove/Refix Exhaust			\$120.00 X
TOTAL LABOUR				\$1,840.00
ESTIMATE TOTAL				\$5,885.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: *[Signature]*
 Date: 29/3/19

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.