

Surveyor

Taffin

REF: ASM(AxA)

ASSIGNMENT

From:

Date: 11/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No.

GBE 2362S

at Workshop n/s

Gold Bell

of

8 tuas Ave 18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1:30-3pm

Brian @

97557336

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$3912

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

1-8-1

%

3 Vol: Yes or No

CA / REV / REP. / 24 HRS 1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBE 2362S

Yr Regn: 2015 / Sep.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Pratt Doble Cargo Maxi 1593

Colour

8/ner

A/C: Insured / Std / NI / NA

Sp. Reading

83537

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA263 0000 6A 82304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

145/60R11

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Annaike.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I

4/4/19

Survey held at

Goldbell Tues.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$2836.62 / - (Red = \$6020.61 / 63.1.)

No 2nd hand part, only replacement of rear bumper and repair Rear Door

Date/Time, File Pass to?

☐

: Prefi. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + RES 3

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$



MOTORVIVA PTE LTD
 Main Office: 48 Changi South Street 1 Singapore 480130 Tel : 6865 2518
 Finance: 18 Tuas Avenue 10 Singapore 639142 Tel : 6861 0007 Fax: 6862 3500
 Fiat Professional: 61 Ubi Avenue 2 #01-11 Singapore 408896 Tel : 6865 2518 Fax: 6861 7956
 Iveco: 18 Tuas Avenue 10 Singapore 639142 Tel : 6863 6864 Fax: 6861 3678
 Website: www.motorviva.com.sg
 Co. Reg. No.: 1005076142

Page 1 / 2

ESTIMATE

Date :	01/04/2019	Reg No :	GBE23625
To :	AXA INSURANCE SINGAPORE PTE LTD	Model :	263.216.1
Attn. :		Chassis No :	ZFA26300006A82304
Office / Mobile :		Engine No :	263A50007396767
Email Address :		Quotation No. :	84841
		Ref. No. :	GBE/SVC/SALES-4847/190401
From :	MOTORVIVA PTE LTD	D.O.A. :	20/03/2019
Attn. :	ENGKWOKLONG	Policy No. :	MA002478
Office / Mobile :	+65 6864 0637	Claim Type :	TP CLAIM - AXA
Email / Fax No. :	EngKwokLong@goldbell.com.sg	Workshop :	8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	735512760	BUMPER, RR	1	797.68	-10	717.91	717.91
2	735516619	PLUG, BUMPER(TOW COVER)	1	15.60	-10	14.04	14.04 x n
3	51810677	REFLEX/REFLECTOR -RH	1	18.22	-10	16.40	16.40 x n
4	51810678	REFLEX/REFLECTOR -LH	1	33.80	-10	30.42	30.42 x n
5	51818353	BUMPER, RR, BRACKET -RH	1	45.76	-10	41.18	41.18 x n
6	51818261	BUMPER, RR, BRACKET -LH	1	45.76	-10	41.18	41.18 x n
7	52044717	TAIL LAMP LHS	1	595.36	-10	535.82	535.82 x n
8	51844575	SEALING GASKET (DOOR)	1	446.71	-10	402.04	402.04 x n
9	51874302	TYPE PLATE, MAXI	1	42.94	-10	38.65	38.65 x n
10	52052874	TYPE PLATE RR, DOBLO	1	76.13	-10	68.52	68.52 x n
11	51810535	CROSSRAIL, RR BUMPER	1	441.50	-10	397.35	397.35 x n
12	52032351	DOOR, RR -LH	1	2,896.75	-10	2,607.08	2,607.08 x n
13	52029627	HINGE LOWER	1	185.22	-10	166.70	166.70 x n

PARTS TOTAL : 5,077.29

SPECIAL NETT ITEMS

1	"70 KM/H" STICKER	1	20.00
2	REVERSE SENSOR ASSY	1	280.00

PARTS TOTAL: 300.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	1500.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1400.00
3	SUNDRIES	80.00
4	TO REMOVE & REFIX REAR WINDSCREENS. (NETT)	150.00
5	TO REMOVE & REFIX REAR DOOR COMPARTMENTS INCLUDING TRANSFER DOOR LOCK, INNER TRIM & WIPER MOTOR	350.00

ESTIMATE

Date	: 01/04/2019	Reg No	: GBE2362S
To	: AXA INSURANCE SINGAPORE PTE LTD	Model	: 263.216.1
Attn.	:	Chassis No	: ZFA26300006A82304
Office / Mobile	:	Engine No	: 263A50007396767
Email Address	:	Quotation No.	: 84841
From	: MOTORVIVA PTE LTD	Ref. No.	: GBE/SVC/SALES-4847/190401
Attn.	: ENGWOKLONG	D.O.A.	: 20/03/2019
Office / Mobile	: +65 6864 0637	Policy No.	: MA002478
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Claim Type	: TP CLAIM - AXA
		Workshop	: 8 TUAS AVE 18

SUB-TOTAL :	8,857.29
GST @ 7% for \$ 8,857.29	620.01
GRAND TOTAL (S\$) :	9,477.30

PREPARED BY : ENGWOKLONG

DATE / TIME : 4/4/19 12:30

SURVEYOR : Tan Jiah

MOBILE NO : 97493264

OFFICE FAX NO :

EMAIL ADDRESS : sue@kianson.com

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 4-5 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



IVECO



SATISFACTION VOUCHER

To: **Motorviva Pte Ltd.**
8 Tuas Avenue 18
Singapore 638892

Date: **10/06/2019**
Reference:

We hereby confirm the receipt of the our vehicle in good and working condition from the repairer, M/s Goldbell Engineering Pte Ltd. , and that all necessary repairs resulting from the below mentioned accident had been completed to our satisfactory.

Vehicle Number : **GBE2362S**

Make & Model : **FIAT 263.216.1**

Chassis Number : **ZFA26300006A82304**

Engine Number : **263A50007396767**

Accident Date : **20/03/2019**

Claim Reference : **GBE/SVC/SALES-4847/190401**

Remarks : **TP CLAIM - AXA**

On behalf of M/s : **KACHI GLOBAL PTE. LTD.**

Company Stamp :

Signature :

Name :



Desmond

eTiqa Insurance

Page 12 of 23

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 2 April 2019 3:48 PM
To: assignments
Subject: FW: TP claim - Accident case between GBE 2362 S & SGB 33 L (your insured) on 20/03/2019 at 0930hrs along Slip Road Toa Payoh LOR 6 TOWARD PIE
Attachments: GBE2362S ETIQA.PDF; ESTIMATE.pdf

Hi team,

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

4.10pm @ 2/4/2019
Brian
vehicle not in.

From: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>
Sent: Tuesday, 2 April, 2019 2:20 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: Ramesh <Ramesh@goldbell.com.sg>; Ashlyn Chng <AshlynChng@goldbell.com.sg>
Subject: TP claim - Accident case between GBE 2362 S & SGB 33 L (your insured) on 20/03/2019 at 0930hrs along Slip Road Toa Payoh LOR 6 TOWARD PIE

Dear Sir/Madam,

Kindly refer to the attached above.

Please arrange for survey.

Thanks & Best Regards,



Brian Eng Kwok Long | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6864 0637 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9755 7336 | Web: <http://www.goldbell.com.sg>



x



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 6/9/2019

Survey Details:

Date of loss	20-Mar-19
Date of appointment	2-Apr-19
Date of survey	4-Apr-19
Location of survey	MOTORVIVA PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBE2362S
Make and Model	FIAT OBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Date of registration	30-Sep-15
Parf Rebate	
Market Value	\$ 39,000.00
Parf Rebate	\$ 3,515.00
Nett Loss	\$ 35,485.00

Repair details:

Initial Estimate	\$ 8,857.29
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 916.68
Check items (estimate)	\$ -
Labour	\$ 1,920.00
Total	\$ 2,836.68
Lump Sum(if applicable)	

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 3,035.25	W/GST
Loss of use	\$ 400.00	4days x \$100
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 7.49	
Others	-	
Proposed Total	3,442.74	



<MANDATE IA> - S9M01HOG {ACCIDENT INVOLVING SGB 33L (OI) & GBE 2362S (TP) ON 20/03/2019}

Type

Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3,442.74 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER
SINGAPORE 068811
Attn: MS CATHERINE

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : MXI00028339
Invoice Date. : 20-06-2019
Account No. : C00000371
Quotation No. : 84841
Work Order No. : 778455
Service Centre. : 8 TUAS AVE 18
Agreement No. : MV-3974

Agreement No. : MV 5574

PARTICULARS		AMOUNT SGD			
Reg No	: GBE2362S				
Chassis No	: ZFA26300006A82304				
Engine No	: 263A50007396767				
Model No	: 263.216.1				
Mileage	: 83585				
SRR No	:				
ACCIDENT REPAIR: GBE/SVC/SALES-4847/190401					
DATE OF ACCIDENT: 20/03/2019					
POLICY NO.: MA002478					
**** TP CLAIM - AXA****					
ITEM 1:TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT,STRAIGHTEN & REALIGN, ETC					
ITEM 2:TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC					
ITEM 3:SUNDRIES					
<u>Description</u>	<u>QTY</u>	<u>U/Price</u>	<u>Disc</u>	<u>Net Price</u>	<u>Ext Price</u>
BUMPER	1	717.91	N	717.91	717.91
REFLEX/REFLECTOR-LH	1	30.42	N	30.42	30.42
BUMPER,RR BRACKET LH	1	41.18	N	41.18	41.18
TYPE PLATE MAXI	1	38.65	N	38.65	38.65
TYPE PLATE DOBLO	1	68.52	N	68.52	68.52
70 KM/H STICKER	1	20.00	N	20.00	20.00
LABOUR CHARGES (REFER TO ITEM 1)	1	1200.00	N	1200.00	1200.00
LABOUR CHARGES (REFER TO ITEM 2)	1	700.00	N	700.00	700.00
LABOUR CHARGES (REFER TO ITEM 3)	1	20.00	N	20.00	20.00
Parts Charges:					2836.68
Sub Total:					2836.68
GST @ 7.00 %					198.57

E. & O. E

E. & O. E



IVECO



TOTAL 3035.25

Please make all cheques payable to MOTORVIVA PTE LTD.
When making payment, please quote our invoice numbers.
No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.



IVECO





Re:RE: Re:<MANDATE IA> - S9M01HOG {ACCIDENT INVOLVING SGB 33L (OI) & GBE 2362S (TP) ON 20/03/2019}

Type

🔗 Question

Message

Noted. Proceed. Thanks

Reply

9th July 2019

Our Reference : GBE2362S
Your Reference : CC4/ASM19005841/T1ja3

AXA Insurance Singapore Pte Ltd

8 Shenton Way,
#27-01 AXA Tower,
Singapore 068811

Attn: Motor Claims Department

Dear Officer In-Charge,

Subject: Accident Involving GBE2362S and SGB33L on 20/03/2019 along Slip Road Toa Payoh Lorong 6 towards PIE.

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. SGB33L.

1. Cost of Repair (\$2836.68 x 7% GST)	S\$	3,035.25
2. Loss of Use (\$120 x 4 days)	S\$	480.00
3. Third Party Insurer Enquiry Fee	S\$	7.49
Total	S\$	3522.74

We quantify our client's claim as follows:

We hereby append the following relevant documents for your perusal:

- I. Repair Bill Tax Invoice
- II. Third Party Insurer Enquiry Tax Invoice
- III. Satisfaction Voucher
- IV. Letter of Authority

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to accept all the above amount.

Best regards,


Chua Syasya
Motor Claims Officer
Goldbell Engineering Pte Ltd
Tel : 9739 6433
Email : chuasyasya@goldbell.com.sg



IVECO



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005841/T1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-01-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 33L	Veh. Inspected	GBE 2362S
Policy No.	VPA/P1962889	Coverage (\$)	0.00
Claim No.	S9M01HOG	Excess (\$)	0.00
Assign From		Assign Date	02/04/2019

2. Vehicle Particulars & Condition

Make & Model	FIAT DOBLO CARGO MAXI	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZFA26300006A82304	Colour	SILVER
Odometer	83537	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	ANNAITE	6 mm
L/H Front Tyre	195/60 R15	ANNAITE	6 mm
R/H Rear Tyre	195/60 R15	ANNAITE	6 mm
L/H Rear Tyre	195/60 R15	ANNAITE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/03/2019	Inspection Date	04/04/2019
Survey held at	8 TUAS AVE 18		
Repairer	MOTORVIVA PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2362S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER ,RR (CONSISTENT)	DEFORMED	797.68	797.68
1	PLUG ,BUMPER (TOW COVER) (CONSISTENT)	NOT NECESSARY	15.60	-
1	REFLEX /REFLECTOR -RH (CONSISTENT)	NOT NECESSARY	18.22	-
1	REFLEX /REFLECTOR -LH (CONSISTENT)	CUT	33.80	33.80
1	BUMPER ,RR ,BRACKET -RH (CONSISTENT)	NOT NECESSARY	45.76	-
1	BUMPER ,RR ,BRACKET -LH (CONSISTENT)	NECESSARY	45.76	45.76
1	TAIL LAMP LHS (CONSISTENT)	NOT NECESSARY	595.36	-
1	SEALING GASKET (DOOR) (CONSISTENT)	NOT NECESSARY	446.71	-
1	TYRE PLATE ,MAXI (CONSISTENT)	NECESSARY	42.94	42.94
1	TYRE PLATE RR,DOBLO (CONSISTENT)	NECESSARY	76.13	76.13
1	CROSSRAIL ,RR BUMPER (CONSISTENT)	NOT NECESSARY	441.50	-
1	DOOR ,RR-LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,896.75	-
1	HINGE LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	185.22	-
	LESS 10% DISCOUNT		-564.14	-99.63
			5,077.29	896.68
<u>SPECIAL NETT ITEMS</u>				
1	'70KM/H' STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REVERSE SENSOR ASSY (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	20.00
			380.00	40.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT,STRAIGHTEN & REALIGN ,ETC.INCLUSIVE OF THE REPAIR OF DOOR ,RR -LH AND HINGE LOWER .		1,500.00	1,200.00
	TO PUTTY,CLEAN ,SPRAY PAINT AND POLISH ,ETC.		1,400.00	700.00
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-

Report Ref No. CC4/ASM19005841/T1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR DOOR COMPARTMENT INCLUDING TRANSFER DOOR LOCK ,INNER TRIM & WIPER MOTOR .	NOT NECESSARY	350.00	-
			3,400.00	1,900.00
GRAND TOTAL			8,857.29	2,836.68
RECOMMENDED COST OF REPAIRS				2,836.68

Report Ref No. CC4/ASM19005841/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M01HOG
Reference	CC4UASM19005841/71g3q2 
Loss Date	20 March 2019
Report Date	21 Mar 2019 12:00:00 AM
Request Date	30 August 2019
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TPP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	GBE23625
Make	TPVO FIAT
Model	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Service Address	
...	
Primary Contact/Insured	
LOO CHAN KAH BLK 60 LORONG 4 TOA PAYOH, #30-113, 310060, Singapore 98588600 DON@DCVISION.COM.SG	
Claim Handler	
KHONG Lynn 68804892 lynn.khong@axa.com.sg	

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement	GSA Report	Merimen	
LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LKKInspection (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LKKadjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
PAYMENT BREAKDOWN, EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LTA SEARCH.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Issued	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2020
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019
WABF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019
MANDATE IA DO 06/09/2019 .pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019
TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	8 April 2019
 EMAIL FROM WORKSHOP (THIRD PARTY HR).png	Letters and Correspondence	Workshop	KADRI Maiteem	2 April 2019
 GIA REPORT OF GBE23625 (TP).pdf	Reports & Statement	GIA Report	KADRI Maiteem	2 April 2019
 P1963889_P5.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KHONG Lynn	21 March 2019