Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### **VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CC4/FWD19005848/K1PA3Q2

**Date:** 28/05/2020

**REFERENCE** 

Price:

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00006854

Claimant SHD8584M Insured Vehicle No: SJG1278D

Date of Loss: 01/04/2019 Nature of Claim: TP Claim No: 1201900009260

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD8584M

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR Engine No: D4FDGU674239

(A)

Reg. Date: 15/09/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU093780

Colour: Yellow Odometer: 356856 km

Engine Capacity: 1685 cc
Market Value/New Car
N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,184.32	2,971.84	212.48	6.67
Miscellaneous Items		0.00	0.00	0.00	
Labour		850.00	400.00	450.00	52.94
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,034.32	3,371.84	662.48	16.42
	+ GST 7.00/7.00% (S\$)	282.40	236.03	46.37	16.42
	Nett Amount (S\$)	4,316.72	3,607.87	708.85	16.42
	+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
	+ Car Rental (2.0 x S\$	112.67/day) (S\$)	225.34		
		(S\$)	3,933.21		
	Liable Amount (50.00%) (S\$)		1,966.61		
	+ Doc/Search Fee (S\$)		7.49		
	N	lett Liability (S\$)	1,974.10		
	Global Sum Settlement (S\$)		1,950.00		

**INSPECTION** 

Date of Assignment: 02/04/2019

Date Inspected: 03/04/2019 Inspected At: ComfortDelGro Engineering Pte Ltd

(Loyang)

Adjuster Report Page 2 of 4

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## **REPAIR DETAILS**

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2019)		
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	e: (Unsubmitted, no print-code for SHD8584M)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

## **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RADIATOR GRILLE	Cut	1,110.10 FL	*1,110.10 FL
2	1	*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
3	1	*FRONT BUMPER GRILLE (RH)	Serviceable	93.60 FL	*-FL
4	1	*FRONT BUMPER BRACKET TOP (RH)	Serviceable	22.40 FL	*-FL
5	1	*FRONT BUMPER BRACKET (RH)	Serviceable	24.60 FL	*-FL
6	1	*FRONT BUMPER COVER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
7	1	*FRONT FENDER ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*-FS
8	1	*HEADLAMP ASSY RH	Cracked	1,388.00 FL	*1,388.00 FL
9	1	*H EMBLEM	Necessary	39.50 FL	*39.50 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.					
			Sub Total (S\$)	3,930.40	3,689.80
- List Item Discount on L Items 20.00/20.00% (S\$)			746.08	717.96	
			Total Parts (S\$)	3,184.32	2,971.84

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	300.00	200.00
2	SPRAY PAINTING CHARGE	New	500.00	200.00
3	TUFF KOTE	New	50.00	0.00
		Gross Labour Cost (S\$)	850.00	400.00
	Repor	t was unsubmitted during this print-out.		

< END OF ESTIMATES >