



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT19001477	Page	1
	64 CECIL STREET	Date	: 2. Apr 2019		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SKP5711J	Engine No	: K24W31200877		
Chassis No	: MRHCR2630EP000032	Date Time	: 2. Apr 2019 3:04:34 PM		
Model	: ACCORD 2.4 AT 2014 (EURO 4)	Surveyor Name	:		
Owner's Name	: MR YUE XIAONING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 1/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YUE XIAONING						
	OWNER INSURER: FWD						
	ACC DATE: 01/04/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INS						
	TP VEH: SHC8762X						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) SCR ✓	1	45.00		45.00	3.15	48.15
71501-T2M-T10ZZ	FACERR.BUMPER DEF ✓	1	630.50	25	472.87	33.10	505.97
71593-T2A-A01	SPACERR.RR.BUMPER SIDE REC ✓	1	12.20	25	9.15	0.64	9.79
71598-T2A-A01	SPACERL.RR.BUMPER SIDE REC ✓	1	12.20	25	9.15	0.64	9.79
91505-TM8-003	CLIP,BUMPER REC ✓	2	2.30	25	3.45	0.24	3.69
33505-T2A-A01	REFLECTOR ASSYR.RR. nux	1	20.30	25	15.22	1.07	16.29
33555-T2A-A01	REFLECTOR ASSYL.RR. CRA ✓	1	20.30	25	15.22	1.07	16.29
71510-T2G-A00	GARNISH ASSYRR.BUMPER LOWER SCR ✓	1	159.80	25	119.85	8.39	128.24
90113-SJA-A00	SCREWTAPPING 5X14 ?	2	2.30	25	3.45	0.24	3.69
71505-S5A-J00	BRACKETR.RR.BUMPER ?	1	7.20	25	5.40	0.38	5.78
71555-S5A-J00	BRACKETL.RR.BUMPER ?	1	5.80	25	4.35	0.30	4.65
71508-T2A-A00	PROTECTORRR.BUMPER SIDE DEF ✓	1	5.00	25	3.75	0.26	4.01
71530-T2M-T00ZZ	BEAM COMPRR.BUMPER ?	1	199.20	25	149.40	10.46	159.86
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR Shorted ✓	1	320.00		320.00	22.40	342.40
68500-T2M-Z10ZZ	LID COMPTRUNK BUC ✓	1	876.20	25	657.15	46.00	703.15
74865-T2A-003	WEATHERSTRIPTRUNK LID DEF ✓	1	71.30	25	53.47	3.74	57.21
74851-T2A-003	LOCK ASSYTRUNK SVC X	1	92.60	25	69.45	4.86	74.31
74590-T2A-A02	FENDERL.RR.INNER ? BUC ✓	1	122.90	25	92.17	6.45	98.62
91501-T2A-003	CLIPINNER FENDER ?	6	0.40	25	1.80	0.13	1.93

Printed on 2/4/2019 4:03:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT19001477	Page	2
	64 CECIL STREET	Date	: 2. Apr 2019		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SKP5711J	Engine No	: K24W31200877		
Chassis No	: MRHCR2630EP000032	Date Time	: 2. Apr 2019 3:04:34 PM		
Model	: ACCORD 2.4 AT 2014 (EURO 4)	Surveyor Name	:		
Owner's Name	: MR YUE XIAONING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 1/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
75701-T2A-A02	EMBLEMH	1	26.70	25	20.02	1.40	21.42
75722-T2A-A01	EMBLEMRR.ACCORD	1	19.30	25	14.47	1.01	15.48
75725-TG2-K00	EMBLEMRR.I-VTEC	1	34.10	25	25.57	1.79	27.36
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
75731-T2A-W01	EMBLEMRR.2.4	1	11.60	25	8.70	0.61	9.31
33550-T2A-Y11	TAILLIGHT ASSYL. <i>CRA</i>	1	538.40	25	403.80	28.27	432.07
34150-T2A-T01	LIGHT ASSYR.LID <i>SCR</i>	1	259.10	25	194.32	13.60	207.92
63720-T2F-A00ZZ	GUTTER COMPL.RR. <i>?</i>	1	110.50	25	82.87	5.80	88.67
66100-T2M-U00ZZ	PANEL COMPRR. <i>?</i>	1	403.60	25	302.70	21.19	323.89
Sum Item					3105.90	217.41	3,323.31
BOSUN	SUNDRIES	1	100.00		20 <i>100.00</i>	7.00	107.00
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BOMISC1	RESET & INSTALL SMART ENTRY SYSTEM (N)	1	200.00		200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT TRUNK	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	120.00		100 <i>120.00</i>	8.40	128.40
BKB02R	REMOVE & RENEW RR BUMPER & DAMAGE PARTS.	1	3000.00	500 x3	1650 <i>3000.00</i>	210.00	3210.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2000.00		1350 <i>2000.00</i>	140.00	2140.00
Sum Labor					5920.00	414.40	6,334.40

Survey By Hwee Jie-Lkk
Date & Time 10/4/19
Excess -
Status P/P Slays.
Signature [Signature]

Total Amount 9,025.90 631.81 9,657.71

Total (Inclusive of GST) 9,657.71

Printed on 2/4/2019 4:03:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: