



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003848
INV Date 13/05/2020
Reference CC3/CTI19005944/Jda3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHB 228E
Insured Veh. YN 8255J
Claim No. SNM19D201477C02/5
Policy No. DMCVSN3068131800
Accident Date 01/04/2019
Inspection Date 02/04/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19005944/Jda3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 13-05-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8255J	Veh. Inspected	SHB 228E	
Policy No.	DMCVSN3068131800	Coverage (\$)	0.00	
Claim No.	SNM19D201477C02/5	Excess (\$)	0.00	
Assign From		Assign Date	02/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U905692526	Colour	MAROON	
Odometer	511941	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2019	Inspection Date	02/04/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 228E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER SEAL ,RR LH (DISC 25%)	CUT	88.90	66.68
1	BUMPER SEAL ,RR RH (DISC 25%)	CUT	65.70	49.28
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	TAIL GATE DOOR GLASS MOULDING LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	DAM ,BACK DOOR GLASS ADHESIVE NO.1 (DISC 25%)	NECESSARY	27.30	20.48
1	DAM ,BACK DOOR GLASS ADHESIVE NO.2 (DISC 25%)	NECESSARY	17.40	13.05
1	MOULDING BACK WINDOW LOWER NO.2 (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING ,BACK WINDOW ,OUTSIDE LH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW OUTSIDE RH (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	CUT	504.90	378.68
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	SPOILER REAR (DISC 25%)	BROKEN	953.70	715.28
1	BUMPER FRT (DISC 25%)	CRUMPLED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER LIP COVER RR/RH (DISC 25%)	BROKEN	118.10	88.58
1	TAILGATE DOOR WEATHERSTRIP (DISC 25%)	CRUMPLED	353.40	265.05
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
2	LICENCE PLATE LAMP @\$35.70 (DISC 10%)	CUT	71.40	64.26
1	LENS & BODY ,FR TURN LH (DISC 10%)	CUT	511.80	460.62
1	HEAD LAMP LH (DISC 10%)	CUT	945.20	850.68
1	3RD BRAKE LAMP (DISC 10%)	BROKEN	231.30	208.17
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00

Report Ref No. CC3/CTI19005944/Jda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NUMBER PLATE (SN)	CUT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CUT	12.00	12.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	UNDER COVER SUBASSY ,RR FLOOR	NOT NECESSARY	514.50	-
1	EXHAUST HEAT SHIELD ,REAR	NOT NECESSARY	107.40	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	656.20	-
2	TAILGATE DOOR HINGE LH/RH	NOT NECESSARY	58.30	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE DOOR STAY LH	NOT NECESSARY	241.50	-
1	TAILGATE DOOR STAY RH	NOT NECESSARY	241.50	-
1	TAILGATE DOOR WEATHERSTRIP	NOT NECESSARY	353.40	-
1	TAILGATE LOCK COVER	NOT NECESSARY	15.70	-
1	STRIKER BACK DOOR	NOT NECESSARY	48.90	-
1	TAILGATE BOARD ASSY	NOT NECESSARY	246.90	-
1	SIWITCH ASSY ,BACK DOOR OPENER	NOT NECESSARY	146.10	-
1	3RD BRAKE LAMP	NOT NECESSARY	231.30	-
1	END PANEL	NOT NECESSARY	602.10	-
1	END PANEL COVER ,DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER ,DECK TRIM RR	NOT NECESSARY	121.10	-
1	REINFORCEMENT ,RR	NOT NECESSARY	34.60	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	BOX DECK FLOOR ,RR	NOT NECESSARY	649.70	-
1	BOX ,RR FLOOR ,BOARD	NOT NECESSARY	679.60	-
1	TAIL LAMP BRACKET LH	NOT NECESSARY	30.70	-
1	TAIL LAMP BRACKET RH	NOT NECESSARY	30.70	-
1	TAILGATE LOWER WINDOW GLASS	NOT NECESSARY	721.30	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-

Report Ref No. CC3/CTI19005944/Jda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY ,FR BUMPER LH	NOT NECESSARY	250.40	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER GRILLE SUB-ASSY ,LOWER	NOT NECESSARY	311.10	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-
1	BRACKET ,FR TURN CENTER LH	NOT NECESSARY	58.20	-
1	BRACKET ,FR TURN LOWER LH	NOT NECESSARY	26.00	-
1	BRACKET ,FR TURN UPPER LH	NOT NECESSARY	24.40	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	FENDER FRT/LH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	-
1	FENDER LINER PAD ,FR WHEEL ,LH	NOT NECESSARY	49.30	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY ,RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY ,RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA ,ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	WHEEL DISC .FRONT	TO REPAIR SEE LABOUR	1,484.20	-
			20,955.20	5,798.42
	LABOUR			
	PANEL BEATING & BODY WORK .INCLUSIVE OF THE REPAIR OF WHEEL DISC .FRONT.		2,459.00	1,000.00
	SPRAY PAINT.		3,132.00	950.00
	TOWING CHARGE.		126.00	90.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO APPLY RUST -PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO DO WHEEL ALIGNMENT /TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE MECHANISM .		120.00	50.00

Report Ref No. CC3/CTI19005944/Jda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	150.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	250.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			7,387.00	2,370.00
GRAND TOTAL			28,342.20	8,168.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC3/CT119005944/Jda3q2

ONG HWEE JIE

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 228E

INSPECTION






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 228E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

