

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna	ationale Des Experts En Automol	oile			
QBE INSURANCE (SI		Ref : CC4/QBE190059				
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 29-11-2019 Code: QBE				
•	Policy Particula	rs :- THIRD PARTY CLAIM				
Insured Veh.	SLK 555R	Veh. Inspected	SKS 100P			
Policy No.	8-V0014368-MVA-R002	Coverage (\$)	0.00			
Claim No.	VC012440	Excess (\$)	0.00			
Assign From	JENNY TOH	Assign Date	29/03/2019			
	Vehicle Pa	rticulars & Condition				
Make & Model	BENTLEY CONTINENTAL	c.c	5998			
Engine No.	HIDDEN	Year of Reg.	2008			
Chassis No.	SCBBE53W98C057298	BLACK				
Odometer	65337	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	FAIR					
	Cond	ditions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	275/35ZR21	PIRELLI	7 mm			
L/H Front Tyre	275/35ZR21	PIRELLI	7 mm			
R/H Rear Tyre	275/35ZR21	PIRELLI	7 mm			
L/H Rear Tyre	275/35ZR21	PIRELLI	7 mm			
	Descri	ption of Damages				
THE VEHICLE SU	STAINED DAMAGES AT THE F	REAR PORTION.				
DAMAGES SEE D	ETAILS.					
	Gene	eral Information				
Accident Date	25/03/2019	Inspection Date	04/04/2019			
Survey held at	MBM WHEELPOWER PTE L	TD				
	176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721					
5a.		Remarks				
	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS					
5b.	Estima	ate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 100P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP)	BROKEN	5,782.00	5,782.00	
9 1	REAR BUMPER LOWER GRILLE (WCP)	BROKEN	2,512.00	2,512.00	
1	REAR BUMPER UNDER LINING (WCP)	NOT NECESSARY	426.00	=	
1	REAR BUMPER TOP COVER (WCP)	NOT NECESSARY	440.00	-	
1	REAR BUMPER SPONGE (WCP)	BROKEN	496.00	496.00	
1	REAR BUMPER INNER SPONGE (WCP)	NOT NECESSARY	230.00	-	
1	REAR BUMPER CENTER GUIDE (WCP)	BROKEN	790.00	790.00	
1	REAR BUMPER RETAINING CLIP LH (WCP)	NECESSARY	36.00	36.00	
1	REAR BUMPER RETAINING CLIP RH (WCP)	NECESSARY	36.00	36.00	
1	REAR BUMPER SIDE RETAINER LH (WCP)	NOT NECESSARY	216.00	=	
1	REAR BUMPER SIDE RETAINER RH (WCP)	NOT NECESSARY	216.00	_	
2	REVERSE SENSOR @ \$248.00 (WCP)	N/S SHORTED	496.00	248.00	
1	REVERSE CAMERA (WCP)	NOT NECESSARY	352.00	_	
1	REVERSE LAMP LH (WCP)	CRACKED	616.00	616.00	
1	REVERSE LAMP RH (WCP)	NOT NECESSARY	616.00	· ·	
1	LICENCE LAMP (WCP)	NOT NECESSARY	120.00	-	
	COST PLUS 15%		2,007.00	1,577.40	
			15,387.00	12,093.40	
	SPECIAL NETT ITEMS				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-	
1	REAR NUMBER PLATE (SN)	BENT	50.00	30.00	
			130.00	30.00	
	LABOUR				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.		1,200.00	300.00	
	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR.	II.	250.00	100.00	
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)		200.00	100.00	
	TO CHECK & RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	100.00	-	

Report Ref No. CC4/QBE19005948/Eha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts Con-		Estimate By Workshop (\$))	Our Adjusted (\$)	
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,200.00	300.00	
			2,950.00	800.00	
	GRAND TOTAL		18,467.00	12,923.40	

RECOMMENDED COST OF LUMP SUM REPAIRS					10,350.00
(TO ITS PRE-ACCIDENT CONDITION)	112 84				

Report Ref No. CC4/QBE19005948/Eha3s2

1

CHEN TSUE YEE

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.