



ACCIDENT REPAIR ESTIMATE

Vehicle Reg. No. :	SLE3403H
Vehicle Reg. Date:	18-Jul-2016
Make / Model :	T. SIENTA 1.5G CVT ABS
Engine No. :	2NR8595583
Chassis No. :	NSP1707025045

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : **EZEL**

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE3403H**

Vehicle Reg. Date: **7/18/2016**

Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **2NR8595583**

Chassis No. : **NSP1707025045**

Steve CLKK)

4/4/19 2:30pm

with prejudice

5 days

L/S

Reg AL spm

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding / <i>NEC</i>		\$ 168.40		
2	1	Rear number plate lamp assy X		\$ 158.00		
3	1	Rear bumper /		\$ 534.00		
4	1	Rear bumper cover center / <i>DD</i>		\$ 183.00		
5	2/	Rear bumper cover LH/RH <i>RH / CUT</i>	<i>@14</i>	\$ 248.00		
6	1set	Rear bumper clips / <i>NEC</i>		\$ 50.00	<i>70-</i>	
7	2	Rear bumper side retainer LH/RH <i>RH - LH -</i>	<i>OR</i>	\$ 164.00		
8	2/	Rear bumper bracket LH/RH <i>LH X RH ?</i>	<i>Q85</i>	\$ 164.00	<i>7</i>	
9	1	Rear bumper sponge ?		\$ 54.00	<i>7</i>	
10	2/	Rear bumper reflector LH/RH <i>LH X RH ?</i>	<i>B106</i>	\$ 216.00	<i>7</i>	
11	2	Rear bumper splash shield LH/RH <i>LH X RH X</i>		\$ 156.00		
12	1	Tail gate / <i>DD</i>		\$ 1,086.00		
13	1	Tail gate lock / <i>DT</i>		\$ 448.00		
14	1	Tail gate striker X		\$ 48.00		
15	2	Tail gate stay LH/RH X		\$ 454.00		
16	1	Tail gate logo / <i>NEC</i>		\$ 57.00		
17	1	Tail gate emblem RH X <i>NEC</i>		\$ 63.00		
18	1	Tail gate outer garnish X		\$ 278.00		
19	1	Tail gate weatherstrip <i>CRU /</i>		\$ 357.00		
20	2	Tail gate lamp LH/RH <i>LH X RH X</i>		\$ 294.00		
21	1	Tailgate trimboard X		\$ 280.00		
22	2	Tail gate inner side trim LH/RH X		\$ 1,214.00		
23	2	Tail lamp LH/RH X <i>RH X LH</i>		\$ 780.00		
24	2	Tail lamp clips LH/RH X		\$ 40.00		
25	1	Tail gate inner handle X		\$ 90.00		
26	1	Antenna sensor ?		\$ 190.00	<i>7</i>	
27	1	Rear wiper motor X		\$ 400.00		
28	1	Rear wiper motor link X		\$ 240.00		
29	1	Rear wiper arm X		\$ 200.00		
30	1	Rear wiper blade X		\$ 400.00		
31	1	Rear end panel outer X <i>R</i>		\$ 498.20		
32	1	Rear end panel inner X		\$ 498.20		
33	1	Rear end panel garnish X		\$ 195.20		
34	1	Spare tyre well panel X		\$ 822.60		
35	1	Spare tyre board X		\$ 487.00		
36	1	Spare tyre bracket X		\$ 60.00		
37	1	Spare tyre tool cover X		\$ 280.00		
38	1	Spare tyre tool tray X		\$ 419.00		
39	1	Exhaust muffler X		\$ 673.00		
40	1	Exhaust muffler mounting X		\$ 70.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE3403H**
Vehicle Reg. Date: **7/18/2016**
Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
Engine No. : **2NR8595583**
Chassis No. : **NSP1707025045**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust heat shield ☒		\$ 90.00		
42	2	Rear fender LH/RH ☒		\$ 3,352.00		
43	2	Rear fender garnish lower LH/RH ☒		\$ 142.00		
44	2	Rear fender garnish upper LH/RH ☒		\$ 1,214.00		
45	2	Rear fender air duct LH/RH ☒		\$ 150.00		
46	1set	Tailgate trimboard clips ☒ <i>1/1</i>		\$ 40.00	<i>1/1</i>	
47	2set	Tail gate inner side trim LH/RH clips ☒		\$ 80.00		
48	1	Rear end panel sealant ☒			\$ 40.00	<i>20</i>
49	1	Sundries			\$ 50.00	<i>20</i>
50	1	Reverse sensor			\$ 200.00	<i>/</i>
51	1	Rear number plate with frame			\$ 45.00	☒
52	1	Rear windscreen sealant			\$ 40.00	<i>/</i>
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area.	\$ 2,000.00	500
2	To remove and replace reverse sensor.	\$ 100.00	30
3	To remove and refit inner trim,inner seat,trim board, to assist repair.	\$ 150.00	30
4	To rustproof accident repair area.	\$ 200.00	30
5	To transfer tailgate mechanism to new tailgate.	\$ 150.00	80
6	To check and rectify wiring after disconnect and connect.	\$ 50.00	30
7	To putty and respray replaced parts and accident repair area.	\$ 1,500.00	500
8	To remove & refit rear windscreen.	\$ 180.00	100
9	To remove and replace and align exhaust pipe	\$ 150.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: