

108/11/14

Durringer

REF:

hpc

61038

ASSIGNMENT

From:

Date:

12/14/2019

Veh No:

SX 9999H

Yr Regn:

2014 / Jun

Estimated Cost:

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To Inspect Vehicle No:

SX 9999H

Make:

Volkswagen Jetta 1.4

C.C.

1390

at Workshop m/s

Volkswagen

Colour:

Red

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

of

247 Alexandra Road

Sp. Reading

50765

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Insured:

Eng/No:

Policy No.

C/No:

WVN22216 Z6 M027470

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

10cm

Modi: ☐ Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:


205/55R16

R:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

46K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/04/19

D.O.I.

12/04/19

Survey held at

ALEXANDRA RD

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)