



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3425H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
3	<b><u>REPLACEMENT OF PARTS</u></b> SIDE SIGNAL LAMP @\$80.00 LESS 10% DISCOUNT	CRACKED	240.00	240.00
			-24.00	-24.00
			216.00	216.00
1	<b><u>SPECIAL NETT ITEMS</u></b> STICKER EXCURSION (SN)	NECESSARY		
			20.00	20.00
			20.00	20.00
	<b><u>LABOUR</u></b> TO CHECK ALL THE WIRING OF SIGNAL LAMP,DOOR AND OTHER AFFECTED AREA. TO KNOCK AND REPAIR,PUTTY AND SPRAY ON LEFT HAND SIDE REAR,CENTER,DOOR AREA AND ALL AFFECTED ACCIDENT PARTS (TWO COLOUR PAINT).		200.00	50.00
			2,850.00	1,600.00
			3,050.00	1,650.00
<b>GRAND TOTAL</b>			<b>3,286.00</b>	<b>1,886.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/FCI19005993/Jsd3s2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.