



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4584K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,530.20	-
1	FRONT DOOR CHROME LH	CUT	360.20	360.20
1	REAR DOOR LH	DENTED	1,530.20	1,280.20
1	REAR DOOR CHROME LH	NOT NECESSARY	360.20	-
	LESS 25% DISCOUNT		-945.20	-410.10
			<b>2,835.60</b>	<b>1,230.30</b>
<b>LABOUR</b>				
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH.		800.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		800.00	400.00
	TUFF COAT.	NOT NECESSARY	200.00	-
	REMOVE AND REFIX FRONT & REAR DOOR MECHANISM LH.		380.00	80.00
			<b>2,180.00</b>	<b>780.00</b>
<b>GRAND TOTAL</b>			<b>5,015.60</b>	<b>2,010.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CS/SPF19006043/Avd3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00-\$2,000**

**ADRIAN LING WAI PING**

**B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**